



Status Report

HAWKER 400XP S/N RK-465 N99VS

OWNER: AVIAN APARTMENTS LLC
ADDRESS: 3424 PEACHTREE RD NE STE 300
 ATLANTA GA 30326-2818
PHONE: 470-443-2707
FAX:

OPERATOR: CORTLAND DEVELOPMENT
ADDRESS: 2021 FLIGHTWAY DR.
 CHAMBLEE GA 30341
PHONE: 470-548-6081
FAX:

ANALYST: CRAIG NICHOLS
EMAIL: CNICHOLS@CAMPSYSTEMS.COM

+1-316-462-2427 (DIRECT)
 1-866-581-2267 (OFFICE)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: RK-465/N99VS **MODEL:** HAWKER 400XP **MANUFACTURER:** TEXTRON AVIATION INC.

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	23-MAR-2006	4030.73 A/C HRS	as of 10-SEP-2020	A/C HRS	as of ___/___/___
INSERVICE DATE:	23-MAR-2006	3391 AFL	as of 10-SEP-2020	AFL	as of ___/___/___
		1220 ACH	as of 28-SEP-2018	ACH	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-JA0722/3030100 **MODEL:** JT15D-5/-5R **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-MAR-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	4030.73 ENG. HRS	as of 10-SEP-2020	ENG. HRS	as of ___/___/___
0 ENC		3391 ENC	as of 10-SEP-2020	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-JA0723/3030100 **MODEL:** JT15D-5/-5R **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 23-MAR-2006		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	4030.73 ENG. HRS	as of 10-SEP-2020	ENG. HRS	as of ___/___/___
0 ENC		3391 ENC	as of 10-SEP-2020	ENC	as of ___/___/___



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS								
052001	INSPECT HAIL DAMAGE/ELECTROMAGNETIC DENT REPAIR (EDR)	MOS					17-FEB-2020		
		HRS/MSC	400				3991.8		4391.8
MAINTENANCE MANUAL SUPPLEMENT	REF:	AFL					3356		
+ 05A000	INSPECTION A	MOS					26-AUG-2019		
05.010		HRS/MSC	200	+20			3871.6		4071.6
	REF: AMM 05-20-00	AFL					3259		4091.6
+ 05B000	INSPECTION B	MOS					26-AUG-2019		
05.010		HRS/MSC	400	+20			3871.6		4271.6
	REF: IP 27-60-20-01	AFL					3259		4291.6
+ 05C000	INSPECTION C	MOS					23-JAN-2018		
05.010		HRS/MSC	1200	+20			3473.1		4673.1
	REF:	AFL					2951		4693.1
+ 05D000	INSPECTION D	MOS					23-MAR-2006		
05.015		HRS/MSC	5000	+20			0		5000
	REF: AMM 05-20-00	AFL							5020
+ 05NXS2	INSPECTION S (PROLINE 21 AVIONICS SYSTEM) STAND BY BATTERY PERIODIC TEST	MOS	6				29-JUN-2020	29-DEC-2020	
		HRS/MSC					3998.9		
ICA	REF:	AFL					3364		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05NXS3	INSPECTION S (PROLINE 21 AVIONICS SYSTEM) AHRS STAND BY BATTERY PERIODIC TEST								
		MOS	6				29-JUN-2020	29-DEC-2020	
ICA	REF:	HRS/MSC					3998.9		
		AFL					3364		

ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100

+ 057110	NO. 1 ENGINE - MINOR INSPECTION								
		MOS					26-AUG-2019		
	REF: EMM 72-00-00	HRS/MSC	200	+20			3871.6	(4071.6) 4071.6	4091.6
		ENC					3259		

ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100

+ 057110	NO. 2 ENGINE - MINOR INSPECTION								
		MOS					26-AUG-2019		
	REF: EMM 72-00-00	HRS/MSC	200	+20			3871.6	(4071.6) 4071.6	4091.6
		ENC					3259		

CHAPTER 08 LEVELING AND WEIGHING

+ 082000	WEIGHT AND BALANCE AIRCRAFT								
08.010		MOS	36				26-AUG-2019	26-AUG-2022	
	REF: GENERIC NO REF	HRS/MSC					3871.6		
		AFL					3259		

CHAPTER 12 SERVICING

+ 122030	ACCOMPLISH A INSPECTION LUBRICATION								
12.020		MOS					26-AUG-2019		
	REF: AMM 12-20-00	HRS/MSC	200	+20			3871.6	4071.6	4091.6
		AFL					3259		

+ 122050	ACCOMPLISH B INSPECTION LUBRICATION								
12.030		MOS					26-AUG-2019		
	REF: AMM 12-20-00	HRS/MSC	400	+20			3871.6	4271.6	4291.6
		AFL					3259		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 122180	ACCOMPLISH C INSPECTION LUBRICATION								
12.050	REF: AMM 12-20-00	MOS HRS/MSC AFL	1200	+20			23-JAN-2018 3473.1 2951	4673.1	4693.1
+ 123001	LUBRICATE SPOILER DRIVE SERVO MOUNT CLUTCH TEETH								
12.090	622-5027-102 22KNB REF: AMM 12-20-00	MOS HRS/MSC AFL	48 6500	+20			26-AUG-2019 3871.6 3259	26-AUG-2023 10371.6	10391.6
+ 123002	LUBRICATE ELEVATOR DRIVE SERVO MOUNT CLUTCH TEETH								
12.090	622-6717-104 22D2H REF: AMM 12-20-00	MOS HRS/MSC AFL	48 6500	+20			26-AUG-2019 3871.6 3259	26-AUG-2023 10371.6	10391.6
+ 123003	LUBRICATE RUDDER DRIVE SERVO MOUNT CLUTCH TEETH								
12.090	622-6717-104 22D2F REF: AMM 12-20-00	MOS HRS/MSC AFL	48 6500	+20			26-AUG-2019 3871.6 3259	26-AUG-2023 10371.6	10391.6
+ 12A01H	LUBRICATE MAIN LANDING GEAR 100 HOUR								
12.060	REF: AMM 12-20-00	MOS HRS/MSC AFL	N/R				23-MAR-2006 0 0		
CHAPTER 21 AIR CONDITIONING									
+ 210036	AIR CONDITIONING DRIVE MOTOR								
21.530	1134104-5 2721 REF: GENERIC CMM	MOS HRS/MSC AFL ACH					23-JAN-2018 3473.1 2951 1217.9	4217.9	
OVERHAUL			3000						



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
211003	EMERGENCY PRESSURE VALVE								
21.020	979494-1 SN-UNKNOWN REF: AMM 21-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
211025	BLEED AIR PRESSURE SWITCH								
21.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
211031	TEST VALVE								
21.040	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
212001	CEILING AIR OUTLET SHUTOFF VALVE								
21.050	PN SN-UNKNOWN REF: AMM 21-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
212007	COCKPIT MODE SELECTOR								
21.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
212013	DIFFUSER								
21.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
212029	NO. 1 DEFOGGER BLOWER								
21.070	FED8000 9-000634-R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-OCT-2010 1888.2 1655		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212035	NO. 2 DEFOGGER BLOWER								
21.070	FED8000 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
212041	CHECK VALVE								
21.060	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213001	CABIN PRESSURE CONTROL MODULE								
21.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213007	PNEUMATIC RELAY								
21.080	130358-3 42-272 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-JUN-2009 1785.2 1565		
213013	LEFT HAND CABIN ALTITUDE PRESSURE REGULATOR								
21.080	102466-15 95-B0310 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213014	RIGHT HAND CABIN ALTITUDE PRESSURE REGULATOR								
21.080	102466-15 105-B0331 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213015	VACUUM REGULATOR								
21.110	2103401-2 1150 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213016	PRESSURE CONTROL REGULATOR								
21.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213037	S2 SOLENOID VALVE								
21.130	101-380021-7 05-032169 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213038	S3 SOLENOID VALVE								
21.130	101-380021-7 05-032175 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213039	MANUAL CONTROL VALVE								
21.140	45AS63001-005 115-6198 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213040	LEFT OUTFLOW SAFETY VALVE								
21.150	45AS63001-025 115-G0761 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213041	RIGHT OUTFLOW SAFETY VALVE								
21.150	103570-27 45-G0664 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	O:7 O:0 O:0			10-JUL-2015 2519.5 2188		
213098	DUMP VALVE								
21.160	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213103	CABIN AIR PRESSURE CONTROLLER								
21.170	130356-9 17-A0751 REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-SEP-2007 1093.8 950		
213115	CABIN PRESSURE AUXILIARY VOLUME TANK								
21.180	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
213151	CABIN ALTITUDE SWITCH								
21.210	PN SN-UNKNOWN REF: AMM 21-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215001	REFRIGERATION UNIT								
21.220	PN SN-UNKNOWN REF: AMM 21-50-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215003	AIR CONDITIONING COMPRESSOR								
21.090	PN SN-UNKNOWN REF: AMM 21-51-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 215005	INSPECT AIR-CONDITIONING SYSTEM (500 HOUR)								
21.500	REF: GENERIC CMM	MOS HRS/MSC AFL ACH	500	+20			23-JAN-2018 3473.1 2951 1217.9	1717.9	1737.9
215012	CABIN TEMPERATURE MODULATOR VALVE								
21.230	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215013	COCKPIT TEMPERATURE MODULATOR VALVE								
21.230	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215014	TURBINE COOLING BY-PASS VALVE								
21.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215015	EJECTOR SHUT-OFF VALVE								
21.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215016	RAM AIR CHECK VALVE								
21.250	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215018	ZONE NO. 2 MODULATOR SHUT-OFF VALVE								
21.250	3290802-2 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215025	AIR TEMPERATURE BULB								
21.260	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215031	ENVIRONMENTAL CONTROL VALVE								
21.270	45AS63018-171 843 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215035	COOLING TURBINE								
21.275	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215037	PRIMARY HEAT EXCHANGER								
21.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215043	SECONDARY HEAT EXCHANGER								
21.280	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215049	THERMAL SWITCH								
21.260	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
215060	CABIN TEMPERATURE INDICATOR								
21.470	5003-3016 746 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 215155	INSPECT FREON AIR-CONDITIONING SYSTEM COMPRESSOR/CONDENSER MODULE								
21.520	REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-JAN-2018 3473.1 2951		
216001	COCKPIT TEMPERATURE SENSOR								
21.290	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216002	CABIN TEMPERATURE SENSOR								
21.290	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216003	COCKPIT HIGH LIMIT SENSOR								
21.300	45AS63018-127 7098 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216004	CABIN HIGH LIMIT SENSOR								
21.300	45AS63018-127 7095 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216005	LOW LIMIT SENSOR								
21.310	1150976-1 1150976-00877 REF: AMM 21-60-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216006	COCKPIT DUCT TEMPERATURE SENSOR								
21.310	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216007	CABIN DUCT TEMPERATURE SENSOR								
21.310	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216008	FORWARD DUCT TEMPERATURE SENSOR								
21.320	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216009	AFT DUCT TEMPERATURE SENSOR								
21.320	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216043	COCKPIT TEMPERATURE SENSOR BLOWER								
21.330	19A3008 733 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-NOV-2011 2083.7 1830		
216044	CABIN TEMPERATURE SENSOR BLOWER								
21.330	19A3008 737 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			30-JUL-2017 3318 2835		
216067	COCKPIT TEMPERATURE SELECTOR								
21.350	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216068	CABIN TEMPERATURE SELECTOR								
21.350	1152058-1 1152058-00871 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216069	CABIN MODE SELECTOR								
21.350	1152058-1 1152058-00872 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216073	OVERTEMPERATURE SWITCH								
21.360	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216079	CABIN MODE SELECTOR								
21.370	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216080	COCKPIT MODE SELECTOR								
21.370	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
216090	CABIN ALTITUDE DIFFERENTIAL PRESSURE INDICATOR								
21.215	45AS86832-005 507575 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
217001	WATER SEPARATOR								
21.220	PN SN-UNKNOWN REF: AMM 21-70-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
217013	COALESCER								
21.390	PN SN-UNKNOWN REF: AMM 21-70-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 218009	INSPECT COMPRESSOR DRIVE MOTOR BEARING								
21.420	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL	N/R	I:0 I:0 I:0			23-MAR-2006 0 0		
+ 218011	INSPECT COMPRESSOR DRIVE MOTOR BRUSH								
21.190	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL ACH	N/R				10-DEC-2016 0 0 971.2		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 218013	INSPECT COMPRESSOR (R12) ASSEMBLY SHAFT SEAL								
21.030	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL ACH	N/R				10-DEC-2016 0 0 971.2		
+ 218015	INSPECT COMPRESSOR (R12) ASSEMBLY BEARING								
21.400	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL	N/R	I:0 I:0 I:0			23-MAR-2006 0 0		
+ 218017	INSPECT COMPRESSOR (R12) ASSEMBLY PRESSURE SWITCH								
21.200	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL	N/R	I:0 I:0 I:0			23-MAR-2006 0 0		
+ 218030	INSPECT AIR CONDITIONING COMPRESSOR/CONDENSER MODULE BAY								
21.410	REF: CMM ICA-HOF90103	MOS HRS/MSC AFL	N/R	I:0 I:0 I:0			23-MAR-2006 0 0		
218035	FORWARD EVAPORATOR MODULE								
21.480	1134310-1 881 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
218040	AFT EVAPORATOR MODULE								
21.480	1134310-1 883 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
218045	COMPRESSOR CONDENSER								
21.490	1134400-1 463 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 22	AUTO FLIGHT								
221043	SPOILER DRIVE SERVO								
22.010	622-5027-102 22KNB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221044	ELEVATOR DRIVE SERVO								
22.010	622-6717-104 22D2H REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221050	RUDDER DRIVE SERVO								
22.030	622-6717-104 22D2F REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221055	SPOILER SERVO DRIVE MOUNT								
22.020	822-0260-001 22J5H REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221056	ELEVATOR SERVO DRIVE MOUNT								
22.020	622-6718-101 22G8Y REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221057	RUDDER SERVO DRIVE MOUNT								
22.020	622-6718-101 23TXC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
221074	MODE CONTROL PANEL								
22.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221075	AUTOPILOT CONTROLLER PANEL								
22.050	622-6208-204 DWJF REF: AMM 22-13-00	MOS HRS/MSC AFL	O/C	O:3 O:0 O:0			01-MAR-2016 2759.3 2387		
+ 227010	INSPECT SPOILER (ROLL) SERVO MOUNT SLIP CLUTCH.								
22.060	REF: GENERIC CMM	MOS HRS/MSC AFL	12200	+20			23-MAR-2006 0 0	12200	12220
+ 227012	INSPECT ELEVATOR SERVO MOUNT SLIP CLUTCH								
22.070	REF: GENERIC CMM	MOS HRS/MSC AFL	12200	+20			23-MAR-2006 0 0	12200	12220
+ 227014	INSPECT RUDDER SERVO MOUNT SLIP CLUTCH								
22.080	REF: GENERIC CMM	MOS HRS/MSC AFL	12200	+20			23-MAR-2006 0 0	12200	12220
CHAPTER 23 COMMUNICATIONS									
231001	NO. 1 VHF COMMUNICATIONS TRANSCEIVER								
23.010	822-1115-001 1M4LM REF:	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			09-FEB-2014 2421 2091		
231002	NO. 2 VHF COMMUNICATIONS TRANSCEIVER								
23.010	822-1115-001 23TBN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
231079	NO. 1 VHF COMMUNICATION ANTENNA								
23.020	S65-8280-42 730 REF: AMM 34-59-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231080	NO. 2 VHF COMMUNICATION ANTENNA								
23.020	S65-8280-42 581 REF: AMM 34-59-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
231082	FLIGHT PHONE ANTENNA								
23.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233001	CABIN FLIGHT PHONE HANDSET								
23.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233002	COCKPIT FLIGHT PHONE HANDSET								
23.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233004	COCKPIT FLIGHT PHONE (C118E) FORWARD CONTROL								
23.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233006	COCKPIT FLIGHT PHONE (C118E) AFT CONTROL								
23.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233008	FLIGHT PHONE(RT18D) TRANSCEIVER								
23.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233010	FLIGHT PHONE CONTROLLER								
23.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233015	LEFT RADIO TUNING UNIT								
23.070	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
233020	RIGHT RADIO TUNING UNIT								
23.070	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
233085	FORWARD VIDEO MONITOR-								
23.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
233086	AFT VIDEO MONITOR-								
23.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
235013	PILOT AUDIO CONTROL PANEL								
23.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
235014	COPILOT AUDIO CONTROL PANEL								
23.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235020	VLF RECEIVER								
23.070	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
235025	NO. 1 AUDIO AMPLIFIER								
23.090	438-001 4711 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
235030	NO. 2 AUDIO AMPLIFIER								
23.090	438-001 4405 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2010 1888.2 1655		
235035	AURAL WARNING TONE GENERATOR								
23.100	603 865 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
237002	COCKPIT VOICE RECORDER								
31.030	2100-1020-00 000293010 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JUL-2007 961.9 837		
+ 237014	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
31.030	DK120 SD63155 REF:	MOS HRS/MSC AFL	O/C				10-DEC-2016 3066.7 2631		
+ 237016	FUNCTIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
31.030	REF:	MOS HRS/MSC AFL	24				20-AUG-2020 4028.3 3387	20-AUG-2022	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 237017	REPLACE COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY								
31.030	DK120 SD63155 REF: CMM 23-70-01	MOS HRS/MSC AFL	DUE	I:0 I:0			10-DEC-2016	28-FEB-2023 M	
Expiry Date: 28-FEB-2023									
+ 237018	INSPECT/CLEAN COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON SWITCH								
31.030	REF:	MOS HRS/MSC AFL	24				20-AUG-2020 4028.3 3387	20-AUG-2022	
237019	COCKPIT VOICE RECORDER IMPACT SWITCH								
31.025	689D1X2.5-2.5 5597 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
237020	COCKPIT VOICE RECORDER CONTROL UNIT								
31.035	93A151-30 360171 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
238031	LEFT CONTROL PANEL DISPLAY								
23.130	822-1828-002 4FL1M7 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
238034	RIGHT CONTROL PANEL DISPLAY								
23.130	822-1828-002 4FL1D8 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
CHAPTER 24 ELECTRICAL POWER									
240001	STANDBY BATTERY POWER SUPPLY								
24.055	501-1228-04 80233 REF: AMM 24-20-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JUN-2020 3998.9 3364		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240002	AHRS BATTERY POWER SUPPLY								
24.005	501-1228-04 3789 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			29-JUN-2020 3998.9 3364		
+ 240012	STANDBY POWER SUPPLY BATTERY CAPACITY CHECK								
24.055	501-1228-04 80233 REF: See Workcard	MOS HRS/MSC AFL	12				29-JUN-2020 3998.9 3364	29-JUN-2021	
+ 240013	STANDBY AHRS POWER SUPPLY BATTERY CAPACITY CHECK								
24.005	501-1228-04 3789 REF: See Workcard	MOS HRS/MSC AFL	12				29-JUN-2020 3998.9 3364	29-JUN-2021	
242001	NO. 1 INVERTER								
24.010	SPC-5(B) 1932 REF: AMM 24-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-NOV-2011 2083.7 1830		
242002	NO. 2 INVERTER								
24.010	SPC-5 1369 REF: AMM 24-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
242003	NO. 3 INVERTER								
24.180	SS50 2212 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-MAR-2009 1727.4 1508		
242013	AC VOLTMETER								
24.020	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243001	NO. 1 GENERATOR CONTROL UNIT								
24.060	45AS88801-025 P1285 REF: AMM 24-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243002	NO. 2 GENERATOR CONTROL UNIT								
24.060	45AS88801-025 P1291 REF: AMM 24-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243013	DC INSTRUMENT CLUSTER								
24.070	PN SN-UNKNOWN REF: AMM 24-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243019	BATTERY FEED PROTECTION UNIT								
24.080	PN SN-UNKNOWN REF: AMM 24-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243022	BATTERY GROUND FAULT PROTECTION PANEL								
24.030	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 243025	BATTERY								
24.090	9750W0370 172160012 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:12 O:0 N:273.4 O:0 N:214 O:0			26-AUG-2019 3871.6 3259		
243027	PERFORM BATTERY CAPACITY CHECK PER ICA								
ICA	9750W0370 172160012 REF:	MOS HRS/MSC AFL	18 4500				26-AUG-2019 3871.6 3259	26-FEB-2021 8371.6	
+ 243043	NO. 1 ENGINE STARTER/GENERATOR								
24.110 REPLACE	23080-050 95071 REF: See Workcard	MOS HRS/MSC AFL	1000	O:21 R:0 O:380.9 R:0 O:288 R:0			23-AUG-2018 3598.2 3045	4217.3	
+ 243044	NO. 2 ENGINE STARTER/GENERATOR								
24.110 REPLACE	23080-050 Y-30112 REF: See Workcard	MOS HRS/MSC AFL	1000	O:0 O:0 O:0			14-MAY-2019 3808.8 3211	4808.8	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243073	LEFT OVERCURRENT SENSOR RELAY								
24.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243074	RIGHT OVERCURRENT SENSOR RELAY								
24.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243085	BATTERY TEMPERATURE INDICATOR								
24.130	PN SN-UNKNOWN REF: AMM 24-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243091	LEFT STARTER/GENERATOR POSITIVE GROUND FAULT CURRENT TRANSFORMER								
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243092	LEFT STARTER/GENERATOR NEGATIVE GROUND FAULT CURRENT TRANSFORMER								
24.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243093	RIGHT STARTER/GENERATOR POSITIVE GROUND FAULT CURRENT TRANSFORMER								
24.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243094	RIGHT STARTER/GENERATOR NEGATIVE GROUND FAULT CURRENT TRANSFORMER								
24.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243095	FORWARD FUSELAGE CURRENT TRANSFORMER								
24.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243096	AFT FUSELAGE CURRENT TRANSFORMER								
24.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243121	LEFT INDICATOR PANEL								
24.040	PN SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243122	RIGHT INDICATOR PANEL								
24.040	PN SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
243123	ANNUNCIATOR PANEL								
24.040	PN CAE330011 REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
251001	PILOT SEAT								
25.010	128-384056-1 334 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
251002	COPILOT SEAT								
25.010	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252001	RIGHT NO.1 PASSENGER SEAT								
25.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252002	RIGHT NO.2 PASSENGER SEAT								
25.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252003	RIGHT NO.3 PASSENGER SEAT								
25.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252004	LEFT NO.1 PASSENGER SEAT								
25.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252005	LEFT NO.2 PASSENGER SEAT								
25.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252017	LEFT NO.3 PASSENGER SEAT								
25.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252018	NO. 1 SWIVEL SEAT								
25.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252019	TOILET SEAT								
25.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
252065	RH #1 CABIN SEAT HYDROLOCK								
	UL32-040SP1 7980DA REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-JAN-2018 3473.1 2951		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
254010	LAVATORY TIMER VALVE ASSEMBLY								
25.130	3012-24 T9377 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
254015	PUMP MOTOR LAVATORY								
	5250-7 P10266 REF:	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
256001	EMERGENCY LOCATOR TRANSMITTER								
25.050	453-50000(999) 210-10183 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				20-AUG-2020 4028.3 3387		
256003	ELT ANTENNA								
25.060	PN SN-UNKNOWN REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
256005	EMERGENCY LOCATOR TRANSMITTER BATTERY								
	452-0133 377841-039 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-AUG-2018 3598.2 3045		
+ 256011	REPLACE EMERGENCY LOCATOR TRANSMITTER BATTERY								
25.050	452-0133 377841-039 REF: AMM 25-61-00	MOS HRS/MSC AFL	DUE				23-AUG-2018 3598.2 3045	01-JUL-2023 M	
+ 256012	INSPECT/FUNCTIONAL CHECK EMERGENCY LOCATOR TRANSMITTER								
25.050 MANDATORY	453-50000(999) 210-10183 REF: See Workcard	MOS HRS/MSC AFL	12				20-AUG-2020 4028.3 3387	20-AUG-2021	
+ 256013	REGISTRATION RENEWAL EMERGENCY LOCATOR TRANSMITTER								
25.140	453-50000(999) 210-10183 REF: CMM NOAA/SARSAT	MOS HRS/MSC AFL	24	I:456 I:162.4 I:133			20-AUG-2020 4028.3 3387	20-AUG-2020	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256014	PILOT LIFE VEST P01074-201 848437 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256015	COPILOT LIFE VEST P01074-201 803526 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256016	NO. 3 LIFE VEST P01074-201 803562 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256017	NO. 4 LIFE VEST P01074-201 803592 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256018	NO. 5 LIFE VEST P01074-201 848435 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256019	NO. 6 LIFE VEST P01074-201 803580 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256020	NO. 7 LIFE VEST P01074-201 774773 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256021	NO. 8 LIFE VEST P01074-201 774819 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				25-MAR-2016 2785.3 2405		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256022	NO. 9 LIFE VEST P01074-201 803579 REF: AMM 25-60-00	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
256023	NO. 10 LIFE VEST P01074-201 803572 REF:	MOS HRS/MSC AFL	O/C				06-APR-2006 0 0		
+ 256030	RECERTIFY PILOT LIFE VEST P01074-201 848437 REF: GENERIC NO REF Calibration Date: 24-MAR-2016	MOS HRS/MSC AFL	120				24-MAR-2016 I:0 I:0	24-MAR-2026	
+ 256031	RECERTIFY COPILOT LIFE VEST P01074-201 803526 REF: GENERIC NO REF Calibration Date: 24-MAR-2016	MOS HRS/MSC AFL	120				24-MAR-2016 I:0 I:0	24-MAR-2026	
+ 256032	RECERTIFY NO. 3 LIFE VEST P01074-201 803562 REF: GENERIC NO REF Calibration Date: 24-MAR-2016	MOS HRS/MSC AFL	120				24-MAR-2016 I:0 I:0	24-MAR-2026	
+ 256033	RECERTIFY NO. 4 LIFE VEST P01074-201 803592 REF: GENERIC NO REF Calibration Date: 24-MAR-2016	MOS HRS/MSC AFL	120				24-MAR-2016 I:0 I:0	24-MAR-2026	
+ 256034	RECERTIFY NO. 5 LIFE VEST P01074-201 848435 REF: GENERIC NO REF Calibration Date: 24-MAR-2016	MOS HRS/MSC AFL	120				24-MAR-2016	24-MAR-2026	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 256035	RECERTIFY NO. 6 LIFE VEST								
25.085	P01074-201 803580 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	I:0 I:0			24-MAR-2016	24-MAR-2026	
	Calibration Date: 24-MAR-2016								
+ 256036	RECERTIFY NO. 7 LIFE VEST								
25.090	P01074-201 774773 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	I:0 I:0			24-MAR-2016	24-MAR-2026	
	Calibration Date: 24-MAR-2016								
+ 256037	RECERTIFY NO. 8 LIFE VEST								
25.090	P01074-201 774819 REF: GENERIC NO REF	MOS HRS/MSC AFL	120				24-MAR-2016	24-MAR-2026	
	Calibration Date: 24-MAR-2016								
+ 256038	RECERTIFY NO. 9 LIFE VEST								
25.095	P01074-201 803579 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	I:0 I:0			24-MAR-2016	24-MAR-2026	
	Calibration Date: 24-MAR-2016								
+ 256039	RECERTIFY NO. 10 LIFE VEST								
25.095	P01074-201 803572 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	I:0 I:0			24-MAR-2016	24-MAR-2026	
	Calibration Date: 24-MAR-2016								
+ 256050	INSPECT AFT FUSELAGE BAGGAGE COMPARTMENT HOOK FASTENER (VELCRO)								
25.120		MOS HRS/MSC AFL	400	+20			26-AUG-2019 3871.6 3259	4271.6	4291.6
AIRWORTHINESS	REF: AMM 25-50-00								
+ 256052	REPLACE AFT BAGGAGE COMPARTMENT VELCRO (HOOK ONLY)								
25.115		MOS HRS/MSC AFL	2600				15-SEP-2015 2587 2236	5187	
LIFE LIMIT	REF: AMM 25-50-00								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258010	AIRSHOW DIGITAL INTERFACE UNIT								
25.190	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
258011	COCKPIT CONTROL - AIRSHOW UNIT								
28.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
258014	FORWARD AIRSHOW COLOR MONITOR-								
25.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
258015	AFT AIRSHOW COLOR MONITOR-								
25.160	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
258016	FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY								
25.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
258017	AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY								
25.180	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 26	FIRE PROTECTION								
261001	LEFT ENGINE FIRE DETECTION CONTROL UNIT								
26.010	244-25282 062501 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-JAN-2007 569.4 496		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261002	RIGHT ENGINE FIRE DETECTION CONTROL UNIT								
26.010	244-25282 062502 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-JAN-2007 569.4 496		
261005	ASSEMBLY (A248) CONTROL								
26.080	477-23906 0526-132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
261013	LEFT ENGINE FIRE DETECTION SENSOR								
26.020	244-25282 062501 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JAN-2007 569.4 496		
261014	RIGHT ENGINE FIRE DETECTION SENSOR								
26.020	244-25282 062502 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JAN-2007 569.4 496		
262001	NO. 1 ENGINE FIRE EXTINGUISHER								
26.040	30400018-1 44475B1 REF: AMM 26-20-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			12-DEC-2019 3939.4 3315		
262002	NO. 2 ENGINE FIRE EXTINGUISHER								
26.050	30400018-1 41058B1 REF: AMM 26-20-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			10-SEP-2020 4030.73 3391		
262003	COCKPIT PORTABLE FIRE EXTINGUISHER								
26.060	C352TS Y-278335 REF: AMM 26-21-00	MOS HRS/MSC AFL	O/C				01-JAN-2012 0 0		
262004	CABIN PORTABLE FIRE EXTINGUISHER								
26.070	C352TS Y-278189 REF: AMM 26-21-00	MOS HRS/MSC AFL	O/C				01-JAN-2012 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 262005	HYDROSTATIC TEST COCKPIT PORTABLE FIRE EXTINGUISHER C352TS Y-278335	MOS HRS/MSC AFL	144				01-JAN-2012	01-JAN-2024	
26.060	MANDATORY HydroCheck Date: 01-JAN-2012	REF: GENERIC CMM							
+ 262006	HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER C352TS Y-278189	MOS HRS/MSC AFL	144				01-JAN-2012	01-JAN-2024	
26.070	MANDATORY HydroCheck Date: 01-JAN-2012	REF: GENERIC CMM							
+ 262025	INSPECT/HYDROSTATIC TEST NO. 1 ENGINE FIRE EXTINGUISHER 30400018-1 44475B1	MOS HRS/MSC AFL	60				17-SEP-2019	17-SEP-2024	
26.040	AIRWORTHINESS	REF: GENERIC NO REF							
+ 262026	INSPECT/HYDROSTATIC TEST NO. 2 ENGINE FIRE EXTINGUISHER 30400018-1 41058B1	MOS HRS/MSC AFL	60				01-OCT-2019	01-OCT-2024	
26.050	AIRWORTHINESS	REF: GENERIC NO REF							
+ 262037	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (SERVICE LIFE) MOS HRS/MSC AFL	48					17-SEP-2019	17-SEP-2023	
26.040	SCRAP	REF: AMM 26-20-00							
+ 262038	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (SERVICE LIFE) MOS HRS/MSC AFL	48					17-JUL-2020	17-JUL-2024	
26.050	SCRAP	REF: AMM 26-20-00							
+ 262039	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (SERVICE LIFE) MOS HRS/MSC AFL	48					23-AUG-2018	23-AUG-2022	
26.040	SCRAP	REF: AMM 26-20-00							



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 262040	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (SERVICE LIFE)								
26.050		MOS	48				17-JUL-2020	17-JUL-2024	
SCRAP	REF: AMM 26-20-00	HRS/MSC AFL							
+ 262042	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (LIFE LIMIT)								
26.040		MOS	72				01-NOV-2017	01-NOV-2023	
LIFE LIMIT	REF: AMM 26-20-00	HRS/MSC AFL							
+ 262043	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 1 CARTRIDGE (LIFE LIMIT)								
26.050		MOS	72				02-MAR-2020	02-MAR-2026	
LIFE LIMIT	REF: AMM 26-20-00	HRS/MSC AFL							
+ 262044	REPLACE NO. 1 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (LIFE LIMIT)								
26.040		MOS	72				01-NOV-2017	01-NOV-2023	
LIFE LIMIT	REF: AMM 26-20-00	HRS/MSC AFL							
+ 262045	REPLACE NO. 2 ENGINE FIRE EXTINGUISHER NO. 2 CARTRIDGE (LIFE LIMIT)								
26.050		MOS	72				01-NOV-2017	01-NOV-2023	
LIFE LIMIT	REF: AMM 26-20-00	HRS/MSC AFL							
+ 262049	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER								
26.060		MOS	12				19-AUG-2020	19-AUG-2021	
	REF: GENERIC CMM	HRS/MSC AFL							
+ 262050	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER								
26.070		MOS	12				19-AUG-2020	19-AUG-2021	
	REF: GENERIC CMM	HRS/MSC AFL							
262079	CABIN BAGGAGE SMOKE DETECTOR								
26.030	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 27	FLIGHT CONTROLS								
271001	LEFT ROLL TRIM ACTUATOR								
27.010	45AS61014-107 66609015 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:10 O:0 O:0			23-AUG-2017 3349.6 2865		
271002	RIGHT ROLL TRIM ACTUATOR								
27.010	45AS61014-108 990305 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:9 O:0 O:0			04-SEP-2017 3359.2 2873		
271023	ROLL TRIM POSITION INDICATOR								
27.030	45AS86848-001 03100808A REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			19-MAY-2011 1888.2 1655		
272001	RUDDER								
27.050	45A24001-211 RK-466 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
272007	RUDDER TRIM TAB ACTUATOR								
27.060	45AS61014-111 50802 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 272013	UPPER RUDDER HINGE ASSEMBLY								
27.070	45A23205-001 09210503ICT REF: AMM 27-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 272014	LOWER RUDDER HINGE ASSEMBLY								
27.070	45A23204-001 08100502ICT REF: AMM 27-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272041	RUDDER TRIM POSITION INDICATOR								
27.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
273001	LEFT ELEVATOR								
27.160	45A22002-641 RK-466 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2010 1888.2 1655		
273002	RIGHT ELEVATOR								
27.160	45A22002-642 RK-465 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			03-OCT-2010 1888.2 1655		
+ 273013	LEFT INBOARD ELEVATOR HINGE ASSEMBLY								
27.170	45A21188-005 11300501SAL REF: AMM 27-30-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 273014	RIGHT INBOARD ELEVATOR HINGE ASSEMBLY								
27.170	45A21188-005 11290501SAL REF: AMM 27-30-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 273015	LEFT OUTBOARD ELEVATOR HINGE ASSEMBLY								
27.180	45A21187-001 11200501SAL REF: AMM 27-30-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 273016	RIGHT OUTBOARD ELEVATOR HINGE ASSEMBLY								
27.180	45A21187-001 11290501SAL REF: AMM 27-30-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
273037	PILOT COLUMN CONTROL								
27.190	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273038	COPILOT COLUMN CONTROL								
27.190	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
274001	HORIZONTAL STABILIZER								
27.240	45A21001-663 RK-465 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 274007	PITCH TRIM ACTUATOR								
27.250 LIFE LIMIT*	45AS61023-143 ET0096 REF: See Workcard	MOS HRS/MSC AFL	1800	O:0 O:0 O:0			26-AUG-2019 3871.6 3259	5671.6	
274034	PITCH TRIM POSITION INDICATOR								
27.280	PN SN-UNKNOWN REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
274046	STABILIZER TRIM POSITION TRANSMITTER								
27.300	45AS86805-019 05K217 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275001	LEFT MAIN FLAP ASSEMBLY								
27.310	45A16001-031 RK-465 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275002	RIGHT MAIN FLAP ASSEMBLY								
27.310	45A16001-032 RK-465 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275003	LEFT AFT FLAP ASSEMBLY								
27.320	45A16241-001 RK-466 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275004	RIGHT AFT FLAP ASSEMBLY								
27.320	45A16241-002 RK-465 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275025	LEFT FLAP ACTUATOR								
27.330	45AS61021-009 1401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275026	RIGHT FLAP ACTUATOR								
27.330	45AS61021-010 1422 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275043	LEFT FLAP ASYMMETRY DETECTOR								
27.340	45AS86805-17 05E72 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-MAY-2007 770.3 663		
275044	RIGHT FLAP ASYMMETRY DETECTOR								
27.340	45AS86805-17 05H208 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-MAY-2007 770.3 663		
275047	LEFT FLAP FOLLOW-UP SWITCH								
27.350	45AS61015-025 05H398 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275048	RIGHT FLAP FOLLOW-UP SWITCH								
27.350	45AS61015-023 05H307 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
275051	LEFT FLAP POSITION TRANSMITTER								
27.360	45AS86805-033 5156 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275052	RIGHT FLAP POSITION TRANSMITTER								
27.360	45AS86805-031 6134 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 275055	REPLACE LEFT WING FLAP BOLTS								
27.370		MOS HRS/MSC AFL	22400	I:0 I:0			23-MAR-2006 0 0	22400	
LIFE LIMIT	REF: GENERIC NO REF								
+ 275056	REPLACE RIGHT WING FLAP BOLTS								
27.370		MOS HRS/MSC AFL	22400	I:0 I:0			23-MAR-2006 0 0	22400	
LIFE LIMIT	REF: GENERIC NO REF								
+ 275089	LEFT MAIN FLAP CENTER RAIL SUPPORT ASSEMBLY								
27.380	132-100033-13 072505181CT REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 275090	RIGHT MAIN FLAP CENTER RAIL SUPPORT ASSEMBLY								
27.380	132-100033-14 101405081ICT REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 275091	LEFT MAIN FLAP OUTBOARD RAIL SUPPORT ASSEMBLY								
27.410	45A10420-021 11280501SAL REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 275092	RIGHT MAIN FLAP OUTBOARD RAIL SUPPORT ASSEMBLY								
27.410	45A10420-022 11170501SAL REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									
+ 275093	LEFT MAIN FLAP INBOARD RAIL SUPPORT ASSEMBLY								
27.290	45A10422-031 11280501SAL REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 275094	RIGHT MAIN FLAP INBOARD RAIL SUPPORT ASSEMBLY								
	45A10422-032	MOS		N:0			23-MAR-2006		
27.290	11170501SAL	HRS/MSC	22400	N:0			0	22400	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			0		
+ 275095	LEFT AFT FLAP OUTBOARD RAIL								
	45A16087-013	MOS		N:0			23-MAR-2006		
27.270	022105008ICT	HRS/MSC	22400	N:0			0	22400	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			0		
+ 275096	RIGHT AFT FLAP OUTBOARD RAIL								
	45A16087-014	MOS		N:0			23-MAR-2006		
27.270	12080501SAL	HRS/MSC	22400	N:0			0	22400	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			0		
+ 275097	LEFT AFT FLAP INBOARD RAIL								
	45A16127-003	MOS		N:0			23-MAR-2006		
27.260	09010506ICT	HRS/MSC	22400	N:0			0	22400	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			0		
+ 275098	RIGHT AFT FLAP INBOARD RAIL								
	45A16127-004	MOS		N:0			23-MAR-2006		
27.260	5170523	HRS/MSC	22400	N:0			0	22400	
LIFE LIMIT	REF: GENERIC NO REF	AFL		N:0			0		
275131	FLAP SYSTEM LEFT LOCK VALVE								
	PN	MOS		N:0			23-MAR-2006		
27.230	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
275132	FLAP SYSTEM RIGHT LOCK VALVE								
	PN	MOS		N:0			23-MAR-2006		
27.230	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
275155	FLAP POSITION INDICATOR								
	45AS86805-029	MOS		N:0			23-MAR-2006		
27.220	04H213A	HRS/MSC	O/C	N:0			0		
	REF: AMM 31-10-00	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 276001	LEFT INBOARD SPOILER								
	45A10501	MOS		N:0			23-MAR-2006		
27.210	SN-UNKNOWN	HRS/MSC	14600	N:0			0		14600
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
+ 276002	RIGHT INBOARD SPOILER								
	45A10502	MOS		N:0			23-MAR-2006		
27.210	SN-UNKNOWN	HRS/MSC	14600	N:0			0		14600
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
+ 276003	LEFT OUTBOARD SPOILER								
	45A10501	MOS		N:0			23-MAR-2006		
27.200	SN-UNKNOWN	HRS/MSC	14600	N:0			0		14600
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
+ 276004	RIGHT OUTBOARD SPOILER								
	45A10502	MOS		N:0			23-MAR-2006		
27.200	SN-UNKNOWN	HRS/MSC	14600	N:0			0		14600
LIFE LIMIT	REF: See Workcard	AFL		N:0			0		
276013	SPEED BRAKE ACTUATOR								
	PN	MOS		N:0			23-MAR-2006		
27.150	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
276031	LEFT SPOILER LEFT HINGE								
	PN	MOS		N:0			23-MAR-2006		
27.140	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-00	AFL		N:0			0		
276032	RIGHT SPOILER LEFT HINGE								
	PN	MOS		N:0			23-MAR-2006		
27.140	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-00	AFL		N:0			0		
276033	LEFT SPOILER RIGHT HINGE								
	PN	MOS		N:0			23-MAR-2006		
27.130	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-00	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276034	RIGHT SPOILER RIGHT HINGE								
27.130	PN SN-UNKNOWN REF: AMM 27-60-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
276055	LEFT SPOILER FITTINGS								
27.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
276056	RIGHT SPOILER FITTINGS								
27.120	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 28 FUEL									
281001	LEFT CENTER TANK								
28.010	128-384025-1 98-80692 REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	R:7 R:0 R:0			10-JUL-2015 2519.5 2188		
281002	RIGHT CENTER TANK								
28.010	128-384025-2 97-52432 REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	R:14 R:0 R:0			10-JUL-2015 2519.5 2188		
281003	AFT FUSELAGE TANK								
28.020	128-384023-1 05-06544 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281009	LH FUEL CELL								
28.490	128-384016-1 05-05886 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281010	RH FUEL CELL								
28.490	128-384017-1 05-05910 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 281012	DETAIL INSPECT FUSELAGE FILLER FUEL TANK (128-920022)								
28.210	REF: AMM 05-20-02	MOS HRS/MSC AFL	2400 +20				03-NOV-2014 2501.6 2171	4901.6	4921.6
281013	LEFT FORWARD FLAPPER CHECK VALVE								
28.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281014	LEFT MIDDLE FLAPPER CHECK VALVE								
28.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281015	LEFT AFT FLAPPER CHECK VALVE								
28.440	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281016	RIGHT FORWARD FLAPPER CHECK VALVE								
28.450	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281017	RIGHT MIDDLE FLAPPER CHECK VALVE								
28.450	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281018	RIGHT AFT FLAPPER CHECK VALVE								
28.450	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281019	LEFT WING CARRY THRU FLOAT SWITCH								
28.030	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281021	RIGHT WING CARRY THRU FLOAT SWITCH								
28.040	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281022	RIGHT WING AFT INBOARD FLOAT VALVE								
28.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281023	LEFT WING SURGE SPACE VENT VALVE								
28.050	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281024	RIGHT WING SURGE SPACE VENT VALVE								
28.050	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281027	LEFT LEVEL CONTROL VALVE								
28.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281028	RIGHT LEVEL CONTROL VALVE								
28.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281029	LEFT INBOARD WING TANK SNIFFLE VALVE								
28.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281030	RIGHT INBOARD WING TANK SNIFFLE VALVE								
28.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281031	AFT FUSELAGE TANK SNIFFLE VALVE								
28.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281032	LEFT VENT FLOAT VALVE								
28.100	132-920281-19 816 REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			24-OCT-2012 2300.3 2026		
281033	RIGHT VENT FLOAT VALVE								
28.100	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281037	LEFT OUTBOARD WING TANK SNIFFLE VALVE								
28.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
281044	RIGHT OUTBOARD WING TANK SNIFFLE VALVE								
28.110	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282001	LEFT FUEL BOOST PUMP								
28.120	45AS48015-002 2AN19 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-AUG-2018 3598.2 3045		
282002	RIGHT FUEL BOOST PUMP								
28.120	45AS48015-002 2AT22 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282003	LEFT PRIMARY JET FUEL PUMP								
28.130	45AS48018-001 1694 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282004	RIGHT PRIMARY JET FUEL PUMP								
28.130	45AS48018-001 1686 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282005	LEFT FORWARD FUEL TRANSFER JET PUMP								
28.140	128-389033-1 674 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282006	RIGHT FORWARD FUEL TRANSFER JET PUMP								
28.140	128-389033-2 672 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282008	LEFT AFT FUEL TRANSFER JET PUMP								
28.025	128-389033-5 696 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282009	RIGHT AFT FUEL TRANSFER JET PUMP								
28.025	128-389033-6 680 REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282010	LEFT FUEL BOOSTER TRANSFER PUMP								
28.480	45AS48015-002 8BA181 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282011	RIGHT FUEL BOOSTER TRANSFER PUMP								
28.480	45AS48015-002 8BA185 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282048	FUEL CROSSFEED VALVE								
28.160	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282049	LEFT CROSSFEED VALVE								
28.160	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282050	RIGHT CROSSFEED VALVE								
28.160	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282051	LEFT FUEL TRANSFER SHUT-OFF VALVE								
28.170	45AS48017-007 2264 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-AUG-2011 1999.1 1756		
282052	RIGHT FUEL TRANSFER SHUT-OFF VALVE								
28.170	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282053	LEFT FUEL FEED SHUT-OFF VALVE								
28.180	1321-518316 1516 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282054	RIGHT FUEL FEED SHUT-OFF VALVE								
28.180	1321-518316 1510 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282055	LEFT MOTIVE FLOW SHUT-OFF VALVE								
28.190	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282056	RIGHT MOTIVE FLOW SHUT-OFF VALVE								
28.190	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282057	LEFT MANUAL DEFUEL VALVE								
28.200	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282058	RIGHT MANUAL DEFUEL VALVE								
28.200	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282169	LEFT FUEL FILTER								
28.220	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282170	RIGHT FUEL FILTER								
28.220	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282200	LEFT (TRANSFER FUEL) LOW PRESSURE SWITCH								
28.230	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282201	RIGHT (TRANSFER FUEL) LOW PRESSURE SWITCH								
28.230	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282209	LEFT (FUEL FEED) LOW PRESSURE SWITCH								
28.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282213	RIGHT (FUEL FEED) LOW PRESSURE SWITCH								
28.240	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282219	LEFT WING NO. 1 DRAIN VALVE								
28.250	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282220	RIGHT WING NO. 1 DRAIN VALVE								
28.250	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282221	LEFT WING NO. 2 DRAIN VALVE								
28.260	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282222	RIGHT WING NO. 2 DRAIN VALVE								
28.260	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282223	LEFT WING NO. 3 DRAIN VALVE								
28.270	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282224	RIGHT WING NO. 3 DRAIN VALVE								
28.270	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
282225	LEFT WING NO. 4 DRAIN VALVE								
28.280	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282226	RIGHT WING NO. 4 DRAIN VALVE								
28.280	PN SN-UNKNOWN REF: AMM 28-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284001	WING FUEL TANK QUANTITY INDICATOR								
28.290	PN CAE330011 REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
284002	FUSELAGE FUEL TANK QUANTITY INDICATOR								
28.300	PN CAE330011 REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
284005	FUEL QUANTITY AMPLIFIER								
28.310	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 284013	CALIBRATE WING FUEL TANK QUANTITY INDICATOR								
28.290	PN CAE330011 REF: AMM 28-41-00	MOS HRS/MSC AFL	24				26-AUG-2019 3871.6 3259	26-AUG-2021	
+ 284014	CALIBRATE FUSELAGE FUEL TANK QUANTITY INDICATOR								
28.300	PN CAE330011 REF: AMM 28-41-00	MOS HRS/MSC AFL	24				26-AUG-2019 3871.6 3259	26-AUG-2021	
284035	LEFT WING INBOARD FUEL QUANTITY TRANSMITTER								
28.150	128-389001-1 1559 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284036	RIGHT WING INBOARD FUEL QUANTITY TRANSMITTER								
28.150	128-389001-1 1556 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			04-AUG-2014 2501.5 2165		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284037	AUXILIARY FUEL TANK FUEL QUANTITY TRANSMITTER								
28.360	128-389001-13 622 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284038	MID-FUSELAGE TANK OUTBOARD FUEL QUANTITY TRANSMITTER								
28.360	128-389001-9 843 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284039	MID-FUSELAGE TANK INBOARD FUEL QUANTITY TRANSMITTER								
28.400	128-389001-7 841 REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284040	AFT FUSELAGE TANK FUEL QUANTITY TRANSMITTER								
28.400	128-389001-11 616 REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284041	LEFT WING TANK INBOARD FUEL QUANTITY TRANSMITTER								
28.410	128-389001-3 1565 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284042	RIGHT WING TANK INBOARD FUEL QUANTITY TRANSMITTER								
28.410	128-389001-3 1563 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284043	LEFT WING TANK CENTER FUEL QUANTITY TRANSMITTER								
28.420	128-389001-15 1436 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284044	RIGHT WING TANK CENTER FUEL QUANTITY TRANSMITTER								
28.420	128-389001-15 1444 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284045	LEFT WING TANK OUTBOARD FUEL QUANTITY TRANSMITTER								
28.430	128-389001-5 1550 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284046	RIGHT WING TANK OUTBOARD FUEL QUANTITY TRANSMITTER								
28.430	128-389001-5 1551 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 284050	LEFT FORWARD FUSELAGE FUEL TANK								
28.320	PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284051	RIGHT AFT FUEL FILLER TANK								
28.330	128-384018-1 05-06870 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 284052	RIGHT FORWARD FUSELAGE FUEL TANK								
28.320	PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 284057	DETAIL INSPECT LEFT FORWARD AUXILIARY FUEL TANK								
28.350 AIRWORTHINESS	REF:	MOS HRS/MSC AFL	2400	+20			03-NOV-2014 2501.6 2171	4901.6	4921.6
+ 284058	DETAIL INSPECT RIGHT FORWARD AUXILIARY FUEL TANK								
28.350 AIRWORTHINESS	REF:	MOS HRS/MSC AFL	2400	+20			03-NOV-2014 2501.6 2171	4901.6	4921.6
284115	FUEL TEMPERATURE INDICATOR								
28.380	PN CAE330011 REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284121	LEFT TANK LOW LEVEL FLOAT SWITCH								
28.390	PN SN-UNKNOWN REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284122	RIGHT TANK LOW LEVEL FLOAT SWITCH								
28.390	45AS48013-003 15278U REF: AMM 28-21-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			18-MAY-2008 1423 1223		
284123	LEFT WING FUEL OVERPRESSURE SWITCH								
28.370	PN SN-UNKNOWN REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284124	RIGHT WING FUEL OVERPRESSURE SWITCH								
28.370	PN SN-UNKNOWN REF: AMM 28-41-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284126	LEFT WING NO. 1 FLOAT SWITCH								
28.460	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284127	LEFT WING NO. 2 FLOAT SWITCH								
28.460	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284128	RIGHT WING NO. 1 FLOAT SWITCH								
28.470	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
284129	RIGHT WING NO. 2 FLOAT SWITCH								
28.470	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 29	HYDRAULIC POWER								
291001	HYDRAULIC PACKAGE								
29.010	45AS65021-015 651 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
291002	HYDRAULIC VALVE PACKAGE								
29.020	45AS65022-023 658 REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
291043	LEFT HYDRAULIC ISOLATION VALVE								
29.030	PN SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
291044	RIGHT HYDRAULIC ISOLATION VALVE								
29.030	PN SN-UNKNOWN REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
291055	NO. 1 ENGINE HYDRAULIC PUMP								
29.040	45AS65020-001 MX361173C REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-JUN-2009 1785.2 1565		
291056	NO. 2 ENGINE HYDRAULIC PUMP								
29.040	45AS65020-001 MX692806C REF: AMM 29-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
293001	HYDRAULIC PRESSURE TRANSDUCER								
29.050	PN SN-UNKNOWN REF: AMM 29-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293007	HYDRAULIC PRESSURE INDICATOR								
29.060	45AS86846-009 05090845BA REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
293013	HYDRAULIC LOW LEVEL SWITCH								
29.070	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
293014	LEFT HYDRAULIC LOW PRESSURE SWITCH								
29.080	45AS65572-009 K4830 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JAN-2018 3473.1 2951		
293015	RIGHT HYDRAULIC LOW PRESSURE SWITCH								
29.080	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 30	ICE AND RAIN PROTECTION								
301001	WING ANTI-ICE CONTROL VALVE								
30.010	45AS66001-011 0921A REF: AMM 30-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301007	LEFT WING S054 OVERTEMP SWITCH								
30.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301008	RIGHT WING S052 OVERTEMP SWITCH								
30.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301009	LEFT WING S158 OVERTEMP SWITCH								
30.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301010	RIGHT WING S157 OVERTEMP SWITCH								
30.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301011	LEFT WING S191 OVERTEMP SWITCH								
30.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301012	RIGHT WING S192 OVERTEMP SWITCH								
30.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301013	LEFT WING S055 OVERTEMP SWITCH								
30.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301014	RIGHT WING S053 OVERTEMP SWITCH								
30.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301067	ANTI-ICE TEMPERATURE CONTROLLER								
30.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
301073	DEICE TIMER UNIT								
30.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301079	LEFT HORIZONTAL STABILIZER HEATER MAT 128-380078-9	MOS		N:0			23-MAR-2006		
30.080	MYGDQMO REF: AMM 30-12-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301080	RIGHT HORIZONTAL STABILIZER HEATER MAT 128-380078-10	MOS		N:0			23-MAR-2006		
30.080	MYF6UTO REF: AMM 30-12-00	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301081	LEFT ELEVATOR HORN HEATER MAT 45AS66010-019	MOS		N:0			23-MAR-2006		
30.090	05-40031 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301082	RIGHT ELEVATOR HORN HEATER MAT 45AS66010-020	MOS		N:0			23-MAR-2006		
30.090	05-40132 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301090	MOSFET (K251) CONTACTOR PN	MOS		N:0			23-MAR-2006		
30.160	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301091	MOSFET (K252) CONTACTOR PN	MOS		N:0			23-MAR-2006		
30.170	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301092	MOSFET (K253) CONTACTOR PN	MOS		N:0			23-MAR-2006		
30.180	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		
301093	MOSFET (K254) CONTACTOR PN	MOS		N:0			23-MAR-2006		
30.190	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC AFL	O/C	N:0 N:0			0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301103	WING ANTI-ICE DUCT SWITCH								
30.100	45AS48008-003 U028857A REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JAN-2018 3473.1 2951		
302001	LEFT NACELLE INLET BLEED AIR VALVE								
30.130	45AS63019-009 1758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
302002	RIGHT NACELLE INLET BLEED AIR VALVE								
30.130	45AS63019-009 1759 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
302005	LEFT PRESSURE REGULATOR SHUTOFF VALVE								
30.210	PN SN-UNKNOWN REF: AMM 21-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
302006	RIGHT PRESSURE REGULATOR SHUTOFF VALVE								
30.210	PN SN-UNKNOWN REF: AMM 21-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
302013	LEFT NACELLE TEMPERATURE SWITCH								
30.140	PN SN-UNKNOWN REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
302014	RIGHT NACELLE TEMPERATURE SWITCH								
30.140	PN SN-UNKNOWN REF: AMM 30-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
304019	LEFT WINDSHIELD TEMPERATURE CONTROL								
30.110	HYLZ50310 5918C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304020	RIGHT WINDSHIELD TEMPERATURE CONTROL								
30.110	HYLZ50310 5323C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
308005	ICE DETECTOR								
30.200	0871CT2 1243 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
311009	LEFT CURSOR CONTROL (CCP) PANEL								
	822-1746-002 4C42HG REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
311010	RIGHT CURSOR CONTROL (CCP) PANEL								
	822-1746-002 4DL72P REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
312001	PILOT CLOCK								
31.010	PN CAE330011 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
312002	COPILOT CLOCK								
31.020	PN CAE330011 REF: See Workcard	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
314001	NO. 1 ENVIRONMENTAL (IEC) CONTROL								
31.050	822-0333-001 2411L REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314004	NO. 2 ENVIRONMENTAL (IEC) CONTROL								
31.050	822-0333-001 2411N REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
314011	NO. 1 FLIGHT MANAGEMENT FMC-6000 CARD								
31.065	822-0868-133 296GB REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
314016	NO. 2 FLIGHT MANAGEMENT FMC-6000 CARD								
31.060	822-0868-133 158R REF:	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
314026	#1 OPTION CONFIGURATION MODULE								
	822-1463-228 4F1HPY REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
314027	#2 OPTION CONFIGURATION MODULE								
	822-1463-228 4F1HPX REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
314047	NO. 1 CONFIGURATION STRAPPING (CSU) UNIT								
31.055	822-1362-002 4F1K0R REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
314048	NO. 2 CONFIGURATION STRAPPING (CSU) UNIT								
31.055	822-1364-002 4F1KLK REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
314050	MAINTENANCE DIAGNOSTIC COMPUTER								
34.800	822-1987-006 4F1K1Y REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316201	NO. 1 FILE SERVER (FSU) UNIT 822-1543-201 4D98VG REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
CHAPTER 32 LANDING GEAR									
+ 321001	INSPECT LEFT MAIN GEAR STRUT LEFT MAIN GEAR STRUT 128-810085-613 11280501ICT REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+20 +15			23-MAR-2006 0 0	7400 5000	7420 5015
32.010	AIRWORTHINESS								
+ 321002	INSPECT RIGHT MAIN GEAR STRUT RIGHT MAIN GEAR STRUT 128-810085-614 12220501ICT REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+20 +15			23-MAR-2006 0 0	7400 5000	7420 5015
32.010	AIRWORTHINESS								
+ 321003	INSPECT LEFT MAIN GEAR SIDE STRUT LEFT MAIN GEAR SIDE STRUT 128-810081-5 1260601 REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+20 +15			23-MAR-2006 0 0	7400 5000	7420 5015
32.030	AIRWORTHINESS								
+ 321004	INSPECT RIGHT MAIN GEAR SIDE STRUT RIGHT MAIN GEAR SIDE STRUT 128-810081-6 1040601 REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+20 +15			23-MAR-2006 0 0	7400 5000	7420 5015
32.030	AIRWORTHINESS								
+ 321005	LEFT MAIN GEAR STRUT 128-810085-613 11280501ICT REF: AMM 32-10-00	MOS HRS/MSC AFL	15000	N:0 N:0 N:0			23-MAR-2006 0 0	15000	
32.010	LIFE LIMIT								
+ 321006	RIGHT MAIN GEAR STRUT 128-810085-614 12220501ICT REF: AMM 32-10-00	MOS HRS/MSC AFL	15000	N:0 N:0 N:0			23-MAR-2006 0 0	15000	
32.010	LIFE LIMIT								



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 321009	LEFT MAIN GEAR SIDE STRUT								
	128-810081-5	MOS		N:0			23-MAR-2006		
32.030	1260601	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	15000	N:0			0		15000
+ 321010	RIGHT MAIN GEAR SIDE STRUT								
	128-810081-6	MOS		N:0			23-MAR-2006		
32.030	1040601	HRS/MSC		N:0			0		
LIFE LIMIT	REF: See Workcard	AFL	15000	N:0			0		15000
+ 321047	LEFT MAIN LANDING GEAR SUPPORT FITTING								
	45A10207-019	MOS		N:0			23-MAR-2006		
32.050	11170501SAL	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	15000	N:0			0		15000
+ 321048	RIGHT MAIN LANDING GEAR SUPPORT FITTING								
	45A10207-020	MOS		N:0			23-MAR-2006		
32.050	11010501SAL	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	15000	N:0			0		15000
+ 321049	EDDY CURRENT INSPECT LEFT MAIN LANDING GEAR SUPPORT FITTING								
		MOS					23-MAR-2006		
32.050		HRS/MSC	5000	+20			0		5000 5020
AIRWORTHINESS	REF: AMM 57-40-00	AFL					0		
+ 321050	EDDY CURRENT INSPECT RIGHT MAIN LANDING GEAR SUPPORT FITTING								
		MOS					23-MAR-2006		
32.050		HRS/MSC	5000	+20			0		5000 5020
AIRWORTHINESS	REF: AMM 57-40-00	AFL					0		
+ 321060	REPLACE LEFT MAIN LANDING GEAR TORQUE LINK BOLT								
		MOS		I:0			23-MAR-2006		
32.420		HRS/MSC		I:0			0		
LIFE LIMIT	REF: AMM 32-10-00	AFL	9800				0		9800
+ 321065	REPLACE RIGHT MAIN LANDING GEAR TORQUE LINK BOLT								
		MOS		I:0			23-MAR-2006		
32.420		HRS/MSC		I:0			0		
LIFE LIMIT	REF: AMM 32-10-00	AFL	9800				0		9800

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 322001	INSPECT NOSE GEAR STRUT NOSE GEAR STRUT 128-820028-11 00080 REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+15			30-AUG-2019 3872.7 3260	11272.7 8260	11292.7 8275
32.060 AIRWORTHINESS									
+ 322003	NOSE GEAR STRUT 128-820028-11 00080 REF: AMM 32-20-00	MOS HRS/MSC AFL	15000		N:4981		30-AUG-2019 3872.7 3260	13279	
32.060 LIFE LIMIT									
+ 322009	INSPECT NOSE GEAR DRAG STRUT ASSEMBLY NOSE GEAR DRAG STRUT ASSEMBLY 128-820044-605 01110604ICT REF: See Workcard	MOS HRS/MSC AFL	7400 +20 5000	+15			23-MAR-2006 0 0	7400 5000	7420 5015
32.035 AIRWORTHINESS									
+ 322010	NOSE GEAR DRAG STRUT ASSEMBLY 128-820044-605 01110604ICT REF: AMM 32-20-00	MOS HRS/MSC AFL	15000		N:0 N:0 N:0		23-MAR-2006 0 0	15000	
32.035 LIFE LIMIT									
322031	NOSE WHEEL SHIMMY DAMPER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		23-MAR-2006 0 0		
32.090									
+ 322043	LEFT NOSE LANDING GEAR FITTING 45A31311-021 10050501SAL REF: GENERIC NO REF	MOS HRS/MSC AFL	15000		N:0 N:0 N:0		23-MAR-2006 0 0	15000	
32.440 LIFE LIMIT									
+ 322044	RIGHT NOSE LANDING GEAR FITTING 45A31311-022 10050502SAL REF: GENERIC NO REF	MOS HRS/MSC AFL	15000		N:0 N:0 N:0		23-MAR-2006 0 0	15000	
32.440 LIFE LIMIT									
323001	LEFT MAIN LANDING GEAR RETRACTION CYLINDER 45AS38515 SN-UNKNOWN REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C				23-MAR-2006 0 0		
32.110									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323002	RIGHT MAIN LANDING GEAR RETRACTION CYLINDER								
32.110	45AS38515 SN-UNKNOWN REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C				23-MAR-2006 0 0		
323003	NOSE LANDING GEAR RETRACTION CYLINDER								
32.120	45AS39503-005 738 REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323004	LEFT MAIN LANDING GEAR UPLOCK MECHANISM ACTUATOR								
32.130	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323005	RIGHT MAIN LANDING GEAR UPLOCK MECHANISM ACTUATOR								
32.140	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323006	NOSE GEAR UPLOCK MECHANISM ACTUATOR								
32.150	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323007	LEFT MAIN LANDING GEAR DOWNLOCK MECHANISM ACTUATOR								
32.160	45AS38510-007 1418 REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323008	RIGHT MAIN LANDING GEAR DOWNLOCK MECHANISM ACTUATOR								
32.160	45AS38510-008 1409 REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323009	NOSE GEAR DOWNLOCK MECHANISM ACTUATOR								
32.170	45AS39504-007 SN-UNKNOWN REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323010	LEFT MAIN LANDING GEAR DOOR ACTUATOR								
32.180	45AS38515-007 1535 REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323011	RIGHT MAIN LANDING GEAR DOOR ACTUATOR								
32.180	45AS38515-008 1541 REF: AMM 32-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 323015	EDDY CURRENT INSPECT LEFT MAIN LANDING GEAR RETRACTION CYLINDER								
32.450	REF: AMM 20-80-03	MOS HRS/MSC AFL	7400 5000	+20 +15			23-MAR-2006 7400 5000	7420 5015	
+ 323016	EDDY CURRENT INSPECT RIGHT MAIN LANDING GEAR RETRACTION CYLINDER								
32.450	REF: AMM 20-80-03	MOS HRS/MSC AFL	7400 5000	+20 +15			23-MAR-2006 7400 5000	7420 5015	
+ 323017	EDDY CURRENT INSPECT NOSE LANDING GEAR RETRACTION CYLINDER								
32.460	REF: AMM 20-80-03	MOS HRS/MSC AFL	7400 5000	+20 +15			23-MAR-2006 7400 5000	7420 5015	
323061	LEFT MAIN LANDING GEAR DOOR UPLOCK RELEASE CYLINDER								
32.190	45AS38502-005 1325 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323062	RIGHT MAIN LANDING GEAR DOOR UPLOCK RELEASE CYLINDER								
32.190	45AS38502-005 1318 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
323063	NOSE LANDING GEAR UPLOCK RELEASE CYLINDER								
32.070	45AS39502-007 2085 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 323079	AIR STORAGE BOTTLE								
	23111321-1H	MOS	180				26-AUG-2019	08-OCT-2027	
32.200	1609	HRS/MSC		N:3871.6			3871.6		
LIFE LIMIT	REF: AMM 32-30-00	AFL		N:3259			3259		
	Manufacture Date: 08-OCT-2012								
+ 323085	HYDROSTATIC TEST AIR STORAGE BOTTLE								
	23111321-1H	MOS	36				25-JUL-2019	25-JUL-2022	
32.200	1609	HRS/MSC							
AIRWORTHINESS	REF: GENERIC NO REF	AFL							
323087	EMERGENCY BRAKE/GEAR DOWN PRESSURE INDICATOR								
	132-380062-5	MOS		N:0			23-MAR-2006		
32.210	05J242	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
323091	LANDING GEAR CONTROL UNIT								
	122-382038-1	MOS		N:0			23-MAR-2006		
32.220	485	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-30-00	AFL		N:0			0		
+ 323093	REPLACE LEFT MAIN LANDING GEAR DOOR OPENING CABLE								
		MOS					03-NOV-2014		
32.230		HRS/MSC	2400				2501.6	4901.6	
LIFE LIMIT	REF: GENERIC NO REF	AFL					2171		
+ 323094	REPLACE RIGHT MAIN LANDING GEAR DOOR OPENING CABLE								
		MOS					03-NOV-2014		
32.230		HRS/MSC	2400				2501.6	4901.6	
LIFE LIMIT	REF: GENERIC NO REF	AFL					2171		
+ 323097	LEFT MAIN LANDING GEAR FITTING ASSEMBLY								
	45A33506-007	MOS		N:0			23-MAR-2006		
32.240	11300501ICT	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	15000	N:0			0	15000	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 323098	RIGHT MAIN LANDING GEAR FITTING ASSEMBLY								
	45A33506-008	MOS		N:0			23-MAR-2006		
32.240	11300501ICT	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	15000	N:0			0	15000	
324001	LEFT MAIN LANDING GEAR WHEEL								
	5010720-1	MOS		O:28			29-OCT-2019		
32.260	MAR09-2529	HRS/MSC	O/C	O:638.8			3923		
	REF: See Workcard	AFL		O:491			3300		
324002	RIGHT MAIN LANDING GEAR WHEEL								
	5010720-1	MOS		O:24			26-AUG-2019		
32.270	DEC08-2411	HRS/MSC	O/C	O:543.1			3871.6		
	REF: See Workcard	AFL		O:413			3259		
324003	NOSE GEAR WHEEL								
	5006450-5	MOS		O:24 R:4			26-AUG-2019		
32.280	OCT08-3073	HRS/MSC	O/C	O:509.9 R:71.9			3871.6		
	REF: AMM 32-40-00	AFL		O:384 R:55			3259		
324008	INSPECT NOSE GEAR WHEEL								
	5006450-5	MOS					26-APR-2019		
32.280	OCT08-3073	HRS/MSC	T/C				3799.7		
	REF: AMM 32-40-00	AFL					3204		
324009	INSPECT LEFT MAIN LANDING GEAR WHEEL								
	5010720-1	MOS					29-OCT-2019		
32.260	MAR09-2529	HRS/MSC	T/C				3923		
	REF: AMM 32-40-00	AFL					3300		
324010	INSPECT RIGHT MAIN LANDING GEAR WHEEL								
	5010720-1	MOS					07-AUG-2017		
32.270	DEC08-2411	HRS/MSC	T/C				3328.5		
	REF: AMM 32-40-00	AFL					2846		
324055	LEFT MAIN LANDING GEAR TIRE								
	247F63-3	MOS		N:1			29-OCT-2019		
32.260	91542528	HRS/MSC	O/C	N:0			3923		
	REF: See Workcard	AFL		N:0			3300		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324056	RIGHT MAIN LANDING GEAR TIRE 247F63-3 62582491 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-AUG-2017 3328.5 2846		
324057	NOSE GEAR TIRE 184F13-5 73462792 REF: AMM 32-40-00	MOS HRS/MSC AFL	O/C	N:14 N:0 N:0			26-APR-2019 3799.7 3204		
324073	LEFT MAIN GEAR BRAKE ASSEMBLY 5010614 JAN95-293 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			23-AUG-2018 3598.2 3045		
324074	RIGHT MAIN GEAR BRAKE ASSEMBLY 5010614 FEB96-364 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			17-JUL-2020 3998.9 3364		
+ 324096	CLEAN POWER BRAKE CONTROL VALVE FILTERS REF: See Workcard	MOS HRS/MSC AFL	1000	+20			26-AUG-2019 3871.6 3259	4871.6	4891.6
324097	ANTI-SKID POWER BRAKE VALVE 38-771 800 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324098	EMERGENCY BRAKE CONTROL VALVE 45A65261-001 V201/05 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324099	LEFT MIXING VALVE C100169 1208A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-JUN-2006 46 39		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324100	RIGHT MIXING VALVE								
32.360	C100169 1017A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-JUN-2006 46 39		
324101	LEFT PARKING BRAKE VALVE								
32.370	4500-A2 W-34474-1 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-JUL-2020 3998.9 3364		
324102	RIGHT PARKING BRAKE VALVE								
32.370	4500A2 W-34474-1 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			17-JUL-2020 3998.9 3364		
324139	HYDRAULIC EMERGENCY ACCUMULATOR								
32.380	33-073-1 938 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324145	ANTI-SKID CONTROL BOX								
32.390	42-901 823 REF: AMM 32-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324151	BRAKE FLUID RESERVOIR								
32.410	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324157	PILOT LEFT MASTER BRAKE CYLINDER								
32.040	45AS38401-011 2983 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324158	PILOT RIGHT MASTER BRAKE CYLINDER								
32.040	45AS38401-012 2911 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324159	COPILOT LEFT MASTER BRAKE CYLINDER								
32.290	45AS38401-011 2984 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
324160	COPILOT RIGHT MASTER BRAKE CYLINDER								
32.290	45AS38401-012 2945 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 324181	LEFT WHEEL SPEED TRANSDUCER								
32.300 REPLACE	140-03110 2213 REF: See Workcard	MOS HRS/MSC AFL	120 5000	O:7 N:3596.9 O:0 N:3301 O:0			25-MAR-2016 2785.3 2405	25-MAR-2026 M 4188.4 M	
+ 324182	RIGHT WHEEL SPEED TRANSDUCER								
32.300 REPLACE	140-03110 2220 REF: See Workcard	MOS HRS/MSC AFL	120 5000	O:7 N:3596.1 O:0 N:3301 O:0			25-MAR-2016 2785.3 2405	25-MAR-2026 M 4189.2 M	
CHAPTER 33	LIGHTS								
331001	INSTRUMENT LIGHT (PS103) POWER SUPPLY								
33.010	76699-01 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
331002	INSTRUMENT LIGHT (PS104) POWER SUPPLY								
33.010	76699-01 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
331003	INSTRUMENT LIGHT (PS105) POWER SUPPLY								
33.020	76699-01 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331004	INSTRUMENT LIGHT (PS106) POWER SUPPLY								
33.020	76699-01 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
331005	INSTRUMENT LIGHT (PS107) POWER SUPPLY								
33.020	76699-01 SN-UNKNOWN REF: AMM 33-11-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334001	LEFT WING NAVIGATION/ANTI-COLLISION LIGHT								
33.030	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334002	RIGHT WING NAVIGATION/ANTI-COLLISION LIGHT								
33.030	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334003	TAIL ANTI-COLLISION LIGHT								
33.040	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334004	LEFT LANDING LIGHT								
33.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334005	RIGHT LANDING LIGHT								
33.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334006	LEFT TAIL FLOOD LIGHT								
33.060	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334007	RIGHT TAIL FLOOD LIGHT								
33.060	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334008	TAIL NAVIGATION LIGHT								
33.045	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334009	FORWARD RECOGNITION LIGHT								
33.065	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334011	WING ICE INSPECTION LIGHT								
33.070	PN SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334031	ANTI-COLLISION LIGHT POWER SUPPLY								
33.080	01-0790080-00 SN-UNKNOWN REF: AMM 33-40-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334037	LEFT LANDING LIGHT ACTUATOR								
33.090	45AS88830-007 51006 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334038	RIGHT LANDING LIGHT ACTUATOR								
33.090	45AS88830-007 51207 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
334061	TAIL ROTATING BEACON								
33.100	90033-25 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335030	FORWARD EMERGENCY LIGHT POWER SUPPLY								
33.150	87-5106-2 985104 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-MAR-2019 3763.8 3176		
+ 335031	REPLACE FORWARD EMERGENCY LIGHT POWER SUPPLY BATTERY								
33.150	87-5106-2 985104 REF: AMM 33-51-00	MOS HRS/MSC AFL	36				21-MAR-2019 3763.8 3176	21-MAR-2022	
335032	AFT EMERGENCY LIGHT POWER SUPPLY								
33.160	87-5106-2 1214 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			21-MAR-2019 3763.8 3176		
+ 335033	REPLACE AFT EMERGENCY LIGHT POWER SUPPLY BATTERY								
33.160	87-5106-2 1214 REF: AMM 33-51-00	MOS HRS/MSC AFL	36				21-MAR-2019 3763.8 3176	21-MAR-2022	
+ 335034	INSPECT/CHECK EMERGENCY LIGHT POWER SUPPLIES								
33.170		MOS HRS/MSC AFL	12				20-AUG-2020 4028.3 3387	20-AUG-2021	
+ 335038	FUNCTIONAL TEST EMERGENCY LIGHT SYSTEM								
33.170		MOS HRS/MSC AFL	12				20-AUG-2020 4028.3 3387	20-AUG-2021	
335066	NO. 1 LAMP DIMMER								
33.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
335067	NO. 2 LAMP DIMMER								
33.140	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335068	NO. 3 LAMP DIMMER								
33.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
335069	NO. 4 LAMP DIMMER								
33.130	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
335070	NO. 5 LAMP DIMMER								
33.135	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 34 NAVIGATION									
340048	VISUAL INSPECTION AHC-3000A SYSTEM COMPONENTS, WIRE HARNESS								
ICA	REF:	MOS HRS/MSC AFL	12				20-AUG-2020 4028.3 3387	20-AUG-2021	
341001	LEFT PITOT TUBE								
34.010	PH1100-MU-L-1 B3024 REF: AMM 34-12-00	MOS HRS/MSC AFL	O/C				02-JUL-2019 3869.9 3257		
341002	RIGHT PITOT TUBE								
34.010	PN SN-UNKNOWN REF: AMM 34-12-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341013	LEFT LOWER PILOT STATIC PORT								
34.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341014	RIGHT UPPER PILOT STATIC PORT								
34.020	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341015	LEFT UPPER COPILOT STATIC PORT								
34.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341016	RIGHT LOWER COPILOT STATIC PORT								
34.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341017	THIRD SYSTEM STATIC PORT								
34.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 341043	LEAK CHECK PILOT PITOT STATIC SYSTEM (FAR 91.411)								
34.145	REF: AMM 34-12-00	MOS HRS/MSC AFL	24				23-AUG-2018	23-AUG-2020	
+ 341044	LEAK CHECK COPILOT PITOT STATIC SYSTEM (FAR 91.411)								
34.145	REF: AMM 34-12-00	MOS HRS/MSC AFL	24				04-APR-2019	04-APR-2021	
341052	STANDBY MACH/AIRSPEED INDICATOR								
34.080	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
341055	PILOT MACH/AIRSPEED INDICATOR								
34.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341056	COPILOT MACH/AIRSPEED INDICATOR								
34.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341058	COPILOT INSTANTANEOUS VERTICAL SPEED INDICATOR								
34.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341062	(DRI-55) RADIO ALTITUDE INDICATOR								
34.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341063	ANGLE OF ATTACK INDICATOR								
34.110	30AN 681 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341065	CABIN RATE OF CLIMB INDICATOR								
34.120	35060-1164 361490 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341117	STANDBY ALTIMETER								
34.090	6420302-5 G18-11544 REF:	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
+ 341125	TEST STANDBY ALTIMETER FAR 91.411								
34.090	6420302-5 G18-11544 REF: FAR 91.411	MOS HRS/MSC AFL	24				23-AUG-2018	23-AUG-2020	
	MANDATORY								
341127	MACH/AIRSPEED WARNING HORN								
34.150	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341128	ALTITUDE ALERT WARNING HORN								
34.160	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341129	GEAR WARNING HORN								
34.180	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341130	TRIM WARNING HORN								
34.180	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 341139	FUNCTIONAL TEST MACH OVERSPEED WARNING SYSTEM								
34.730	REF: AMM 34-12-00	MOS HRS/MSC AFL	24				23-AUG-2018 3598.2 3045	23-AUG-2020	
341145	NO. 1 AIR DATA COMPUTER								
34.190	822-0389-633 24GDC REF:	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
341146	NO. 2 AIR DATA COMPUTER								
34.200	822-0389-633 3577V REF:	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
341147	LEFT STALL WARNING COMPUTER								
34.210	20BG1 23434 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341148	RIGHT STALL WARNING COMPUTER								
34.210	20BG1 22943 REF: See Workcard	MOS HRS/MSC AFL	O/C				22-NOV-2007 1219.2 1061		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 341169	TEST NO. 1 AIR DATA COMPUTER FAR 91.411								
34.190	822-0389-633	MOS	24				23-AUG-2018	23-AUG-2020	
MANDATORY	24GDC REF: FAR 91.411	HRS/MSC AFL							
+ 341170	TEST NO. 2 AIR DATA COMPUTER FAR 91.411								
34.200	822-0389-633	MOS	24				23-AUG-2018	23-AUG-2020	
MANDATORY	3577V REF: FAR 91.411	HRS/MSC AFL							
341185	NO. 1 NAVIGATION DATA COMPUTER								
34.240	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
341186	NO. 2 NAVIGATION DATA COMPUTER								
34.240	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
341193	(55B) RADIO ALTITUDE TRANSCEIVER								
34.250	822-1939-005	MOS		O:0			03-OCT-2010		
	33P1G	HRS/MSC	O/C	O:0			1888.2		
	REF:	AFL		O:0			1655		
341195	RADIO ALTIMETER CONVERTER								
34.245	622-7209-002	MOS		N:0			23-MAR-2006		
	1CLTN	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		
341199	RADIO ALTITUDE RECEIVER ANTENNA								
34.260	S67-2002-14	MOS		N:0			23-MAR-2006		
	546-7461	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
+ 341200	CHECK AIR DATA SYSTEM FOR RVSM ACCURACY, MEASURE STEP HEIGHT OF THE STATIC PORT.								
34.790		MOS	24				26-AUG-2019	26-AUG-2021	
		HRS/MSC					3871.6		
	REF: AMM 34-10-01	AFL					3259		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341211	LEFT ANGLE OF ATTACK TRANSMITTER								
34.280	0861EB1 1346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341212	RIGHT ANGLE OF ATTACK TRANSMITTER								
34.280	0861EB 0843 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			17-JUL-2007 949.5 827		
341223	LEFT STALL WARNING SHAKER								
34.290	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341224	RIGHT STALL WARNING SHAKER								
34.290	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341235	ANGLE OF ATTACK INDEXER								
34.300	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
341300	RADIO ALTITUDE TRANSMITTER ANTENNA								
34.270	S67-2002-14 546-7204 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342001	STANDBY MAGNETIC COMPASS								
34.310	CB2100T6D RA-00835 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342037	NO. 1 COMPASS FLUX VALVE								
34.350	622-5812-001 33694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342038	NO. 2 COMPASS FLUX VALVE								
34.350	622-5812-001 33699 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342056	THIRD ATTITUDE INDICATOR								
34.370	501-1812-01 1114 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAY-2008 1430.4 1231		
342151	NO. 1 ALTITUDE SENSOR								
34.500	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342152	NO. 1 AIR SPEED SENSOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342153	NO. 2 ALTITUDE SENSOR								
34.500	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342154	NO. 2 AIR SPEED SENSOR								
34.510	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
342180	STANDBY GYRO								
34.520	501-1812-01 1277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-AUG-2009 1856.2 1630		
342403A	INSPECT GPS2/XM DOUBLER INSTALLATION REPAIR								
ICA	REF:	MOS HRS/MSC AFL	9250				21-AUG-2018 3598.2 3045		12295



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342412	NO. 1 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000) 822-1200-209 4D9HYT REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
342413	NO. 2 ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000) 822-1200-209 4D9HYV REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
342415	ATTITUDE/HEADING EXTERNAL COMPENSATION UNIT (ECU-3000) 822-1200-998 4D9K21 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
342421	NO. 1 AHARS MOUNTING RACK 822-1290-003 4F626Y REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0					
342424	NO. 2 AHARS MOUNTING RACK 822-1290-003 4F626X REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0					
343013	VOR/LOC ANTENNA COUPLER DMH21-1 28514 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
343014	GLIDESLOPE COUPLER 101-380043 17387 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
343015	NAVIGATION/MARKER COUPLER 101-380042 31770 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
343025	NO. 1 VOR/LOC ANTENNA								
34.560	S65-247-12 6097 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
343026	NO. 2 VOR/LOC ANTENNA								
34.560	S65-247-12 6096 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
343027	GLIDESLOPE ANTENNA								
34.570	RGS10-48 10304 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
343028	MARKER BEACON ANTENNA								
34.580	DM-N27-3 17769 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-AUG-2012 2296.7 2024		
344001	WEATHER RADAR								
34.590	622-8440-004 22J1J REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345000	NO. 1 ADF RECEIVER								
34.620	622-7382-101 1VW6R REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345001	NO. 2 ADF RECEIVER								
34.620	622-7382-101 1XY3X REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345002	NO. 1 NAVIGATION RECEIVER								
34.630	622-7194-201 2GBYJ REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-OCT-2010 1888.2 1655		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345003	NO. 2 NAVIGATION RECEIVER								
34.630	622-7194-201 1YFLW REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345024	NO. 1 DME TRANSCEIVER								
34.650	622-7309-101 2903 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			07-SEP-2009 1881.5 1650		
345025	NO. 2 DME TRANSCEIVER								
34.650	622-7309-101 1WH3C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345026	NO. 1 TRANSPONDER TRANSCEIVER								
34.660	622-9210-501 4DVL34 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
345027	NO. 2 TRANSPONDER TRANSCEIVER								
34.660	622-9210-501 4DVL36 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
+ 345043	TEST NO. 1 TRANSPONDER TRANSCEIVER FAR 91.413								
34.660 MANDATORY	622-9210-501 4DVL34 REF: FAR 91.413	MOS HRS/MSC AFL	24				23-AUG-2018 3598.2 3045	23-AUG-2020	
+ 345044	TEST NO. 2 TRANSPONDER TRANSCEIVER FAR 91.413								
34.660 MANDATORY	622-9210-501 4DVL36 REF: FAR 91.413	MOS HRS/MSC AFL	24				23-AUG-2018 3598.2 3045	23-AUG-2020	
345085	ADF ANTENNA								
34.710	622-7384-001 2LGXR REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			06-NOV-2007 1178.9 1025		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345086	NO. 1 DME ANTENNA								
34.720	DMNI50-2-2 104123 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345087	NO. 1 TRANSPONDER ANTENNA								
34.700	DMNI50-2-2 102627 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345088	NO. 2 TRANSPONDER ANTENNA								
34.700	DMNI50-2-2 104132 REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345090	NO. 2 DME ANTENNA								
34.720	DMNI50-2-2 104115 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345098	VLF (LOOP) ANTENNA								
34.640	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345610	NO. 1 FLIGHT CONTROL COMPUTER								
34.230	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345615	NO. 2 FLIGHT CONTROL COMPUTER								
34.230	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345620	AUTO TRIM COUPLER								
34.390	622-9817-001 26GMY REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			14-SEP-2011 2033.3 1787		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345635	NO. 1A IAPS/IO CONCENTRATOR								
34.450	822-1362-512 4F1L1F REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345640	NO. 1B IAPS/IO CONCENTRATOR								
34.450	822-1362-512 4F1L1H REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345645	NO. 2A IAPS/IO CONCENTRATOR								
34.450	822-1362-512 4F1L1L REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345650	NO. 2B IAPS/IO CONCENTRATOR								
34.460	822-1362-512 4F1L1T REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345655	NO. 1A IAPS/IO POWER SUPPLY								
34.225	622-9945-022 23X2P REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345660	NO. 1B IAPS/IO POWER SUPPLY								
34.225	622-9945-022 48VJ REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345665	NO. 2A IAPS/IO POWER SUPPLY								
34.170	622-9945-022 23X2T REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345670	NO. 2B IAPS/IO POWER SUPPLY								
34.170	622-9945-022 23X2R REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345675	NO. 1 ATTITUDE HEADING COMPUTER								
34.600	822-1378-001 4FLGNL REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345680	NO. 2 ATTITUDE HEADING COMPUTER								
34.600	822-1378-001 4DKT0K REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345685	NO. 1 UNIT (ICU-85) COMPENSATOR								
34.680	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345690	NO. 2 UNIT (ICU-85) COMPENSATOR								
34.680	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345695	NO. 1 AIR DATA MODULE								
34.690	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345700	NO. 2 AIR DATA MODULE								
34.690	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345705	DATA ACQUISITION UNIT								
34.670	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345710	PILOT SENSOR UNIT DISPLAY								
34.610	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345715	COPILOT SENSOR UNIT DISPLAY								
34.610	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345720	SENSOR DISPLAY DRIVER UNIT								
34.530	PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
345725	PILOT MODE SELECT PANEL								
34.490	622-8330-003 23XBY REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JUL-2006 200.3 172		
345730	COPILOT MODE SELECT PANEL								
34.490	622-8330-003 23X9G REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345735	PILOT CONTROL DISPLAY UNIT								
34.480	822-1485-066 4FKD24 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345740	COPILOT CONTROL DISPLAY UNIT								
34.480	822-1485-066 4FKD26 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345745	COURSE HEADING PANEL								
34.470	822-1280-003 4DL87C REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
345750	SIGNAL INTERFACE ADAPTER								
34.440	622-9732-002 23TPT REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345755	CONTROL DISPLAY COUPLER								
34.430	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
345760	DATA BASE UNIT								
34.420	822-3000-202 4CV39L REF: AMM 34-59-00	MOS HRS/MSC AFL	O/C				23-AUG-2018 3598.2 3045		
346001	RECEIVER COMPUTER UNIT								
34.340	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
346005	IAPS/CARD CAGE								
34.410	822-1029-101 2064T REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
346006	SYNTHETIC VISION SYSTEM (SVS) COMPUTER								
	866-0232-010 480PT3 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346007	SYNTHETIC VISION SYSTEM (SVS) CONFIGURATION MODULE								
	822-3095-102 77B4D REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346008	SYNTHETIC VISUAL SYSTEM (SVS) VIDEO INTERFACE UNIT								
	866-0232-060 480PRV REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346020	PILOT PRIMARY FLIGHT DISPLAY								
34.380	822-1753-450 4DL8T5 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346025	PILOT MULTIFUNCTION DISPLAY								
34.380	822-1753-450 4DL8V3 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346030	COPILOT MULTIFUNCTION DISPLAY								
34.380	822-1753-450 4DL9FT REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346035	COPILOT PRIMARY FLIGHT DISPLAY								
34.360	822-1753-450 4DL9FV REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
346045	PILOT AIR DATA REFERENCE PANEL								
34.330	PN CAE330011 REF:	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
346050	COPILOT AIR DATA REFERENCE PANEL								
34.330	PN CAE330011 REF:	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
346055	PILOT ALTITUDE AWARENESS PANEL								
34.320	PN CAE330011 REF:	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
346060	COPILOT ALTITUDE AWARENESS PANEL								
34.320	PN CAE330011 REF:	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
346063	NO. 1 WAAS GPS ANTENNA								
34.740	CI-429-200 574887 REF: AMM 34-58-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346064	NO. 2 WAAS GPS ANTENNA CI-429-410 574876 REF: AMM 34-58-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-AUG-2018 3598.2 3045	
346065	NO. 1 GPS RECEIVER 822-2189-100 4FLGML REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				21-AUG-2018 3598.2 3045	
346066	NO. 2 GPS RECEIVER PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C					21-AUG-2018 3598.2 3045	
346070	TCAS TRANSCEIVER 822-1294-002 151411 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAR-2006 0 0	
346075	UPPER TCAS DIRECTIONAL ANTENNA 622-8973-001 1R59R REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAR-2006 0 0	
346080	LOWER TCAS DIRECTIONAL ANTENNA S65-5366-7L 261-69609 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAR-2006 0 0	
346085	TAWS COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-MAR-2006 0 0	
346087	EGPWS COMPUTER 965-0976-040-208-208 EMK5-26910 REF: AMM 34-46-00	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0				24-OCT-2012 2300.3 2026	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346090	AFIS DATA MANAGEMENT UNIT								
34.850	PN SN-UNKNOWN REF: AMM 34-59-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 35 OXYGEN									
+ 351001	OXYGEN CYLINDER								
35.010	101-384207-13 19766 REF: AMM 35-11-00 Manufacture Date: 14-JUN-2007	MOS HRS/MSC AFL	180				14-JUN-2007	30-JUN-2022	M
+ 351007	HYDROSTATIC TEST OXYGEN CYLINDER								
35.010	101-384207-13 19766 REF: AMM 35-11-00 HydroCheck Date: 28-SEP-2016	MOS HRS/MSC AFL	60	I:0 I:0			28-SEP-2016	28-SEP-2021	
+ 351013	OXYGEN CYLINDER REGULATOR								
35.010	172400-14 4783 REF: AMM 35-11-00	MOS HRS/MSC AFL	72	O:0 O:0			01-SEP-2017 3378.8 2886	30-SEP-2023	M
351025	OXYGEN PRESSURE INDICATOR								
35.030	99-384042-3 2988 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 351029	PILOT OXYGEN MASK								
35.020	174262-12 19304 REF: AMM 35-10-00	MOS HRS/MSC AFL	72	O:1 O:0 O:0			23-JAN-2018 3473.1 2951	23-DEC-2023	
+ 351030	COPILOT OXYGEN MASK								
35.020	174262-12 03465 REF: AMM 35-10-00	MOS HRS/MSC AFL	72	O:1 O:0 O:0			23-JAN-2018 3473.1 2951	23-DEC-2023	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351031	PILOT OXYGEN MASK REGULATOR								
35.040	128-380067-15 17360 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-JAN-2007 578.8 503		
351032	COPILLOT OXYGEN MASK REGULATOR								
35.040	128-380067-15 18078 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 352001	NO. 1 PASSENGER OXYGEN MASK								
35.050	174095-58 N/A REF: AMM 35-21-00	MOS HRS/MSC AFL	96				10-SEP-2020 4030.73 3391	17-JUN-2028	
Manufacture Date: 17-JUN-2020									
+ 352002	NO. 2 PASSENGER OXYGEN MASK								
35.050	174095-58 SN-UNKNOWN REF: AMM 35-21-00	MOS HRS/MSC AFL	96	O:0 O:0 O:0			10-SEP-2020 4030.73 3391	17-JUN-2028	
Manufacture Date: 17-JUN-2020									
+ 352003	NO. 3 PASSENGER OXYGEN MASK								
35.060	174095-58 SN-UNKNOWN REF: AMM 35-21-00	MOS HRS/MSC AFL	96	O:0 O:0 O:0			10-SEP-2020 4030.73 3391	17-JUN-2028	
Manufacture Date: 17-JUN-2020									
+ 352004	NO. 4 PASSENGER OXYGEN MASK								
35.060	174095-58 SN-UNKNOWN REF: AMM 35-21-00	MOS HRS/MSC AFL	96				10-SEP-2020 4030.73 3391	17-JUN-2028	
Manufacture Date: 17-JUN-2020									
+ 352005	NO. 5 PASSENGER OXYGEN MASK								
35.070	174095-58 SN-UNKNOWN REF: AMM 35-21-00	MOS HRS/MSC AFL	96	O:0 O:0 O:0			10-SEP-2020 4030.73 3391	17-JUN-2028	
Manufacture Date: 17-JUN-2020									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 352006	NO. 6 PASSENGER OXYGEN MASK								
	174095-58	MOS	96	O:0			10-SEP-2020	17-JUN-2028	
35.070	SN-UNKNOWN	HRS/MSC		O:0			4030.73		
	REF: AMM 35-21-00	AFL		O:0			3391		
	Manufacture Date: 17-JUN-2020								
+ 352007	NO. 7 PASSENGER OXYGEN MASK								
	174095-58	MOS	96	O:0			10-SEP-2020	17-JUN-2028	
35.080	SN-UNKNOWN	HRS/MSC		O:0			4030.73		
	REF: AMM 35-21-00	AFL		O:0			3391		
	Manufacture Date: 17-JUN-2020								
+ 352008	NO. 8 PASSENGER OXYGEN MASK								
	174095-58	MOS	96	O:0			10-SEP-2020	17-JUN-2028	
35.080	SN-UNKNOWN	HRS/MSC		O:0			4030.73		
	REF: AMM 35-21-00	AFL		O:0			3391		
	Manufacture Date: 17-JUN-2020								
+ 352065	REPLACE PASSENGER OXYGEN CONTROL VALVE O-RINGS								
		MOS	48				30-OCT-2018	30-OCT-2022	
35.110		HRS/MSC					3654		
	REF: AMM 35-21-00	AFL					3091		
352070	PASSENGER OXYGEN CONTROL VALVE								
	101-384032-7	MOS		N:0			23-MAR-2006		
35.120	3802B	HRS/MSC	O/C	N:0			0		
	REF: AMM 35-21-00	AFL		N:0			0		
CHAPTER 36	PNEUMATIC								
360011	LEFT ENGINE FULL FLOW PRESSURE REGULATING SHUT-OFF VALVE								
	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		
360012	RIGHT ENGINE FULL FLOW PRESSURE REGULATING SHUT-OFF VALVE								
	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361001	NO. 1 BLEED AIR CHECK VALVE								
36.010	PN SN-UNKNOWN REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361002	NO. 2 BLEED AIR CHECK VALVE								
36.010	PN SN-UNKNOWN REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361003	FLOW INCREASING VALVE								
36.020	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361013	BLEED AIR PRESSURE REGULATOR								
36.030	38E85-7B 52742 REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361019	SUCTION PRESSURE EJECTOR								
36.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361025	DOOR SEAL VALVE								
36.050	PN SN-UNKNOWN REF: AMM 36-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
361030	LEFT HAND BLEED AIR ACTUATOR VALVE								
36.060	3034144 F63169 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 361031	INSPECT LEFT HAND BLEED AIR SUPPLY TUBE								
36.070		MOS HRS/MSC AFL	400	+20			26-AUG-2019 3871.6 3259	4271.6	4291.6
AIRWORTHINESS	REF: ALM 04-00-02								

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 361032	INSPECT RIGHT HAND BLEED AIR SUPPLY TUBE								
36.070		MOS					26-AUG-2019		
AIRWORTHINESS	REF: ALM 04-00-02	HRS/MSC AFL	400	+20			3871.6 3259	4271.6	4291.6
361035	RIGHT HAND BLEED AIR ACTUATOR VALVE								
36.060	3034144	MOS		N:0			23-MAR-2006		
	F63359	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
361037 (s)	LEFT BLEED AIR SUPPLY PRESSURE SHUT-OFF (PRSOV) VALVE								
	1896-00-03	MOS		O:0			10-SEP-2020		
	1501	HRS/MSC	O/C	O:0			4030.73		
	REF:	AFL		O:0			3391		
361038 (s)	RIGHT BLEED AIR SUPPLY PRESSURE SHUT-OFF (PRSOV) VALVE								
	1896-00-3	MOS		O:0			10-SEP-2020		
	0307A	HRS/MSC	O/C	O:0			4030.73		
	REF:	AFL		O:0			3391		
CHAPTER 39	ELECTRICAL PANELS, PARTS AND INSTRUMENTS								
391017	MASTER CAUTION PANEL								
	LT-4001-05	MOS		N:0			21-AUG-2018		
	011	HRS/MSC	O/C	N:0			3598.2		
	REF:	AFL		N:0			3045		
396010	LEFT STARTER (A184) RELAY PCB								
39.010	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
396011	RIGHT STARTER (A188) RELAY PCB								
39.010	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 52	DOORS								



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521001	ENTRANCE DOOR ASSEMBLY								
52.010	45A30103-631 RK-465 REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
522001	EMERGENCY EXIT DOOR								
52.030	45A30203-001 RK-465 REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 522027	REPLACE EMERGENCY EXIT DOOR HANDLE (PULL)(SELF-ILLUMINATING) PLACARD								
52.020		MOS HRS/MSC AFL	60	I:0 I:0			08-JAN-2016	08-JAN-2021	
LIFE LIMIT	REF: GENERIC NO REF Manufacture Date: 08-JAN-2016								
+ 522028	REPLACE EMERGENCY EXIT DOOR HANDLE COVER (PULL)(SELF-ILLUMINATING) PLACARD								
52.020		MOS HRS/MSC AFL	60	I:0 I:0			08-JAN-2016	08-JAN-2021	
LIFE LIMIT	REF: GENERIC NO REF Manufacture Date: 08-JAN-2016								
CHAPTER 53	FUSELAGE								
+ 531079	NO. 1 ENGINE FORWARD CARRY-THRU BRACKET								
53.020	45A34361-007 11110501ICT	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT	REF: GENERIC NO REF								
+ 531080	NO. 1 ENGINE AFT CARRY-THRU BRACKET								
53.030	45A34361-010 11110501ICT	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT	REF: GENERIC NO REF								
+ 531081	NO. 2 ENGINE FORWARD CARRY-THRU BRACKET								
53.020	45A34361-008 01070601ICT	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT	REF: GENERIC NO REF								



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 531082	NO. 2 ENGINE AFT CARRY-THRU BRACKET 45A34361-011 11110501ICT REF: GENERIC NO REF	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
53.030 LIFE LIMIT									
+ 531083	INSPECT NO. 1 ENGINE CARRY-THROUGH BRACKET REF: ALM 04-00-02	MOS HRS/MSC AFL	200	+20			26-AUG-2019 3871.6 3259	4071.6	4091.6
53.030 AIRWORTHINESS									
+ 531085	REPLACE NO. 1 ENGINE CARRY-THROUGH BRACKET BOLTS REF: AMM 20-10-05	MOS HRS/MSC AFL	5000	I:0 I:0			23-MAR-2006 0 0	5000	
53.050 MANDATORY									
+ 531090	REPLACE NO. 2 ENGINE CARRY-THROUGH BRACKET BOLTS REF: AMM 20-10-05	MOS HRS/MSC AFL	5000	I:0 I:0			23-MAR-2006 0 0	5000	
53.050 MANDATORY									
+ 532052	DETAIL INSPECT LEFT MAIN LANDING GEAR FITTING ASSEMBLY REF: AMM 53-40-00	MOS HRS/MSC AFL	7000	+15			23-MAR-2006 0	7000	7015
53.170 MANDATORY									
+ 532054	DETAIL INSPECT RIGHT MAIN LANDING GEAR FITTING ASSEMBLY REF: AMM 53-40-00	MOS HRS/MSC AFL	7000	+15			23-MAR-2006 0	7000	7015
53.170 MANDATORY									
+ 532056	DETAIL INSPECT LEFT MID FUSELAGE MAIN LANDING GEAR UPLOCK FITTING REF: AMM 53-40-00	MOS HRS/MSC AFL	7000	+15			23-MAR-2006 0	7000	7015
53.180 MANDATORY									
+ 532058	DETAIL INSPECT RIGHT MID FUSELAGE MAIN LANDING GEAR UPLOCK FITTING REF: AMM 53-40-00	MOS HRS/MSC AFL	7000	+15			23-MAR-2006 0	7000	7015
53.180 MANDATORY									



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
535001	RADOME								
53.010	PN SN-UNKNOWN REF: AMM 53-50-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 55 STABILIZERS									
+ 551003	PERFORM RADIOGRAPHIC (X-RAY) INSPECTION OF THE HORIZONTAL STABILIZER RIB ASSEMBLIES								
27.470		MOS HRS/MSC AFL	2400	+20			24-OCT-2012 2300.3 2020	4700.3	4720.3
AIRWORTHINESS	REF: AMM 55-10-00								
CHAPTER 56 WINDOWS									
561001	PILOT WINDSHIELD								
56.010	45AS31001-023 14024H2834 REF: AMM 56-10-00	MOS HRS/MSC AFL	O/C	N:6 N:0 N:0			03-NOV-2014 2501.6 2171		
561002	COPILOT WINDSHIELD								
56.010	45AS31001-024 17003H4998 REF: AMM 56-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-JAN-2018 3473.1 2951		
+ 561013	PILOT SIDE WINDOW								
56.020	45AS31010-021 1265 REF: AMM 56-10-00	MOS HRS/MSC AFL	20000				23-MAR-2006 0 0	20000	
LIFE LIMIT									
+ 561014	COPILOT SIDE WINDOW								
56.020	45AS31010-022 1314 REF: AMM 56-10-00	MOS HRS/MSC AFL	20000				23-MAR-2006 0 0	20000	
LIFE LIMIT									
+ 562001	CABIN LEFT FORWARD WINDOW INNER PANEL								
56.030	45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000				23-MAR-2006 0 0	20000	
LIFE LIMIT									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 562002	CABIN LEFT 2ND WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.040									
LIFE LIMIT									
+ 562003	CABIN LEFT 3RD WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.050									
LIFE LIMIT									
+ 562004	CABIN LEFT 4TH WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.060									
LIFE LIMIT									
+ 562005	CABIN LEFT 5TH WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.070									
LIFE LIMIT									
+ 562006	CABIN LEFT 6TH WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.080									
LIFE LIMIT									
+ 562007	CABIN RIGHT FORWARD WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.030									
LIFE LIMIT									
+ 562008	CABIN RIGHT 2ND WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.040									
LIFE LIMIT									
+ 562009	CABIN RIGHT 3RD WINDOW INNER PANEL 45AS31003-3 SN-UNKNOWN REF: AMM 56-20-00	MOS HRS/MSC AFL	20000	N:0 N:0 N:0			23-MAR-2006 0 0		20000
56.050									
LIFE LIMIT									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 562010	CABIN RIGHT 4TH WINDOW INNER PANEL								
	45AS31003-3	MOS		N:0			23-MAR-2006		
56.060	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562011	CABIN RIGHT 5TH WINDOW INNER PANEL								
	45AS31003-3	MOS		N:0			23-MAR-2006		
56.070	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562012	CABIN RIGHT 6TH WINDOW INNER PANEL								
	45AS31003-3	MOS		N:0			23-MAR-2006		
56.080	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562013	CABIN LEFT FORWARD WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.090	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562014	CABIN LEFT 2ND WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.100	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562015	CABIN LEFT 3RD WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.110	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562016	CABIN LEFT 4TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.120	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562017	CABIN LEFT 5TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.130	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 562018	CABIN LEFT 6TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.140	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562019	CABIN RIGHT FORWARD WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.090	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562020	CABIN RIGHT 2ND WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.100	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562021	CABIN RIGHT 3RD WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.110	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562022	CABIN RIGHT 4TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.120	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562023	CABIN RIGHT 5TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.130	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		
+ 562024	CABIN RIGHT 6TH WINDOW OUTER PANEL								
	45AS31003-1	MOS		N:0			23-MAR-2006		
56.140	SN-UNKNOWN	HRS/MSC	20000	N:0			0		20000
LIFE LIMIT	REF: AMM 56-20-00	AFL		N:0			0		

CHAPTER 57 WINGS



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 571061	INSPECT LEFT WING WING-TO-FUSELAGE ATTACH BOLTS - DETAIL INSPECT FOR CORROSION, WEAR, AND DAMAGE. MAGNETIC PARTICLE INSPECT FOR CRACKS.								
57.020	REF: AMM 57-40-00	MOS HRS/MSC AFL	120				24-MAR-2016 2785.3 2405	24-MAR-2026	
+ 571067	INSPECT RIGHT WING WING-TO-FUSELAGE ATTACH BOLTS - DETAIL INSPECT FOR CORROSION, WEAR, AND DAMAGE. MAGNETIC PARTICLE INSPECT FOR CRACKS.								
57.020	REF: AMM 57-40-00	MOS HRS/MSC AFL	120				24-MAR-2016 2785.3 2405	24-MAR-2026	
576010	LEFT ROLL TRIM ASSEMBLY								
57.060	45A10720-001 RK-462 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
576020	RIGHT ROLL TRIM ASSEMBLY								
57.060	45A10720-002 RK-465 REF: AMM 27-10-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 71 POWER PLANT									
710021	NO. 1 ENGINE INTAKE DUCT ASSEMBLY								
71.080	45A35022-601 07-299 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				19-MAY-2011 1888.2 1655		
710022	NO. 2 ENGINE INTAKE DUCT ASSEMBLY								
71.080	45A30024-604 RK-465 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 712007	NO. 1 ENGINE FORWARD UPPER MOUNT								
71.040	45AS42002-009 LK1929 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
LIFE LIMIT									



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 712008	NO. 2 ENGINE FORWARD UPPER MOUNT 45AS42002-009 LK1985 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
71.040 LIFE LIMIT									
+ 712009	NO. 1 ENGINE FORWARD LOWER MOUNT 45AS42002-009 LK1931 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
71.050 LIFE LIMIT									
+ 712010	NO. 2 ENGINE FORWARD LOWER MOUNT 45AS42002-009 LK1968 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
71.050 LIFE LIMIT									
+ 712011	NO. 1 ENGINE AFT MOUNT 45AS42002-011 LK0906 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
71.060 LIFE LIMIT									
+ 712012	NO. 2 ENGINE AFT MOUNT 45AS42002-011 LK0892 REF: AMM 71-20-00	MOS HRS/MSC AFL	22400	N:0 N:0 N:0			23-MAR-2006 0 0	22400	
71.060 LIFE LIMIT									
+ 712014	INSPECT NO. 1 ENGINE ISOLATOR MOUNTS MOS HRS/MSC AFL REF: GENERIC NO REF	1800 +20					23-AUG-2018 3598.2 3045	5398.2	5418.2
71.070 MANDATORY									
+ 712016	INSPECT NO. 2 ENGINE ISOLATOR MOUNTS MOS HRS/MSC AFL REF: GENERIC NO REF	1800 +20					23-AUG-2018 3598.2 3045	5398.2	5418.2
71.070 MANDATORY									
+ 712031	REPLACE NO. 1 ENGINE FORWARD UPPER MOUNT ISOLATOR 45AS42002-009 LK1929 REF: AMM 71-20-00	MOS HRS/MSC AFL	7000	I:0 I:0			23-MAR-2006 0 0	7000	
71.040 REPLACE									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 712032	REPLACE NO. 2 ENGINE FORWARD UPPER MOUNT ISOLATOR								
71.040	45AS42002-009	MOS		I:0			23-MAR-2006		
REPLACE	LK1985	HRS/MSC	7000				0		7000
	REF: AMM 71-20-00	AFL		I:0			0		
+ 712033	REPLACE NO. 1 ENGINE FORWARD LOWER MOUNT ISOLATOR								
71.050	45AS42002-009	MOS		I:0			23-MAR-2006		
REPLACE	LK1931	HRS/MSC	7000				0		7000
	REF: AMM 71-20-00	AFL		I:0			0		
+ 712034	REPLACE NO. 2 ENGINE FORWARD LOWER MOUNT ISOLATOR								
71.050	45AS42002-009	MOS		I:0			23-MAR-2006		
REPLACE	LK1968	HRS/MSC	7000				0		7000
	REF: AMM 71-20-00	AFL		I:0			0		
+ 712035	REPLACE NO. 1 ENGINE AFT MOUNT ISOLATOR								
71.060	45AS42002-011	MOS		I:0			23-MAR-2006		
REPLACE	LK0906	HRS/MSC	7000				0		7000
	REF: AMM 71-20-00	AFL		I:0			0		
+ 712036	REPLACE NO. 2 ENGINE AFT MOUNT ISOLATOR								
71.060	45AS42002-011	MOS		I:0			23-MAR-2006		
REPLACE	LK0892	HRS/MSC	7000				0		7000
	REF: AMM 71-20-00	AFL		I:0			0		
71EN1	NO. 1 ENGINE								
71.EN1	3030100	MOS					23-MAR-2006		
	PCE-JA0722	HRS/MSC	E/C	O:3404.8			0		
	REF: AMM 71-00-00	AFL		O:2902			0		
71EN2	NO. 2 ENGINE								
71.EN2	3030100	MOS					23-MAR-2006		
	PCE-JA0723	HRS/MSC	E/C	O:3404.8			0		
	REF: AMM 71-00-00	AFL		O:2902			0		

ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710010	NO. 1 ENGINE - OVERHAUL	MOS		I:0			23-MAR-2006		
		HRS/MSC	5400	+50/-50			0	(5400) 5400	5450
	REF: GENERIC NO REF	ENC		I:0			0		
+ 710020	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					09-AUG-2018		
		HRS/MSC	1800	+300/-300			3598.2	(5398.2) 5398.2	5698.2
	REF: EMM 72-00-00	ENC					3045		

ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100

+ 710010	NO. 2 ENGINE - OVERHAUL	MOS		I:0			23-MAR-2006		
		HRS/MSC	5400	+50/-50			0	(5400) 5400	5450
	REF: GENERIC NO REF	ENC		I:0			0		
+ 710020	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					09-AUG-2018		
		HRS/MSC	1800	+300/-300			3598.2	(5398.2) 5398.2	5698.2
	REF: EMM 72-00-00	ENC					3045		

CHAPTER 72 ENGINE
ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100

+ 720010	NO. 1 ENGINE - INSPECT FUEL PUMP POPUP INDICATOR BUTTON IF EXTENDED	MOS					26-AUG-2019		
		HRS/MSC	200	+10%			3871.6	(4071.6) 4071.6	4091.6
	REF: GENERIC NO REF	ENC					3259		
+ 720100	NO. 1 ENGINE - ENGINE OVERTEMPERATURE	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720110	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720120	NO. 1 ENGINE - LOSS OF OIL								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720130	NO. 1 ENGINE - ENGINE OVERSPEED								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720140	NO. 1 ENGINE - ENGINE WINDMILLING								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720150	NO. 1 ENGINE - ENGINE IMMERSION IN WATER								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720160	NO. 1 ENGINE - ENGINE DROPPED DURING HANDLING								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720170	NO. 1 ENGINE - LIGHTNING STRIKE								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720180	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720190	NO. 1 ENGINE - HEAVY/HARD LANDING								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720200	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720210	NO. 1 ENGINE - STARTER GENERATOR FAIL INDICATION								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720220	NO. 1 ENGINE - HYDRAULIC PUMP FAILURE								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 723010	NO. 1 ENGINE - CENTRIFUGAL IMPELLER								
	3040939	MOS		N:0			23-MAR-2006		
	A001W9F9	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000) 12000	
+ 723020	NO. 1 ENGINE - LOW BOOST COMPRESSOR HUB								
	3038312	MOS		N:0			23-MAR-2006		
	A001TDYE	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000) 14000	
+ 723030	NO. 1 ENGINE - LOW COMPRESSOR HUB								
	3037911	MOS		N:0			23-MAR-2006		
	A001TCYW	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000) 12000	
723040	NO. 1 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY								
	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
+ 725010	NO. 1 ENGINE - HIGH TURBINE ROTOR DISK								
	3036411	MOS		N:0			23-MAR-2006		
	A001WK45	HRS/MSC		N:0			0		
LIFE LIMIT	REF: EMM 72-50-02	ENC	14000	N:0			0	(14000) 14000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725020	NO. 1 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK 3022212 A001PXT1	MOS HRS/MSC		N:0 N:0			23-MAR-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000) 14000	
+ 725030	NO. 1 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3041593 A001WCF8	MOS HRS/MSC		N:0 N:0			23-MAR-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000) 14000	
+ 725080	NO. 1 ENGINE - VISUAL INSPECT LOW PRESSURE COMPRESSOR BYPASS STATOR INNER AND OUTER RINGS FOR CRACKS	MOS HRS/MSC	1800	+300/-300			09-AUG-2018 3598.2	(5398.2) 5398.2	5698.2
	REF: GENERIC NO REF	ENC					3045		
ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100									
+ 720010	NO. 2 ENGINE - INSPECT FUEL PUMP POPUP INDICATOR BUTTON IF EXTENDED	MOS HRS/MSC	200	+10%			26-AUG-2019 3871.6	(4071.6) 4071.6	4091.6
	REF: GENERIC NO REF	ENC					3259		
+ 720100	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS HRS/MSC	A/R	I:0 I:0			23-MAR-2006 0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720110	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS HRS/MSC	A/R	I:0 I:0			23-MAR-2006 0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720120	NO. 2 ENGINE - LOSS OF OIL	MOS HRS/MSC	A/R	I:0 I:0			23-MAR-2006 0		
	REF: EMM 72-00-00	ENC		I:0			0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720130	NO. 2 ENGINE - ENGINE OVERSPEED	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720140	NO. 2 ENGINE - ENGINE WINDMILLING	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720150	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720160	NO. 2 ENGINE - ENGINE DROPPED DURING HANDLING	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720170	NO. 2 ENGINE - LIGHTNING STRIKE	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720180	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720190	NO. 2 ENGINE - HEAVY/HARD LANDING	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720200	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 720210	NO. 2 ENGINE - STARTER GENERATOR FAIL INDICATION								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 720220	NO. 2 ENGINE - HYDRAULIC PUMP FAILURE								
		MOS		I:0			23-MAR-2006		
		HRS/MSC	A/R	I:0			0		
	REF: EMM 72-00-00	ENC		I:0			0		
+ 723010	NO. 2 ENGINE - CENTRIFUGAL IMPELLER								
	3040939	MOS		N:0			23-MAR-2006		
	A001TWA0	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000)	12000
+ 723020	NO. 2 ENGINE - LOW BOOST COMPRESSOR HUB								
	3038312	MOS		N:0			23-MAR-2006		
	A001TDXY	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000)	14000
+ 723030	NO. 2 ENGINE - LOW COMPRESSOR HUB								
	3037911	MOS		N:0			23-MAR-2006		
	A001TL57	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	12000	N:0			0	(12000)	12000
723040	NO. 2 ENGINE - LP COMPRESSOR ROTOR BALANCE ASSEMBLY								
	PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
+ 725010	NO. 2 ENGINE - HIGH TURBINE ROTOR DISK								
	3036411	MOS		N:0			23-MAR-2006		
	A001WK46	HRS/MSC		N:0			0		
LIFE LIMIT	REF: EMM 72-50-02	ENC	14000	N:0			0	(14000)	14000
+ 725020	NO. 2 ENGINE - 2ND-STAGE LOW TURBINE ROTOR DISK								
	3022212	MOS		N:0			23-MAR-2006		
	A001W9FK	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000)	14000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 725030	NO. 2 ENGINE - 3RD-STAGE LOW TURBINE ROTOR DISK 3041593 A001WCF6	MOS HRS/MSC		N:0 N:0			23-MAR-2006 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	14000	N:0			0	(14000) 14000	
+ 725080	NO. 2 ENGINE - VISUAL INSPECT LOW PRESSURE COMPRESSOR BYPASS STATOR INNER AND OUTER RINGS FOR CRACKS	MOS HRS/MSC	1800	+300/-300			09-AUG-2018 3598.2	(5398.2) 5398.2	5698.2
	REF: GENERIC NO REF	ENC					3045		
CHAPTER 73 ENGINE FUEL AND CONTROL									
733001	NO. 1 ENGINE FUEL FLOW INDICATOR PN	MOS					21-AUG-2018		
73.070	CAE330011 REF: AMM 73-30-00	HRS/MSC AFL	O/C				3598.2 3045		
733002	NO. 2 ENGINE FUEL FLOW INDICATOR PN	MOS					21-AUG-2018		
73.070	CAE330011 REF: AMM 73-30-00	HRS/MSC AFL	O/C				3598.2 3045		
733003	FUEL TOTALIZER INDICATOR PN	MOS					21-AUG-2018		
73.080	CAE330011 REF: AMM 73-30-00	HRS/MSC AFL	O/C				3598.2 3045		
733031	FUEL QUANTITY CONDITIONER 10852B01Y00	MOS		R:0			21-AUG-2018		
73.050	0138 REF: AMM 73-30-00	HRS/MSC AFL	O/C	R:0 R:0			3598.2 3045		
ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100									
731000	NO. 1 ENGINE - FUEL OVERTEMP INDICATOR PN	MOS		N:0			23-MAR-2006		
	SN-UNKNOWN REF: GENERIC NO REF	HRS/MSC ENC	O/C	N:0 N:0			0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731001	NO. 1 ENGINE - VISUAL INSPECT FUEL OVERTEMP INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
+ 731002	NO. 1 ENGINE - CHANGE FUEL PUMP OUTLET FILTER (10 MICRON) REF: EMM 73-10-02	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
731010	NO. 1 ENGINE - FUEL PUMP 3071192-01 002392SB3 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			21-MAY-2007 770.3 663		
+ 731013	NO. 1 ENGINE - REPLACE FUEL FILTER REF: EMM 73-10-13	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
731020	NO. 1 ENGINE - FUEL-OIL COOLER 3117056-01 M156037 REF: EMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 731025	NO. 1 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER 3117056-01 M156037 REF: EMM 73-10-01	MOS HRS/MSC ENC	5400	+50/-50		-3598. 2	23-AUG-2018 3598.2 3045	(5400) 5400	5450
731030	NO. 1 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 731035	NO. 1 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC BLANK	MOS HRS/MSC ENC	5400	+50/-50	I:0 I:0		23-MAR-2006 0 0	(5400) 5400	5450

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731040	NO. 1 ENGINE - FLOW DIVIDER VALVE 25950-2 0098 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C				03-OCT-2010 1888.2 1655		
+ 731060	NO. 1 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC BLANK	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
731065	NO. 1 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: EMM 73-10-12	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
731085	NO. 1 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 731090	NO. 1 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 25950-2 0098 REF: GENERIC NO REF	MOS HRS/MSC ENC	5400	+50/-50		-3598. 2	23-AUG-2018 3598.2 3045	(5400) 5400	5450
732020	NO. 1 ENGINE - ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
732030	NO. 1 ENGINE - HYDROMECHANICAL METERING UNIT 790155-10 F63550 REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-OCT-2010 1888.2 1655		
+ 732040	NO. 1 ENGINE - VISUALLY INSPECT ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: EMM 73-20-04	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732045	NO. 1 ENGINE - ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 732050	NO. 1 ENGINE - VISUALLY INSPECT ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6)	4071.6
+ 732060	NO. 1 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6)	4071.6
732065	NO. 1 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
733010	NO. 1 ENGINE - FUEL FLOW TRANSMITTER 5/8-1-81-303 518756 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100

731000	NO. 2 ENGINE - FUEL OVERTEMP INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 731001	NO. 2 ENGINE - VISUAL INSPECT FUEL OVERTEMP INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6)	4071.6



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731002	NO. 2 ENGINE - CHANGE FUEL PUMP OUTLET FILTER (10 MICRON) REF: EMM 73-10-02	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
731010	NO. 2 ENGINE - FUEL PUMP 3071192-01 002417 SB3 REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C		R:0 R:0 R:0		21-MAY-2007 770.3 663		
+ 731013	NO. 2 ENGINE - REPLACE FUEL FILTER REF: EMM 73-10-13	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
731020	NO. 2 ENGINE - FUEL-OIL COOLER 3117056-01 M153718 REF: EMM 73-10-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-MAR-2006 0 0		
+ 731025	NO. 2 ENGINE - VISUALLY INSPECT FUEL-OIL COOLER 3117056-01 M153718 REF: EMM 73-10-01	MOS HRS/MSC ENC	5400	+50/-50		-3598. 2	23-AUG-2018 3598.2 3045	(5400) 5400	5450
731030	NO. 2 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-MAR-2006 0 0		
+ 731035	NO. 2 ENGINE - VISUALLY INSPECT MOTIVE FLOW VALVE PN SN-UNKNOWN REF: GENERIC BLANK	MOS HRS/MSC ENC	5400	+50/-50	I:0 I:0		23-MAR-2006 0 0	(5400) 5400	5450
731040	NO. 2 ENGINE - FLOW DIVIDER VALVE 25950-2 9959534373 REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C		R:0 R:0 R:0		03-OCT-2010 1888.2 1655		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731060	NO. 2 ENGINE - VISUAL INSPECT BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: GENERIC BLANK	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
731065	NO. 2 ENGINE - BLEED VALVE ACTUATOR PN SN-UNKNOWN REF: EMM 73-10-12	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
731085	NO. 2 ENGINE - SCHEDULE MODULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
+ 731090	NO. 2 ENGINE - VISUALLY INSPECT FLOW DIVIDER VALVE 25950-2 9959534373 REF: GENERIC NO REF	MOS HRS/MSC ENC	5400	+50/-50		-3598. 2	23-AUG-2018 3598.2 3045	(5400) 5400	5450
732020	NO. 2 ENGINE - ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
732030	NO. 2 ENGINE - HYDROMECHANICAL METERING UNIT 790155-10 F63454 REF: EMM 73-20-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-OCT-2010 1888.2 1655		
+ 732040	NO. 2 ENGINE - VISUALLY INSPECT ELECTRONIC BLEED VALVE CONTROL PN SN-UNKNOWN REF: EMM 73-20-04	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
+ 732050	NO. 2 ENGINE - VISUALLY INSPECT ELECTRONIC CONTROL COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732060	NO. 2 ENGINE - VISUAL INSPECT MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
732065	NO. 2 ENGINE - MAIN WIRING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
733010	NO. 2 ENGINE - FUEL FLOW TRANSMITTER 5/8-1-81-303 202530 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : JT15D-5/5R Serial # PCE-JA0722 Part # 3030100

+ 740000	NO. 1 ENGINE - OPERATIONAL TEST SPARK IGNITERS REF: EMM 74-00-00	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
741010	NO. 1 ENGINE - IGNITION EXCITER 3054825-02 NNA08413232 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			13-MAY-2019 3808.8 3211		
+ 741030	NO. 1 ENGINE - VISUAL INSPECT IGNITION EXCITER 3054825-02 NNA08413232 REF: EMM 74-10-01	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	
+ 742002	NO. 1 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION REF: EMM 74-20-02	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 742010	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG CH34659-3 NSN REF: EMM 74-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-JAN-2018 3473.1 2953		
+ 742020	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG CH34659-3 NSN REF: EMM 74-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			26-AUG-2019 3871.6 3259		
742030	NO. 1 ENGINE - 5 O'CLOCK IGNITER PLUG CABLE PN SN-UNKNOWN REF: EMM 74-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
742040	NO. 1 ENGINE - 7 O'CLOCK IGNITER PLUG CABLE PN SN-UNKNOWN REF: EMM 74-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100									
+ 740000	NO. 2 ENGINE - OPERATIONAL TEST SPARK IGNITERS REF: EMM 74-00-00	MOS HRS/MSC ENC	200	+10%			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
741010	NO. 2 ENGINE - IGNITION EXCITER 9060660-2 NN201199 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			23-JAN-2018 3473.1 2953		
+ 741030	NO. 2 ENGINE - VISUAL INSPECT IGNITION EXCITER 9060660-2 NN201199 REF: EMM 74-10-01	MOS HRS/MSC ENC	200				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 742002	NO. 2 ENGINE - CHECK SPARK IGNITERS FOR CLEANLINESS AND EROSION	MOS					26-AUG-2019		
	REF: EMM 74-20-02	HRS/MSC ENC	200	+10%			3871.6 3259	(4071.6) 4071.6	4091.6
+ 742010	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG	MOS					26-AUG-2019		
	CH34659-3	HRS/MSC	O/C	N:0			3871.6		
	REF: EMM 74-20-02	NSN ENC		N:0			3259		
+ 742020	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG	MOS					26-AUG-2019		
	CH34659-3	HRS/MSC	O/C	N:0			3871.6		
	REF: EMM 74-20-02	NSN ENC		N:0			3259		
742030	NO. 2 ENGINE - 5 O'CLOCK IGNITER PLUG CABLE	MOS					23-MAR-2006		
	PN	HRS/MSC	O/C	N:0			0		
	REF: EMM 74-20-01	SN-UNKNOWN ENC		N:0			0		
742040	NO. 2 ENGINE - 7 O'CLOCK IGNITER PLUG CABLE	MOS					23-MAR-2006		
	PN	HRS/MSC	O/C	N:0			0		
	REF: EMM 74-20-01	SN-UNKNOWN ENC		N:0			0		
CHAPTER 75	AIR								
751001	NO. 1 ENGINE ANTI ICE VALVE	MOS					17-AUG-2011		
75.020	45AS66008-005	HRS/MSC	O/C				2009.3		
	REF: GENERIC NO REF	1416A AFL					1766		
751004	NO. 2 ENGINE ANTI ICE VALVE	MOS					27-MAR-2012		
75.020	45AS66008-005	HRS/MSC	O/C	O:0			2192.1		
	REF: GENERIC NO REF	0433A AFL		O:0			1935		

ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
750010	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3033057 3452 REF: EMM 75-00-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			03-OCT-2010 1888.2 1655		
ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100									
750010	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3033057 1674 REF: EMM 75-00-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			14-SEP-2011 2033.3 1787		
CHAPTER 77 ENGINE INDICATING									
771001	NO. 1 ENGINE N1 (FAN) INDICATOR PN 77.010 CAE330011 REF: AMM 77-11-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
771002	NO. 2 ENGINE N1 (FAN) INDICATOR PN 77.010 CAE330011 REF: AMM 77-11-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
771003	NO. 1 ENGINE N2 (TURBINE) INDICATOR PN 77.020 CAE330011 REF: AMM 77-12-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
771004	NO. 2 ENGINE N2 (TURBINE) INDICATOR PN 77.020 CAE330011 REF: AMM 77-12-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
771011	NO. 1 DATA CONCENTRATOR (DCU) UNIT 822-2362-004 4D994N REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771012	NO. 2 DATA CONCENTRATOR (DCU) UNIT 822-2362-004 4D98V7 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
771013	NO. 1 ENGINE DATA CONCENTRATOR (EDC) 822-2362-004 4D98TH REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
771014	NO. 2 ENGINE DATA CONCENTRATOR (EDC) 822-2362-004 4D98TG REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-AUG-2018 3598.2 3045		
772061 77.080	NO. 1 ENGINE ITT INDICATOR PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
772062 77.080	NO. 2 ENGINE ITT INDICATOR PN CAE330011 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
773001 77.090	NO. 1 ENGINE VIBRATION ACCELEROMETER 45AS86803-009 18515 REF: AMM 77-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
773002 77.090	NO. 2 ENGINE VIBRATION ACCELEROMETER 45AS86803-009 18545 REF: AMM 77-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
773013 77.100	ENGINE VIBRATION SIGNAL CONDITONER 45AS86803-011 AE72 REF: AMM 77-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
773019	ENGINE VIBRATION INDICATOR								
	45AS86803-007	MOS		O:0				03-OCT-2010	
77.110	01810133	HRS/MSC	O/C	O:0				1888.2	
	REF: AMM 77-31-00	AFL		O:0				1655	

ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100

771010	NO. 1 ENGINE - N1 SPEED SENSOR PROBE								
	PN	MOS		N:0				23-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	ENC		N:0				0	
771020	NO. 1 ENGINE - N2 SPEED SENSOR PROBE								
	PN	MOS		N:0				23-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	ENC		N:0				0	
772010	NO. 1 ENGINE - T1 THERMOCOUPLE HARNESS								
	3070219-01	MOS		N:0				23-MAR-2006	
	AA55282	HRS/MSC	O/C	N:0				0	
	REF: EMM 77-00-01	ENC		N:0				0	
772020	NO. 1 ENGINE - T6 THERMOCOUPLE HARNESS								
	3119093-01	MOS		O:0				24-OCT-2012	
	SN-UNKNOWN	HRS/MSC	O/C	O:0				2300.3	
	REF: EMM 77-00-02	ENC		O:0				2026	
772030	NO. 1 ENGINE - VARIABLE RESISTOR								
	PN	MOS		N:0				23-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: EMM 77-00-01	ENC		N:0				0	

ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100

771010	NO. 2 ENGINE - N1 SPEED SENSOR PROBE								
	PN	MOS		N:0				23-MAR-2006	
	SN-UNKNOWN	HRS/MSC	O/C	N:0				0	
	REF: GENERIC NO REF	ENC		N:0				0	



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723
4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771020	NO. 2 ENGINE - N2 SPEED SENSOR PROBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
772010	NO. 2 ENGINE - T1 THERMOCOUPLE HARNESS 3101637-01 FA0520992 REF: EMM 77-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
772020	NO. 2 ENGINE - T6 THERMOCOUPLE HARNESS 3119093-01 AW16190 REF: EMM 77-00-02	MOS HRS/MSC ENC	O/C	O:0 O:0 O:0			23-AUG-2018 3598.2 3045		
772030	NO. 2 ENGINE - VARIABLE RESISTOR PN SN-UNKNOWN REF: EMM 77-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 78	EXHAUST								
781001	NO. 1 ENGINE EXHAUST DUCT ASSEMBLY 3119721-01 A000A277 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
781002	NO. 2 ENGINE EXHAUST DUCT ASSEMBLY 3119721-01 A001W6B4 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783001	NO. 1 ENGINE THRUST REVERSER 225-0012-513 B4343-2 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783002	NO. 2 ENGINE THRUST REVERSER								
78.011	225-0012-515 B4344-2 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783061	NO. 1 ENGINE INBOARD STANG FAIRING								
78.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783062	NO. 2 ENGINE INBOARD STANG FAIRING								
78.050	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783063	NO. 1 ENGINE OUTBOARD STANG FAIRING								
78.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783064	NO. 2 ENGINE OUTBOARD STANG FAIRING								
78.060	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783085	NO. 1 ENGINE THRUST REVERSER UPPER DOOR								
78.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783086	NO. 2 ENGINE THRUST REVERSER UPPER DOOR								
78.070	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783087	NO. 1 ENGINE THRUST REVERSER LOWER DOOR								
78.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783088	NO. 2 ENGINE THRUST REVERSER LOWER DOOR								
78.080	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783109	NO. 1 ENGINE THRUST REVERSER INBOARD ACTUATOR								
78.090	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783110	NO. 2 ENGINE THRUST REVERSER INBOARD ACTUATOR								
78.090	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783111	NO. 1 ENGINE THRUST REVERSER OUTBOARD ACTUATOR								
78.100	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783112	NO. 2 ENGINE THRUST REVERSER OUTBOARD ACTUATOR								
78.100	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783133	NO. 1 ENGINE INBOARD THRUST REVERSER ACTUATING MECHANISM								
78.110	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783134	NO. 2 ENGINE INBOARD THRUST REVERSER ACTUATING MECHANISM								
78.110	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783135	NO. 1 ENGINE OUTBOARD THRUST REVERSER ACTUATING MECHANISM								
78.120	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783136	NO. 2 ENGINE OUTBOARD THRUST REVERSER ACTUATING MECHANISM								
78.120	PN SN-UNKNOWN REF: GENERIC CMM	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783157	NO. 1 ENGINE THRUST REVERSER INBOARD STOW LIMIT SWITCH								
78.130	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783158	NO. 2 ENGINE THRUST REVERSER INBOARD STOW LIMIT SWITCH								
78.130	225-0023-1 3071 REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783159	NO. 1 ENGINE THRUST REVERSER OUTBOARD STOW LIMIT SWITCH								
78.140	225-0032-1 03319 REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			01-AUG-2012 2296.7 2024		
783160	NO. 2 ENGINE THRUST REVERSER OUTBOARD STOW LIMIT SWITCH								
78.140	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783161	NO. 1 ENGINE THRUST REVERSER DEPLOY SWITCH								
78.150	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783162	NO. 2 ENGINE THRUST REVERSER DEPLOY SWITCH								
78.150	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783163	NO. 1 ENGINE THRUST REVERSER PRESSURE SWITCH								
78.160	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783164	NO. 2 ENGINE THRUST REVERSER PRESSURE SWITCH								
78.160	PN SN-UNKNOWN REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783205	NO. 1 ENGINE THRUST REVERSER SHUT-OFF VALVE								
78.170	13027-6 2147 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783206	NO. 2 ENGINE THRUST REVERSER SHUT-OFF VALVE								
78.170	13027-6 2151 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783217	NO. 1 ENGINE THRUST REVERSER CONTROL VALVE								
78.175	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783218	NO. 2 ENGINE THRUST REVERSER CONTROL VALVE								
78.175	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
783229	THRUST REVERSER CONTROL BOX								
78.040	45AS88856-005 1406 REF: AMM 78-30-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
CHAPTER 79	OIL								
793001	NO. 1 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
79.030	PN CAE330011 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793002	NO. 2 ENGINE OIL PRESSURE/TEMPERATURE INDICATOR								
79.030	PN CAE330011 REF: AMM 31-10-00	MOS HRS/MSC AFL	O/C				21-AUG-2018 3598.2 3045		
ENGINE NO. 1 Model : JT15D-5/-5R Serial # PCE-JA0722 Part # 3030100									
790010	NO. 1 ENGINE - OIL PUMP ASSEMBLY								
	3104289-01 EC01A000A085 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
792005	NO. 1 ENGINE - ANALYZE OIL AND FILTER (SOAP SAMPLE)								
	REF:	MOS HRS/MSC ENC	200	+10/-10			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4081.6
792010	NO. 1 ENGINE - CHANGE OIL/DRAIN AND FILL								
	REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				23-MAR-2006 0 0		
+ 792015	NO. 1 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER								
	REF: See Workcard	MOS HRS/MSC ENC	200	+20			26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4091.6
+ 792020	NO. 1 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER								
	REF: See Workcard	MOS HRS/MSC ENC	12 800	+50/-50			26-AUG-2019 3871.6 3259	26-AUG-2020 (4671.6) 4671.6	4721.6
+ 792110	NO. 1 ENGINE - THERMOSTATIC BYPASS VALVE								
	PN SN-UNKNOWN REF: EMM 79-21-01	MOS HRS/MSC ENC	4000	+100	N:0 N:0 N:0		23-MAR-2006 0 0	(4000) 4000	4100



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#1: S/N PCE-JA0722

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793010	NO. 1 ENGINE - OIL PRESSURE TRANSMITTER APTE-560-1000-200G 8378-2-697 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				23-AUG-2018 3598.2 3045		
793020	NO. 1 ENGINE - LOW OIL PRESSURE WARNING SWITCH 45AS48008-019 F045495 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
793030	NO. 1 ENGINE - OIL FILTER BYPASS PRESSURE SWITCH 45AS42011-001 2434 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
793040	NO. 1 ENGINE - OIL TEMPERATURE BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
ENGINE NO. 2 Model : JT15D-5/-5R Serial # PCE-JA0723 Part # 3030100									
790010	NO. 2 ENGINE - OIL PUMP ASSEMBLY 3104289-01 EC01A000A086 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-MAR-2006 0 0		
792005	NO. 2 ENGINE - ANALYZE OIL AND FILTER (SOAP SAMPLE) REF:	MOS HRS/MSC ENC	200 +10/-10				26-AUG-2019 3871.6 3259	(4071.6) 4071.6	4081.6
792010	NO. 2 ENGINE - CHANGE OIL/DRAIN AND FILL REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C				23-MAR-2006 0 0		



Status Report

HAWKER 400XP S/N RK-465 (N99VS): 4030.73 HRS, 3391 AFL as of 10-Sep-2020

ENGINE#2: S/N PCE-JA0723

4030.73 HRS, 3391 ENC

Owner: AVIAN APARTMENTS LLC Operator: CORTLAND DEVELOPMENT

Report Date: 23-SEP-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 792015	NO. 2 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER	MOS					26-AUG-2019		
	REF: See Workcard	HRS/MSC ENC	200	+20			3871.6 3259	(4071.6) 4071.6	4091.6
+ 792020	NO. 2 ENGINE - REMOVE THE OIL FILTER AND INSPECT FOR FOREIGN MATTER	MOS	12				26-AUG-2019	26-AUG-2020	
	REF: See Workcard	HRS/MSC ENC	800	+50/-50			3871.6 3259	(4671.6) 4671.6	4721.6
+ 792110	NO. 2 ENGINE - THERMOSTATIC BYPASS VALVE	MOS			N:0		23-MAR-2006		
	PN	HRS/MSC	4000	+100	N:0		0	(4000) 4000	4100
	SN-UNKNOWN	ENC			N:0		0		
	REF: EMM 79-21-01								
793010	NO. 2 ENGINE - OIL PRESSURE TRANSMITTER	MOS			N:0		29-OCT-2019		
	APTE-560-1000-200G	HRS/MSC	O/C		N:0		3923		
	8236-12-365	ENC			N:0		3300		
	REF: GENERIC NO REF								
793020	NO. 2 ENGINE - LOW OIL PRESSURE WARNING SWITCH	MOS			N:0		23-MAR-2006		
	45AS48008-019	HRS/MSC	O/C		N:0		0		
	F045503	ENC			N:0		0		
	REF: GENERIC NO REF								
793030	NO. 2 ENGINE - OIL FILTER BYPASS PRESSURE SWITCH	MOS			N:0		23-MAR-2006		
	45AS42011-001	HRS/MSC	O/C		N:0		0		
	2435	ENC			N:0		0		
	REF: GENERIC NO REF								
793040	NO. 2 ENGINE - OIL TEMPERATURE BULB	MOS			N:0		23-MAR-2006		
	PN	HRS/MSC	O/C		N:0		0		
	SN-UNKNOWN	ENC			N:0		0		
	REF: GENERIC NO REF								