

OWNER: CRASEL CORP
ADDRESS: 444 BRICKELL AVENUE
 MIAMI FL 33131-2492
PHONE: 502-5414 8319
FAX:

OPERATOR: CRASEL CORP
ADDRESS: 444 BRICKELL AVENUE
 MIAMI FL 33131-2492
PHONE: 502-5414 8319
FAX:

ANALYST: ALESSANDRA PEREIRA
EMAIL: APEREIRA@CAMPSYSTEMS.COM

514-636-2020 (OFFICE)
 514-636-7866 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 50500310/N302TG **MODEL:** EMB-505 - PHENOM 300 **MANUFACTURER:** EMBRAER

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 30-OCT-2015	757:42 A/C HRS	as of 31-JUL-2019	A/C HRS	as of ___/___/___
	361 AFL	as of 31-JUL-2019	AFL	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-DG0626/3072913-01 **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 03-AUG-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	757:42 ENG. HRS	as of 31-JUL-2019	ENG. HRS	as of ___/___/___
0 ENC		361 ENC	as of 31-JUL-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-DG0624/3072913-01 **MODEL:** PW535E **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 03-AUG-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	757:42 ENG. HRS	as of 31-JUL-2019	ENG. HRS	as of ___/___/___
0 ENC		361 ENC	as of 31-JUL-2019	ENC	as of ___/___/___



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05-30-01	600 FH MAINTENANCE PACKAGE							
	PKG 1	MOS				23-JUN-2018		
		HRS/MSC	600	+30/-30	18:30	581:30	1200	1230
	REF: SMR 05-30-01	AFL				283		
05-30-02	600 FH/12 MO MAINTENANCE PACKAGE							
	PKG 2	MOS	12	+30d/-30d		09-NOV-2018	09-NOV-2019	09-DEC-2019
		HRS/MSC	600	+30/-30		637:12	1237:12	1267:12
	REF: SMR 05-30-02	AFL				307		
05-30-10	1200 FH MAINTENANCE PACKAGE							
	PKG 10	MOS				30-OCT-2015		
		HRS/MSC	1200	+30/-30		0	1200	1230
	REF: SMR 05-30-10	AFL				0		
05-30-12	1200 FH/24 MO MAINTENANCE PACKAGE							
	PKG 12	MOS	24	+30d/-30d	10	20-OCT-2017	30-OCT-2019	29-NOV-2019
		HRS/MSC	1200	+30/-30		400:54	1600:54	1630:54
	REF: SMR 05-30-12	AFL				200		
05-30-20	1800 FH MAINTENANCE PACKAGE							
	PKG 20	MOS				30-OCT-2015		
		HRS/MSC	1800	+30/-30		0	1800	1830
	REF: SMR 05-30-20	AFL				0		
05-30-40	3000 FH MAINTENANCE PACKAGE							
	PKG 40	MOS				30-OCT-2015		
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-40	AFL				0		
05-30-41	3000 FH/48 MO MAINTENANCE PACKAGE							
	PKG 41	MOS	48	+30d/-30d		30-OCT-2015	30-OCT-2019	29-NOV-2019
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-41	AFL				0		
+ 05-30-42	3000 FH/60 MO MAINTENANCE PACKAGE							
	PKG 42	MOS	60	+1m/-1m		30-OCT-2015	30-OCT-2020	30-NOV-2020
		HRS/MSC	3000	+30/-30		0	3000	3030
	REF: SMR 05-30-42	AFL				0		
05-30-45	4800 FH MAINTENANCE PACKAGE							
	PKG 45	MOS				30-OCT-2015		
		HRS/MSC	4800	+30/-30		0	4800	4830
	REF: SMR 05-30-45	AFL				0		
05-30-50	6000 FH MAINTENANCE PACKAGE							
	PKG 50	MOS				30-OCT-2015		
		HRS/MSC	6000	+30/-30		0	6000	6030
	REF: SMR 05-30-50	AFL				0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-30-53	6000 FH/96 MO MAINTENANCE PACKAGE PKG 53 REF: SMR 05-30-53	MOS HRS/MSC AFL	96 6000 +30d/-30d +30/-30			30-OCT-2015 0 0	30-OCT-2023 6000	29-NOV-2023 6030
05-30-60	7800 FH MAINTENANCE PACKAGE PKG 60 REF: SMR 05-30-60	MOS HRS/MSC AFL	7800 +30/-30			30-OCT-2015 0 0	7800	7830
05-30-65	12000 FH MAINTENANCE PACKAGE PKG 65 REF: SMR 05-30-65	MOS HRS/MSC AFL	12000 +30/-30			30-OCT-2015 0 0	12000	12030
05-30-80	12 MO MAINTENANCE PACKAGE PKG 80 REF: SMR 05-30-80	MOS HRS/MSC AFL	12 +30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
05-30-81	24 MO MAINTENANCE PACKAGE PKG 81 REF: SMR 05-30-81	MOS HRS/MSC AFL	24 +30d/-30d	10		20-OCT-2017 400:54 200	30-OCT-2019	29-NOV-2019
05-30-82	36 MO MAINTENANCE PACKAGE PKG 82 REF: SMR 05-30-82	MOS HRS/MSC AFL	36 +1m/-1m			09-NOV-2018 637:12 307	09-NOV-2021	09-DEC-2021
05-30-83	48 MO MAINTENANCE PACKAGE PKG 83 REF: SMR 05-30-83	MOS HRS/MSC AFL	48 +30d/-30d			30-OCT-2015 0 0	30-OCT-2019	29-NOV-2019
05-30-84	60 MO MAINTENANCE PACKAGE PKG 84 REF: SMR 05-30-84	MOS HRS/MSC AFL	60 +30d/-30d			30-OCT-2015 0 0	30-OCT-2020	29-NOV-2020
05-30-87	120 MO MAINTENANCE PACKAGE PKG 87 REF: SMR 05-30-87	MOS HRS/MSC AFL	120 +30d/-30d			30-OCT-2015 0 0	30-OCT-2025	29-NOV-2025
05-30-90	120 MO THRESHOLD/ 60 MO MAINTENANCE PACKAGE PKG 90 REF: SMR 05-30-90	MOS HRS/MSC AFL	120 +30d/-30d			30-OCT-2015 0 0	30-OCT-2025	29-NOV-2025

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W
(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
051254	NO. 1 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12	+30d		09-NOV-2018	09-NOV-2019	09-DEC-2019
		HRS/MSC	600	+10%		637:12	(1237:12) 1237:12	1297:12
	REF: MM 05-20-00	ENC				307		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01								
051254	NO. 2 ENGINE - 600 HOURS/ 12 MONTHS INSPECTION							
	PKG 1	MOS	12	+30d		09-NOV-2018	09-NOV-2019	09-DEC-2019
		HRS/MSC	600	+10%		637:12	(1237:12) 1237:12	1297:12
	REF: MM 05-20-00	ENC				307		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
EM55-160520	REVIEW EMBRAER PHENOM 300 AMM 2757 TIME LIMITS / MAINTENANCE CHECKS (TLMC) CHAPTER 5 REVISION 40 DATED MAY 20/16								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160520	MOS HRS/MSC - AFL							
EM55-160705	REVIEW EMBRAER PHENOM 300 (EM55) - CHAPTER 4 - AIRWORTHINESS LIMITATIONS REVISION 09 DATED JUL 05/16 FREQUENCY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705	MOS HRS/MSC - AFL					(EBT)		
EM55-160705-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 41 DATED JUL 05/16 REQUIREMENT CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160705-1	MOS HRS/MSC - AFL					(EBT)		
EM55-160822	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS MAINTENANCE CHECKS (TLMC) REVISION 42 DATED AUGUST 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-160822	MOS HRS/MSC - AFL							
EM55-161022	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 43 DATED OCT 22/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161022	MOS HRS/MSC - AFL							



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EM55-161122	REVIEW EMBRAER 505 - PHENOM 300 (EM55) AIR WORTHINESS LIMITATIONS CHAPTER-4 REVISION 10 DATED NOV. 22/2016								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122	MOS HRS/MSC - AFL					(EBT)		
EM55-161122-1	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) CHAPTER-5, REVISION 44 DATED NOV 22/2016								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161122-1	MOS HRS/MSC - AFL							
EM55-161202	REVIEW EMBRAER PHENOM 300 (EM55) TIME LIMITS/MAINTENANCE CHECKS (TLMC) / CHAPTER-5 ADVANCE REVISION DATED DECEMBER 02/2016 REQUIREMENT SUMMARY CHANGE FORM								
REQUIREMENT CHANGE FORMS	REF: RCF EM55-161202	MOS HRS/MSC - AFL							
EM55-180219	REVIEW EMBRAER PHENOM 300 (EM55) SCHEDULE MAINTENANCE REQUIREMENTS (SMR 2757 - CHAPTER 5) PART III REV 01, DATED FEB 19/18								
REQUIREMENT CHANGE FORMS	REF: RCF EM55	MOS HRS/MSC - AFL					(EBT)		
EM55-190218A	REVIEW EMBRAER PHENOM 300 (EM55) CHAPTER 04 AIRWORTHINESS LIMITATIONS REVISION 11 DATED FEB 18/2019								
REQUIREMENT CHANGE FORMS	REF: RCF EM55	MOS HRS/MSC - AFL							
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01									



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E53E-160530	NO. 1 ENGINE - REVIEW	PW535E MM REV 11.0					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
E53E-160530	NO. 2 ENGINE - REVIEW	PW535E MM REV 11.0					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E53E	MOS HRS/MSC - ENC							
CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS									
H140-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF	INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE					PKG		
	PKG 87	MOS 120		+30d/-30d					
	REF: AMM 05-42-00	HRS/MSC AFL							
H242-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF	INTERFACE CONNECTORS IN THE REAR CENTER FUSELAGE					PKG		
	PKG 87	MOS 120		+30d/-30d			30-OCT-2015	0	0
	REF: AMM 05-42-00	HRS/MSC AFL					0	0	
H430-001 (s)	INTERNAL DETAILED INSPECTION OF	ENGINE/PYLON INTERFACE CONNECTORS AND BONDING JUMPERS					PKG		
	PKG 84	MOS 60		+30d/-30d			30-OCT-2015	0	0
	REF: AMM 05-46-00	HRS/MSC AFL					0	0	
H700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF	MAIN LANDING GEAR AND MAIN LANDING GEAR BAY BONDING JUMPERS AND CONNECTORS					PKG		
	PKG 84	MOS 60		+30d/-30d			30-OCT-2015	0	0
	REF: AMM 05-47-00	HRS/MSC AFL					0	0	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
H700-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF JUMPERS AND CONNECTORS						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: AMM 05-47-00	HRS/MSC AFL					0 0		
H700-003 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WOW SENSORS ELECTRICAL BONDING						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: AMM 05-47-00	HRS/MSC AFL					0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01									
+ 05-50-00-210-802	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS								
		MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC ENC	A/R				0 0		
+ 05-50-00-210-803	NO. 1 ENGINE - ENGINE OVERTEMPERATURE								
		MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC ENC	A/R				0 0		
+ 05-50-00-210-804	NO. 1 ENGINE - ENGINE OVERSPEED								
		MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC ENC	A/R				0 0		
+ 05-50-00-210-806	NO. 1 ENGINE - LIGHTNING STRIKE								
		MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC ENC	A/R				0 0		
+ 05-50-00-210-807	NO. 1 ENGINE - DROPPED ENGINE								
		MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC ENC	A/R				0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-808	NO. 1 ENGINE - HEAVY LANDING	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-809	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-810	NO. 1 ENGINE - ENGINE IMMERSION IN WATER	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-811	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-812	NO. 1 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-813	NO. 1 ENGINE - LOSS OF OIL	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-814	NO. 1 ENGINE - CHIP DETECTOR LIGHT "ON"	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-815	NO. 1 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-816	NO. 1 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-817	NO. 1 ENGINE - HIGH OR LOW OIL PRESSURE								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-818	NO. 1 ENGINE - OIL PRESSURE EXCEEDS LIMITS								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-819	NO. 1 ENGINE - FUEL FILTER CONTAMINATION								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-820	NO. 1 ENGINE - HIGH POWER ENGINE SHUTDOWN								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-821	NO. 1 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-822	NO. 1 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL	MOS					14-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
+ 05-50-00-210-802	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) FAULTS	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-803	NO. 2 ENGINE - ENGINE OVERTEMPERATURE	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-804	NO. 2 ENGINE - ENGINE OVERSPEED	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-806	NO. 2 ENGINE - LIGHTNING STRIKE	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-807	NO. 2 ENGINE - DROPPED ENGINE	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		
+ 05-50-00-210-808	NO. 2 ENGINE - HEAVY LANDING	MOS					09-JUL-2015		
	REF: MM 05-50-00	HRS/MSC	A/R				0		
		ENC					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-809	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-810	NO. 2 ENGINE - ENGINE IMMERSION IN WATER								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-811	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-812	NO. 2 ENGINE - AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-813	NO. 2 ENGINE - LOSS OF OIL								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-814	NO. 2 ENGINE - CHIP DETECTOR LIGHT "ON"								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-815	NO. 2 ENGINE - OIL TEMPERATURE EXCEEDS LIMITS								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 05-50-00-210-816	NO. 2 ENGINE - USE OF UNAPPROVED ENGINE OIL BRANDS								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-817	NO. 2 ENGINE - HIGH OR LOW OIL PRESSURE								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-818	NO. 2 ENGINE - OIL PRESSURE EXCEEDS LIMITS								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-819	NO. 2 ENGINE - FUEL FILTER CONTAMINATION								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-820	NO. 2 ENGINE - HIGH POWER ENGINE SHUTDOWN								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-821	NO. 2 ENGINE - STARTER GENERATOR UNSCHEDULED REMOVAL								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		
+ 05-50-00-210-822	NO. 2 ENGINE - HYDRAULIC PUMP UNSCHEDULED REMOVAL								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 05-50-00	ENC					0		

CHAPTER 21 AIR CONDITIONING

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-01-01	RH INSC ILLUM PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-20-01	AVIONICS BLOWER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-20-02	AVIONICS/DISPLAY COOLING FAN PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-20-03	NO. 1 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 923 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-20-03	NO. 2 FLOW CONTROL & SHUTOFF VALVE/MUFFLER ASSY 1300250-9 930 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-20-05	GROUND COOLING FAN 1133660-3 457 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-21-02-001 (s)	OPERATIONAL CHECK NO. 1 INLET AIR CHECK VALVE PKG 50 REF: AMM 21-21-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-21-02-001 (s)	OPERATIONAL CHECK NO. 2 INLET AIR CHECK VALVE PKG 50 REF: AMM 21-21-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-23-01	ELECTROMECHANICAL LINEAR ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
21-23-03	RAM AIR VALVE 505-18030-405 0000853770 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
21-23-03-002 (s)	OPERATIONAL CHECK OF RAM AIR VALVE POSITION PKG 50 REF: AMM 21-23-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-23-03-003 (s)	OPERATIONAL CHECK OF RAM AIR VALVE ACTUATION PKG 1 REF: AMM 21-23-03	MOS HRS/MSC AFL	600				PKG 23-JUN-2018 581:30 283		
21-23-04-001 (s)	OPERATIONAL CHECK OF RAM AIR CHECK VALVES PKG 50 REF: AMM 21-23-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-23-05-001 (s)	GENERAL VISUAL INSPECTION OF GROUND COOLING FAN PKG 10 REF: AMM 21-23-05	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-24-01-001 (s)	OPERATIONAL CHECK OF IFE COOLING FAN PKG 50 REF: AMM 21-24-01	MOS HRS/MSC AFL	6000	+15/-30			PKG 30-OCT-2015 0 0		
21-31-00-002 (s)	OPERATIONAL CHECK OF MANUAL PRESSURIZATION CONTROL MODE PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
21-31-00-003 (s)	OPERATIONAL CHECK OF EMERGENCY CABIN DECOMPRESSION (AUTO MODE) PKG 1 REF: AMM 21-31-00	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
21-31-00-004 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS DIGITAL AND DISCRETE SIGNALS PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-31-00-005 (s)	OPERATIONAL CHECK OF ECMU-TO-AVIONICS ANALOG SIGNAL PKG 50 REF: AMM 21-31-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-31-01	(ECMU) - ELECTRONIC CONTROL AND MONITORING UNIT 2119286-9 2119286-01083 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-OCT-2015 0 0		
21-31-01-001	RESTORATION (REPAIR) OF ELECTRONIC CONTROL AND MONITORING UNIT (ECMU) 2119286-9 2119286-01083 REF: AMM 21-31-01	MOS HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0	6000	6030

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-02	OUTFLOW VALVE 103922-1 103922-00331 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-31-02-001	RESTORATION (REPAIR) OF OUTFLOW VALVE 103922-1 103922-00331 REF: AMM 21-31-02	MOS HRS/MSC AFL	7200	+30/-30			30-OCT-2015 0 0	7200	7230
21-31-03	NEGATIVE PRESSURE RELIEF (NPR) VALVE 130664-2 34163-0701 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-31-03-001 (s)	OPERATIONAL CHECK OF NEGATIVE PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-31-04	PRESSURE RELIEF (PRV) VALVE 103918-2 103918-00415 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-31-04-001 (s)	FUNCTIONAL CHECK OF PRESSURE RELIEF VALVE PKG 50 REF: AMM 21-31-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
21-41-01	BHS SHUT-OFF VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-41-04	RH REAR W302, BASIC / BASIC G1000 / BASIC G3000 HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-52-01	CDM - COMPRESSOR 1133640-5 490 REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-52-01-001	DETAILED INSPECTION OF VCS COMPRESSOR DRIVE MODULE REF: AMM 21-52-01	MOS HRS/MSC AFL	O/C				20-OCT-2017 400:54 200		
21-52-01-002 (s)	DISCARD OF COMPRESSOR DRIVE MODULE BELT PKG 20 REF: AMM 21-52-01	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
21-52-01-003 (s)	FUNCTIONAL CHECK OF COMPRESSOR BELT TENSION PKG 1 REF: AMM 21-52-01	MOS HRS/MSC AFL	600	+30/-30			PKG 20-OCT-2017 400:54 200		
21-52-01-004	RESTORATION (OVERHAUL) CDM - COMPRESSOR 1133640-5 490 REF: AMM 21-52-01	MOS HRS/MSC AFL	2000	+30/-30			30-OCT-2015 0 0	2000	2030
21-52-03	SYSTEM AIR CONDITION CABIN EVAPORATOR MODULE 1133860-4 477 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-52-03-001 (s)	GENERAL VISUAL INSPECTION OF EVAPORATOR MODULES PKG 1 REF: AMM 21-52-03	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
21-52-04	FORWARD FUSELAGE FWD EVAPORATOR, VCS SYSTEM BLOWER 1133850-104 809 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-52-06-001 (s)	SERVICING OF VCS REFRIGERANT FLUID PKG 2 REF: AMM 12-17-00	MOS HRS/MSC AFL	12 600				PKG 09-NOV-2018 637:12 307		
21-52-08	AIR CONDITION CONDENSER ASSEMBLY 1133760-2 436 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-52-08-001 (s)	GENERAL VISUAL INSPECTION OF VCS CONDENSER PKG 10 REF: AMM 21-52-08	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		
21-52-09	AIR CONDITION MIX FLOW CONDENSER FAN 1133720-4 461 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
21-52-10	AIR CONDITION BLEED AIR HEAT EXCHANGER 1320260-2 429 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-61-00-001 (s)	OPERATIONAL CHECK OF MANUAL TEMPERATURE CONTROL SYSTEM PKG 1	MOS					PKG		
	REF: AMM 21-61-00	HRS/MSC AFL	600	+30/-30			23-JUN-2018 581:30 283		
21-61-01	ECS TEMPERATURE CONTROLLER 1300670-6 00425	MOS					22-JUN-2016		
	REF: See Workcard	HRS/MSC AFL	O/C				95:14 54		
21-61-03	LEFT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					30-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0		0		
					TSN:0		0		
21-61-03	RIGHT REAR DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					30-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0		0		
					TSN:0		0		
21-61-04	COCKPIT DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					30-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0		0		
					TSN:0		0		
21-61-05	CABIN PASSENGER DUCT TEMPERATURE SENSOR/SWITCH 1300450-10	MOS					30-OCT-2015		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0		0		
					TSN:0		0		
21-61-06-001 (s)	OPERATIONAL CHECK OF E-BAY OVERTEMPERATURE SENSOR PKG 50	MOS					PKG		
	REF: AMM 21-61-06	HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0		

CHAPTER 22 AUTO FLIGHT

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-00	GMC 715 GUIDANCE PANEL 011-01430-00 15900863 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-00-001	FUNCTIONAL CHECK AILERON REF: AMM 22-11-00	GSA 81 LOW TORQUE AUTOPILOT SERVO MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK ELEVATOR REF: AMM 22-11-00	GSA 81 LOW TORQUE AUTOPILOT SERVO MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK RUDDER REF: AMM 22-11-00	GSA 81 LOW TORQUE AUTOPILOT SERVO MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
AIRWORTHINESS									
22-11-00-001	FUNCTIONAL CHECK TAIL CONE REF: AMM 22-11-00	GSA 80 HIGH SPEED AUTOPILOT SERVO MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
AIRWORTHINESS									
22-11-00-002 (s)	LUBRICATION OF SERVO ACTUATORS PKG 12 REF: AMM 22-11-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 20-OCT-2017 400:54 200		
22-11-00-003 (s)	DETAILED INSPECTION OF AUTOPILOT SERVO CABLE PKG 42 REF: AMM 22-11-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-01	TAIL CONE GSA 80 HIGH SPEED AUTOPILOT SERVO 011-00877-21 1A0006521 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-02	AILERON GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1013427 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-02	ELEVATOR GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1013350 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-02	RUDDER GSA 81 LOW TORQUE AUTOPILOT SERVO 011-00878-20 1A1013356 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-03	AILERON GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK014225 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-06	ELEVATOR GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK014143 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
22-11-09	RUDDER GSM 86 AUTOPILOT SERVO MOUNT 011-01904-00 1GK014144 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-12	TAILCONE GSM 86 AUTOPILOT SERVO (VENTRAL-RUDDER) MOUNT 011-01904-00 1GK014247 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 23 COMMUNICATIONS									
23-10-01	VHF ANTENNA S65-8280-41 322-4414 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-10-03	VHF 3 ANTENNA S65-8280-41 322-4393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-11-01	PS440 HF CONTROL DISPLAY UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-11-02	REAR FUS KRX1053 W/SELCA HF COMMUNICATION TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-11-03	KPA 1052 POWER AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-11-04	HF ANTENNA COUPLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-12-02	BOTTOM VHF 2 ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-21-01	SELCAL CSD DECODER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-50-01	LEFT GMA 1347D AUDIO PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-50-02	COPILOT HEADSET 026-55-999-0131 00202759 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-50-02	PILOT HEADSET 026-55-999-0131 00203372 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-50-03	HAND MICROPHONE 85-03-12369-04 383852 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-50-04	COCKPIT SPEAKER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-50-05	CDVR MICROPHONE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-51-00-001 (s)	OPERATIONAL CHECK OF AIRBORNE AUDIO SYSTEM FAIL-SAFE MODE PKG 40 REF: AMM 23-51-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
23-51-01	RIGHT GMA 1347D AUDIO PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-51-05	LEFT CONTROL PANEL 441-40943-002 1392 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-51-05	RIGHT CONTROL PANEL 441-40943-002 1393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
23-61-00-001 (s)	FUNCTIONAL CHECK OF STATIC DISCHARGERS PKG 83 REF: AMM 23-61-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
CHAPTER 24 ELECTRICAL POWER									
24-01-01	LEFT CONSOLE CONTROL PANEL 441-40929-002 0693 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01	NO. 1 ENGINE STARTER/GENERATOR 400SG180Q S00151XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
24-31-01	NO. 2 ENGINE STARTER/GENERATOR 400SG180Q S00434XL REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:1 TSN:0 TSN:0			05-MAY-2016 63:48 40		
24-31-01-001	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00151XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30			30-OCT-2015 0 0	1200	1230
24-31-01-001	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00434XL REF: AMM 24-31-01	MOS HRS/MSC AFL	1200	+30/-30			05-MAY-2016 63:48 40	1263:48	1293:48
24-31-01-002	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST-MOD SB 505-24-0017) 400SG180Q S00151XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30	18:30		23-JUN-2018 581:30 283	1200	1230
24-31-01-002	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR STARTER GENERATOR BRUSHES - (FOR STARTER GENERATOR P/N MG103C-4 OR 400SG180Q OR POST MOD SB 505-24-0017) 400SG180Q S00434XL REF: AMM 24-31-01	MOS HRS/MSC AFL	600	+30/-30			23-JUN-2018 581:30 283	1181:30	1211:30

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-01-003	RESTORATION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						30-OCT-2015	
	S00151XL	HRS/MSC	N/A					0	
	REF: AMM 24-31-01	AFL						0	
24-31-01-003	RESTORATION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						30-OCT-2015	
	S00434XL	HRS/MSC	N/A					0	
	REF: AMM 24-31-01	AFL						0	
24-31-01-004	DETAILED INSPECTION NO. 1 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						30-OCT-2015	
	S00151XL	HRS/MSC	N/A					0	
	REF: AMM 24-31-01	AFL						0	
24-31-01-004	DETAILED INSPECTION NO. 2 ENGINE STARTER/GENERATOR - (FOR STARTER GENERATOR P/N MG103C-3 OR PRE MOD SB 505-24-0017)								
	400SG180Q	MOS						30-OCT-2015	
	S00434XL	HRS/MSC	N/A					0	
	REF: AMM 24-31-01	AFL						0	
24-31-02	LEFT 28V DC GENERATOR CONTROL UNIT								
	GCSG550-12A	MOS		TSN:0				30-OCT-2015	
	52473	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	AFL		TSN:0				0	
24-31-02	RIGHT 28V DC GENERATOR CONTROL UNIT								
	GCSG550-12A	MOS		TSN:0				30-OCT-2015	
	52475	HRS/MSC	O/C	TSN:0				0	
	REF: See Workcard	AFL		TSN:0				0	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF LH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 30-OCT-2015 0 0		
+ 24-31-07-001 (s)	RESTORATION (CLEANING) OF RH SHUNT GENERATOR PKG 84 REF: AMM 24-31-07	MOS HRS/MSC AFL	60				PKG 30-OCT-2015 0 0		
24-36-01	AFT MAIN BATTERY 7638-48P G02951380 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:17 TSN:266 TSN:122			23-JUN-2018 581:30 283		
24-36-01	FORWARD MAIN BATTERY 7639-34 G03011775 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-NOV-2018 637:12 307		
24-36-01-003	DISCARD AFT MAIN BATTERY 7638-48P G02951380 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			21-JUN-2017 315:30 161	21-JUN-2019 761	21-JUL-2019 791
24-36-01-003	DISCARD FORWARD MAIN BATTERY 7639-34 G03011775 REF: AMM 24-36-01	MOS HRS/MSC AFL	24 600	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2020 907	09-DEC-2020 937
24-36-01-004	FUNCTIONAL CHECK AFT MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7638-48P G02951380 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-36-01-004	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (PRE-MOD SB 505-24-0015) 7639-34 G03011775 REF: AMM 24-36-01	MOS HRS/MSC AFL	N/A						
24-36-01-005	FUNCTIONAL CHECK AFT MAIN BATTERY - (POST-MOD SB 505-24-0015) 7638-48P G02951380 REF: AMM 24-36-01	MOS HRS/MSC AFL	6	+30d/-30d			09-NOV-2018 637:12 307	09-MAY-2019	08-JUN-2019
24-36-01-005	FUNCTIONAL CHECK FORWARD MAIN BATTERY - (POST-MOD SB 505-24-0015) 7639-34 G03011775 REF: AMM 24-36-01	MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
24-36-02-001 (s)	OPERATIONAL CHECK OF BATTERY CURRENT SENSOR (HB2) PKG 50 REF: AMM 24-36-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
24-54-05	28 VDC / 115 VAC STATIC INVERTER AS-24-0026-001 0731 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
24-65-00	W109 LEFT POWER DISTRIBUTION UNIT (LPDU) / RIGHT POWER DISTRIBUTION UNIT (RPDU) FEEDER CABLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
24-65-01	LEFT POWER DISTRIBUTION BOX SX7EG20-3 0367 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-65-02	RIGHT POWER DISTRIBUTION BOX SX7EG21-3 0348 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
24-65-04	NOSE POWER DISTRIBUTION BOX SX7EG22-1B 0064 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2016 50:27 31		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-11-01	COPILOT SEAT 1419-04GM 865-1419 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-11-01	PILOT SEAT 1419-03GM 864-1419 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-11-01-001 (s)	DETAILED INSPECTION COPILOT SEAT PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-11-01-001 (s)	DETAILED INSPECTION PILOT SEAT PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-11-01-002 (s)	DETAILED INSPECTION OF COCKPIT SEAT BELTS PKG 40 REF: AMM 25-11-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-01	PAX 1 - RH AFT FACE SEAT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-21-01	PAX 2 - LH AFT FACE SEAT 403174-29CAFFSLAF 58397 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-21-01	PAX 3 - RH AFT FACE SEAT 403174-30CAFFSLAF 58399 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-21-01	PAX 6 - LH FWD FACE SEAT 403174-31CAFFSLAF 58401 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-21-01	PAX 7 - RH FWD FACE SEAT 403174-32CAFFSLAF 58402 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER SEATS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-21-01-002 (s)	DETAILED INSPECTION OF PASSENGER SEAT BELTS PKG 40 REF: AMM 25-21-01	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-02-001 (s)	DETAILED INSPECTION DIVAN PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-21-02-002 (s)	DETAILED INSPECTION DIVAN SEAT BELTS PN PKG 40 SN-UNKNOWN REF: AMM 25-21-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-21-03	PAX 4 - LH FWD FACE SEAT 403174-29CAFFSLAF 58398 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
25-21-03	PAX 5 - RH FWD FACE SEAT 403174-30CAFFSLAF 58400 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
25-21-04-001	RESTORATION (DIVAN AIRBAG SYSTEM)ELECTRONIC MODULE ASSY (OVERHAUL) OF SEAT BELT AIRBAG SYSTEM REF: AMM 25-21-04	MOS HRS/MSC AFL	N/A						
25-43-01-001 (s)	DETAILED VISUAL INSPECTION BELTED TOILET UNIT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
25-43-01-002 (s)	DETAILED VISUAL INSPECTION BELTED TOILET SEAT BELT PKG 40 REF: AMM 25-43-02	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60-01	EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100174041 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-60-03	ELT ANTENNA S65-8282-406 401-2660 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-60-11	EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-61-00-001	OPERATIONAL CHECK EMERGENCY LOCATOR TRANSMITTER OF ELT SYSTEM S1821502-02 LX1100174041 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				09-NOV-2018 637:12 307	09-NOV-2019	
25-61-00-002	GENERAL VISUAL INSPECTION EMERGENCY LOCATOR TRANSMITTER OF EMERGENCY LOCATOR TRANSMITTER S1821502-02 LX1100174041 REF: AMM 25-61-00	MOS HRS/MSC AFL	12				09-NOV-2018 637:12 307	09-NOV-2019	
25-61-04-001	DISCARD EMERGENCY LOCATOR TRANSMITTER BATTERY S1820506-01C SN-UNKNOWN REF: AMM 25-61-04	MOS HRS/MSC AFL	DUE					01-OCT-2021 M	
25-61-05	CS144-A ELT/NAV INTERFACE MODULE S1825502-02 TM0000078404 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-61-05-001	RESTORATION (REPAIR) OF ELT/NAV INTERFACE MODULE S1825502-02 TM0000078404 REF: AMM 25-61-07	MOS HRS/MSC AFL	120 16000				30-OCT-2015 0 0	30-OCT-2025 16000	
25-62-01	FIRST AID KIT 019708-0005L US00010047 REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T	TSN:5 TSN:0 TSN:0			20-OCT-2017 400:54 200		
25-62-01-001	VISUAL CHECK FIRST AID KIT 019708-0005L US00010047 REF: AMM 25-62-01	MOS HRS/MSC AFL	DUE				20-OCT-2017 400:54 200	01-FEB-2019 M	
25-62-02	COPILOT LIFE VEST 66601-505 L2338670 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 1 PASSENGER LIFE VEST 66601-105 L3012756 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 2 PASSENGER LIFE VEST 66601-105 L3012757 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 3 PASSENGER LIFE VEST 66601-105 L3012759 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02	NO. 4 PASSENGER LIFE VEST 66601-105 L2759463 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 5 PASSENGER LIFE VEST 66601-105 L3012755 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 6 PASSENGER LIFE VEST 66601-105 L3012762 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 7 PASSENGER LIFE VEST 66601-105 L3012763 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	NO. 8 PASSENGER LIFE VEST 66601-105 L3012767 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
25-62-02	PILOT LIFE VEST 66601-505 L2338664 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
+ 25-62-02-001	RESTORATION (OVERHAUL) OF CO-PILOT LIFE VEST 66601-505 L2338670 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-NOV-2013	01-NOV-2023	
OVERHAUL									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
+ 25-62-02-001	RESTORATION (OVERHAUL) OF DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 1 LIFE VEST 66601-105 L3012756 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 2 LIFE VEST 66601-105 L3012757 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 3 LIFE VEST 66601-105 L3012759 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 4 LIFE VEST 66601-105 L2759463 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-DEC-2014	01-DEC-2024	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 5 LIFE VEST 66601-105 L3012755 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 6 LIFE VEST 66601-105 L3012762 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 7 LIFE VEST 66601-105 L3012763 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF NO. 8 LIFE VEST 66601-105 L3012767 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-AUG-2015	01-AUG-2025	
OVERHAUL									
+ 25-62-02-001	RESTORATION (OVERHAUL) OF PILOT LIFE VEST 66601-505 L2338664 REF: AMM 25-62-02	MOS HRS/MSC AFL	120				01-NOV-2013	01-NOV-2023	
OVERHAUL									
25-62-02-003	DISCARD COPILOT LIFE VEST 66601-505 L2338670 REF: AMM 25-62-02 Restoration Date:01-NOV-2013	MOS HRS/MSC AFL	O/C				01-NOV-2013		
+ 25-62-02-003	DISCARD DIVAN NO. 1 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									
+ 25-62-02-003	DISCARD DIVAN NO. 2 LIFE VEST PN SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	N/A						
OVERHAUL									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02-003	DISCARD NO. 1 PASSENGER LIFE VEST 66601-105 L3012756 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
Restoration Date:01-AUG-2015									
25-62-02-003	DISCARD NO. 2 PASSENGER LIFE VEST 66601-105 L3012757 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
Restoration Date:01-AUG-2015									
25-62-02-003	DISCARD NO. 3 PASSENGER LIFE VEST 66601-105 L3012759 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
Restoration Date:01-AUG-2015									
25-62-02-003	DISCARD NO. 4 PASSENGER LIFE VEST 66601-105 L2759463 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-DEC-2014		
Restoration Date:01-DEC-2014									
25-62-02-003	DISCARD NO. 5 PASSENGER LIFE VEST 66601-105 L3012755 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
Restoration Date:01-AUG-2015									
25-62-02-003	DISCARD NO. 6 PASSENGER LIFE VEST 66601-105 L3012762 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
Restoration Date:01-AUG-2015									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-02-003	DISCARD NO. 7 PASSENGER LIFE VEST 66601-105 L3012763 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
	Restoration Date:01-AUG-2015								
25-62-02-003	DISCARD NO. 8 PASSENGER LIFE VEST 66601-105 L3012767 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-AUG-2015		
	Restoration Date:01-AUG-2015								
25-62-02-003	DISCARD PILOT LIFE VEST 66601-505 L2338664 REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				01-NOV-2013		
	Restoration Date:01-NOV-2013								
25-62-04-001 (s)	DETAILED DIMENSIONAL INSPECTION OF WATER BARRIER PKG 81 REF: AMM 25-62-04	MOS HRS/MSC AFL	24	+30d/-30d			PKG 20-OCT-2017 400:54 200		
25-66-01	LIFE RAFT 913FASA-690-1-103 9UL-00895 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0		20-OCT-2017 400:54 200		
25-66-01-001	RESTORATION LIFE RAFT (OVERHAUL) 913FASA-690-1-103 9UL-00895 REF: AMM 25-66-01	MOS HRS/MSC AFL	DUE				20-OCT-2017 400:54 200	01-OCT-2020 M	
25-99-01	REAR FUS INTERCONNECTION CABLE S1825503-01 TM0000063228 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
257050	PAX NO.1 GTC570 TOUCHSCREEN CONTROLLER 011-01924-10 1MB505490 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
257050	PAX NO.2 GTC570 TOUCHSCREEN CONTROLLER 011-01924-10 1MB501235 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			15-FEB-2016 50:27 31		
CHAPTER 26 FIRE PROTECTION									
26-11-01	LEFT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 50754 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-11-01	RIGHT ENGINE FIRE DETECTOR 3951-51-565/215C-5.1M 50755 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		
26-11-01-001 (s)	DETAILED VISUAL INSPECTION RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		
26-11-01-002 (s)	OPERATIONAL CHECK LEFT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		
26-11-01-002 (s)	OPERATIONAL CHECK RIGHT ENGINE FIRE DETECTOR PKG 10 REF: AMM 26-11-01	MOS HRS/MSC AFL	1200	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-15-01	MODEL 602 SMOKE DETECTOR 8930-223B60L014 24066 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-21-01	ENGINE FIRE EXTINGUISHER BOTTLE 33000073-1 73042A1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-21-01-001	FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING PANEL REF: AMM 26-21-00	MOS HRS/MSC AFL	2400	+30/-30			30-OCT-2015 0 0	2400	2430
AIRWORTHINESS									
26-21-01A	FIRE/ENGINE/TRIM/IGNITION CONTROL PANEL 441-44278-001 1143 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-21-03-001	FUNCTIONAL CHECK ENGINE FIRE EXTINGUISHER BOTTLE OF ENGINE EXTINGUISHING BOTTLE 33000073-1 73042A1 REF: AMM 26-21-03	MOS HRS/MSC AFL	120				01-JUN-2015	01-JUN-2025	
AIRWORTHINESS									
26-21-05-001 (s)	OPERATIONAL CHECK OF TEMPERATURE COMPENSATED PRESSURE SWITCH (TCPS) PKG 20 REF: AMM 26-21-05	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
26-21-07	NO. 1 CARTRIDGE 30903962-1 1605TD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
26-21-07	NO. 2 CARTRIDGE 30903963-1 2515TD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-07-001	DISCARD NO. 1 CARTRIDGE 30903962-1 1605TD REF: AMM 26-21-07 Manufacture Date: 01-JUN-2015	MOS HRS/MSC AFL	120				01-JUN-2015	01-JUN-2025	
26-21-07-001	DISCARD NO. 2 CARTRIDGE 30903963-1 2515TD REF: AMM 26-21-07	MOS HRS/MSC AFL	120				01-JUN-2015	01-JUN-2025	
26-21-09-001 (s)	DETAILED VISUAL INSPECTION OF ENGINE FIRE EXTINGUISHING DISCHARGE PIPING PKG 20 REF: AMM 26-21-09	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
26-24-01	CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499620 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
26-24-01	COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499628 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
26-24-01-001	WEIGHT CHECK CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499620 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				09-NOV-2018	09-NOV-2019	
26-24-01-001	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499628 REF: AMM 26-24-01	MOS HRS/MSC AFL	12				09-NOV-2018	09-NOV-2019	
26-24-01-002	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499620 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-JUL-2014	01-JUL-2026	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-24-01-002	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499628 REF: AMM 26-24-01	MOS HRS/MSC AFL	144				01-JUL-2014	01-JUL-2026	
26-24-01-003	DISCARD CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499620 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A				01-JUL-2014		
26-24-01-003	DISCARD OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499628 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A				01-JUL-2014		
+ 26-24-01-004	WEIGHT CHECK OF CABIN PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499620 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
+ 26-24-01-004	WEIGHT CHECK OF COCKPIT PORTABLE FIRE EXTINGUISHER RT-A1200 Y-499628 REF: AMM 26-24-01	MOS HRS/MSC AFL	N/A						
CHAPTER 27	FLIGHT CONTROLS								
27-001	LEFT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0697 REF: See Workcard	MOS HRS/MSC AFL	7200				30-OCT-2015 0 0		7200
LIFE LIMIT									
27-001	RIGHT NO. 3 OUTBOARD FLAP ACTUATOR 475100-1013 0698 REF: See Workcard	MOS HRS/MSC AFL	7200				30-OCT-2015 0 0		7200
LIFE LIMIT									
27-002	LEFT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 1319 REF: See Workcard	MOS HRS/MSC AFL	7200				30-OCT-2015 0 0		7200
LIFE LIMIT									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-002	RIGHT NO. 2 OUTBOARD FLAP ACTUATOR 475000-2013 1369	MOS HRS/MSC AFL	7200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	7200	
LIFE LIMIT	REF: See Workcard								
27-003	LEFT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 1217	MOS HRS/MSC AFL	7200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	7200	
LIFE LIMIT	REF: See Workcard								
27-003	RIGHT NO. 1 INBOARD FLAP ACTUATOR 475000-1013 1381	MOS HRS/MSC AFL	7200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	7200	
LIFE LIMIT	REF: See Workcard								
27-004	ROLL TRIM ACTUATOR 470500-1005 0350	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	12000	
LIFE LIMIT	REF: See Workcard								
27-005	YAW TRIM ACTUATOR 470600-1005 0349	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	12000	
LIFE LIMIT	REF: See Workcard								
27-006	PITCH TRIM ACTUATOR 467500-1003 0177	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT	REF: See Workcard								
27-007	LEFT SPOILER ACTUATOR 456800-1003 0679	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT	REF: See Workcard								
27-007	RIGHT SPOILER ACTUATOR 456800-1003 0682	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-008	ELECTRO - RUDDER GUST LOCK ACTUATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-009	RUDDER BOOSTER ACTUATOR 9125-3 0338T REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:588 TSN:597			23-FEB-2019 688:18 333	35100:18	
27-01-01	LEFT CONTROL WHEEL 83912139 00929 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-01-01	RIGHT CONTROL WHEEL 83912141 00889 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-01-02	LH PEDAL ASSEMBLY 505-15420-427 0000853020 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-01-02	RH PEDAL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-01-03-001 (s)	LUBRICATION OF ROTARY BALL SPLINE PKG 81 REF: AMM 12-21-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 20-OCT-2017 400:54 200		
27-010	LEFT TOGGLE LINK 456870-1001 0786 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-010	RIGHT TOGGLE LINK 456870-1001 0791	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-011	STICK PUSHER ACTUATOR 9124-1 0358T	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-012	POWER DRIVE UNIT 467700-1003 0352	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-013	LEFT FLAP POSITION SENSOR UNIT 457310-1001 0731	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-013	RIGHT FLAP POSITION SENSOR UNIT 457310-1001 0739	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-014	LEFT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1298	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-014	LEFT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1303	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								
27-014	RIGHT INBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1346	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		35000
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-014	RIGHT OUTBOARD FLAP FLEXIBLE 1 SHAFT 457360-1005 SSW1357 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT									
27-015	LEFT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0608 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT									
27-015	RIGHT CENTER FLAP FLEXIBLE 2 SHAFT 457360-1007 SSW0610 REF: See Workcard	MOS HRS/MSC AFL	35000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0	35000	
LIFE LIMIT									
27-03-01	NO. 1 ELECTRONICS FLIGHT CONTROL 462900-1017 0912 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-03-01	NO. 2 ELECTRONICS FLIGHT CONTROL 462900-1017 0913 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-03-01-002 (s)	FUNCTIONAL CHECK OF PITCH TRIM ELECTRICAL STOP PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-03-01-003 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-03-01-004	OPERATIONAL CHECK OF SPOILER SURFACE POSITION MONITOR REF: AMM 27-03-01	MOS HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0	6000	6030
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-04-01	TRIM ACTUATOR CONTROLLER 475200-1009 0393 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-04-01-001 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM ACTUATION TIME LIMITER PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-04-01-002 (s)	FUNCTIONAL CHECK OF ROLL/ YAW TRIM TABS ELECTRICAL STOP PKG 50 REF: AMM 27-04-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-11-00-001 (s)	GENERAL VISUAL INSPECTION OF AILERON ACTUATING SYSTEM MECHANICAL COMPONENTS PKG 42 REF: AMM 27-11-00	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 30-OCT-2015 0 0		
27-11-01	LEFT AILERON 505-14717-405 0000857420 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-11-01	RIGHT AILERON 505-14718-405 0000860922 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-11-02-001	FUNCTIONAL CHECK OF AILERON CONTROL CABLES TENSION REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30		10	20-OCT-2017 400:54 200	30-OCT-2022 3400:54	30-NOV-2022 3430:54
27-11-02-002 (s)	DETAILED INSPECTION OF AILERON CONTROL CABLES PKG 42 REF: AMM 27-11-02	MOS HRS/MSC AFL	60 3000	+1m/-1m +30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-14-02-001	FUNCTIONAL CHECK OF AILERON TRIM BACKLASH/ INTEGRITY	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-14-03	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-14-02-002	DETAILED INSPECTION OF ROLL TRIM ACTUATING MECHANISM	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-14-02	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-14-03	LEFT AILERON TAB	MOS					30-OCT-2015		
	PN SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-21-00-001 (s)	GENERAL VISUAL INSPECTION OF RUDDER ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS					PKG 30-OCT-2015		
	PKG 42 REF: AMM 27-21-00	HRS/MSC AFL	60 3000	+1m/-1m +30/-30			0 0		
27-21-01	RUDDER ASSEMBLY	MOS					30-OCT-2015		
	505-39084-413 0000861213 REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-21-02-001	FUNCTIONAL CHECK OF RUDDER CONTROL CABLES TENSION	MOS					20-OCT-2017	30-OCT-2022	30-NOV-2022
	REF: AMM 27-21-02	HRS/MSC AFL	60 3000	+1m/-1m +30/-30	10		400:54 200	3400:54	3430:54
27-21-02-002 (s)	DETAILED INSPECTION OF RUDDER CONTROL CABLES	MOS					PKG 30-OCT-2015		
	PKG 42 REF: AMM 27-21-02	HRS/MSC AFL	60 3000	+1m/-1m +30/-30			0 0		
27-23-00-001 (s)	OPERATIONAL CHECK OF SPRING LOADED RUDDER BOOST SYSTEM	MOS					PKG 23-JUN-2018		
	PKG 1 REF: AMM 27-23-00	HRS/MSC AFL	600	+30/-30			581:30 283		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-24-02-001	FUNCTIONAL CHECK OF RUDDER TRIM BACKLASH	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-24-03	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-24-02-002	DETAILED INSPECTION OF YAW TRIM ACTUATING MECHANISM	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-24-02	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-24-03	RUDDER TRIM TAB	MOS					30-OCT-2015		
	PN SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-26-01	VENTRAL RUDDER	MOS					30-OCT-2015		
	505-07540-417 0000854176 REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-31-00-001 (s)	GENERAL VISUAL INSPECTION OF ELEVATOR ACTUATING SYSTEM MECHANICAL COMPONENTS	MOS	60	+1m/-1m			30-OCT-2015		
	PKG 42 REF: AMM 27-31-00	HRS/MSC AFL	3000	+30/-30			0 0		
27-31-01	LEFT ELEVATOR	MOS					30-OCT-2015		
	505-11082-401 0000855898 REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-31-01	RIGHT ELEVATOR	MOS					30-OCT-2015		
	505-11082-402 0000855899 REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		0 0 0		
27-31-02-001	FUNCTIONAL CHECK OF ELEVATOR CONTROL CABLES TENSION	MOS	60	+1m/-1m			20-OCT-2017	30-OCT-2022	30-NOV-2022
	REF: AMM 27-31-02	HRS/MSC AFL	3000	+30/-30	10		400:54 200	3400:54	3430:54

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-02-002 (s)	DETAILED INSPECTION OF ELEVATOR CONTROL CABLES PKG 42	MOS	60				PKG 30-OCT-2015		
	REF: AMM 27-31-02	HRS/MSC AFL	3000	+30/-30			0 0		
27-31-03	LEFT ELEVATOR TAB PN	MOS		TSN:0			30-OCT-2015		
	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
27-31-03	RIGHT ELEVATOR TAB PN	MOS		TSN:0			30-OCT-2015		
	SN-UNKNOWN REF: See Workcard	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
27-31-03-001 (s)	FUNCTIONAL CHECK OF ELEVATOR AUTO-TRIM BACKLASH PKG 50	MOS					PKG 30-OCT-2015		
	REF: AMM 27-31-03	HRS/MSC AFL	6000	+30/-30			0 0		
27-31-03-002 (s)	DETAILED INSPECTION OF ELEVATOR AUTO-TAB MECHANISM PKG 50	MOS					PKG 30-OCT-2015		
	REF: AMM 27-31-03	HRS/MSC AFL	6000	+30/-30			0 0		
27-31-05	MID CONTROL PANEL 441-44280-001	MOS		TSN:0			30-OCT-2015		
	1149 REF: GENERIC NO REF	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0		
27-36-03-001 (s)	OPERATIONAL CHECK OF PUSHER CUTOFF SWITCH PKG 12	MOS	24				PKG 20-OCT-2017		
	REF: AMM 27-36-03	HRS/MSC AFL	1200	+30d/-30d +30/-30			400:54 200		
27-41-01-001	DETAILED INSPECTION OF PITCH TRIM ACTUATOR REF: AMM 27-41-01	MOS					30-OCT-2015		
AIRWORTHINESS		HRS/MSC AFL	6000	+30/-30			0 0	6000	6030

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-41-01-002	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR BACKLASH	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-40-00	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-41-01-003 (s)	LUBRICATION OF PITCH TRIM ACTUATOR	MOS	48	+30d/-30d			30-OCT-2015		
	PKG 83	HRS/MSC AFL					0 0		
	REF: AMM 12-21-00								
27-41-01-004	OPERATIONAL CHECK OF PITCH TRIM ACTUATOR NO- BACK	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-41-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-41-01-005 (s)	SERVICING OF PITCH TRIM ACTUATOR GEAR BOXES	MOS	48				30-OCT-2015		
	PKG 83	HRS/MSC AFL					0 0		
	REF: AMM 12-18-00								
27-41-01-006 (s)	FUNCTIONAL CHECK OF PITCH TRIM ACTUATOR MECHANICAL STOP	MOS					30-OCT-2015		
	PKG 50	HRS/MSC AFL	6000	+30/-30			0 0		
	REF: AMM 27-41-01								
27-43-02	COCKPIT PITCH TRIM SYS - INSC ILLUM PANEL	MOS			TSN:0		30-OCT-2015		
	PN	HRS/MSC AFL	O/C		TSN:0		0 0		
	REF: GENERIC NO REF				TSN:0				
27-50-01-01-901	DETAILED INSPECTION OF ACTUATOR PINS. FLAP MECHANICAL COMPONENT - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 27-51-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
27-51-01-001 (s)	LUBRICATION OF FLAP ACTUATORS BALL SCREWS	MOS	48	+30d/-30d			30-OCT-2015		
	PKG 83	HRS/MSC AFL					0 0		
	REF: AMM 12-21-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-01-002	DETAILED INSPECTION LEFT NO. 1 INBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-002	DETAILED VISUAL INSPECTION LEFT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 1 INBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 2 OUTBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-002	DETAILED VISUAL INSPECTION RIGHT NO. 3 OUTBOARD FLAP ACTUATOR	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-004	FUNCTIONAL CHECK OF FLAP ACTUATOR TORQUE LIMITER	MOS					30-OCT-2015		
AIRWORTHINESS	REF: AMM 27-51-01	HRS/MSC AFL	6000	+30/-30			0 0	6000	6030
27-51-01-005 (s)	SERVICING OF FLAP ACTUATOR GEAR BOXES						PKG		
	PKG 83	MOS	48				30-OCT-2015		
	REF: AMM 12-18-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-05	LEFT INBOARD FLAP 505-14358-405 0000860326 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-51-05	LEFT OUTBOARD FLAP 505-14359-405 0000858045 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-51-05	RIGHT INBOARD FLAP 505-14358-406 0000859611 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-51-05	RIGHT OUTBOARD FLAP 505-14359-406 0000861200 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-51-06-001 (s)	LUBRICATION LEFT CENTER FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-001 (s)	LUBRICATION LEFT OUTBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-001 (s)	LUBRICATION LH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-001 (s)	LUBRICATION RH INBOARD FLAP FLEXIBLE SHAFT PKG 83 REF: AMM 12-21-00	MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-51-06-001 (s)	LUBRICATION RIGHT CENTER PKG 83 REF: AMM 12-21-00	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-001 (s)	LUBRICATION RIGHT OUTBOARD PKG 83 REF: AMM 12-21-00	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT CENTER PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LEFT OUTBOARD PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION LH INBOARD PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RH INBOARD PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT CENTER PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		
27-51-06-002 (s)	DETAILED VISUAL INSPECTION RIGHT OUTBOARD PKG 83 REF: AMM 27-51-06	FLAP FLEXIBLE SHAFT MOS HRS/MSC AFL	48	+30d/-30d			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-01	FLAP SELECTOR, PRODUCTION, LEVER 780501-9 1698 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-64-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LUG OF BELL CRANK. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL REF: NDT PART 6 27-64-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
27-64-01-01-902	DETAILED INSPECTION OF BELL CRANK AND FASTENERS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS - INTERNAL REF: NDT PART 5 27-64-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
27-64-01-02-901	SPECIAL DETAILED INSPECTION (MAGNETIC PARTICLE) OF BELL CRANK SAFE PINS. MULTIFUNCTION SPOILER MECHANICAL COMPONENTS- INTERNAL REF: NDT PART 7 27-64-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
27-65-00-001 (s)	FUNCTIONAL CHECK OF MULTIFUNCTION SPOILER SYSTEM PKG 50 REF: AMM 27-60-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-65-01-001 (s)	GENERAL VISUAL INSPECTION OF MULTIFUNCTION SPOILER POWER CONTROL UNIT (PCU) PKG 50 REF: AMM 27-65-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
27-66-01	NO. 1 CONTROL WHEEL POSITION SENSOR 456896-1001 167826 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-66-01	NO. 2 CONTROL WHEEL POSITION SENSOR 456896-1001 167831 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-66-02	LEFT SPOILER SURFACE POSITION SENSOR 456897-1001 170633 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
27-66-02	RIGHT SPOILER SURFACE POSITION SENSOR 456897-1001 171633 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 28 FUEL									
28-11-00-001 (s)	FUNCTIONAL CHECK OF FUEL TANKS FOR MICROORGANISMS PKG 80 REF: AMM 28-11-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 09-NOV-2018 637:12 307		
28-11-05	LEFT WING WATER DRAIN VALVE L83A13-628 J35142 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-11-05	RIGHT WING WATER DRAIN VALVE L83A13-628 J23587 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-11-07	LEFT WING DUMP VALVE V98A32-001 J35386 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-11-07	RIGHT WING DUMP VALVE V98A32-001 J35390 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-12-01-001 (s)	SPECIAL DETAILED INSPECTION OF FUEL VENT NACA PKG 2 REF: AMM 28-12-01	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
28-12-03	LEFT FUEL TANK FLOAT VENT VALVE L87-19-001P2 J28712 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-12-03	RIGHT FUEL TANK FLOAT VENT VALVE L87-19-001P2 J28710 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK LEFT FLOAT VENT VALVE PKG 50 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
28-12-03-001 (s)	OPERATIONAL CHECK RIGHT FLOAT VENT VALVE PKG 50 REF: AMM 28-12-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
28-21-01	LEFT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-01	RIGHT WING FUEL SYSTEM - ENGINE FEED 3/4 IN CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-02	LEFT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 G47936 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-02	RIGHT WING DC AUXILIARY BOOST PUMP CARTRIDGE P99C25-606P2 G42801 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-03	LEFT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 G54592 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-03	RIGHT WING DC AUXILIARY BOOST PUMP CANISTER C93R25-606P2 G54604 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-05	LEFT WING JET PUMP FEED LINE T99A19-602 G51909 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-05	RIGHT WING JET PUMP FEED LINE T99A19-602 G51911 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-07	LEFT 0.75 SHUTOFF VALVE B97-15-601 J29057 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-07	RIGHT 0.75 SHUTOFF VALVE B97-15-601 J29056 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-07-001	OPERATIONAL CHECK LEFT ENGINE FUEL SOV SYSTEM REF: AMM 28-21-07	MOS HRS/MSC AFL	600	+30/-30		18:30	23-JUN-2018 581:30 283	1200	1230
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-07-001	OPERATIONAL CHECK RIGHT ENGINE FUEL SOV SYSTEM	MOS					23-JUN-2018		
AIRWORTHINESS	REF: AMM 28-21-07	HRS/MSC AFL	600	+30/-30		18:30	581:30 283	1200	1230
28-21-08	FORWARD LEFT 28 VDC SOV ACTUATOR D97C00-644P2 C702149 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-08	LEFT WING 28 VDC SOV ACTUATOR D97C00-644P2 C702152 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-08	REAR RIGHT 28 VDC SOV ACTUATOR D97C00-644P2 C702150 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-09	LEFT WING SCAVENGER JET PUMP T99A19-603 G53481 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-09	RIGHT WING SCAVENGER JET PUMP T99A19-603 G53478 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-10	3/4" (CROSSFEED) SHUT OFF VALVE B97H19-608P2 G51482 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
28-21-10-001 (s)	OPERATIONAL CHECK OF FUEL XFEED VALVE PKG 65 REF: AMM 28-21-10	MOS HRS/MSC AFL	12000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-11	LEFT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 J34655 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-11	RIGHT WING 1/2 INCH CHECK VALVE VALVE L96-13-001 J34650 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-21-13	INSC ILLUM PANEL 441-42621-002 1331 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-23-01	REFUEL CONTROL PANEL 742388-1-2 742388IN00453 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-23-03	LEFT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P3 J38478 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-23-03	RIGHT WING PRESSURE REFUELING SOLENOID VALVE L94E31-653P3 J38480 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-23-04-001 (s)	GENERAL VISUAL INSPECTION OF PRESSURE REFUELING ADAPTER PKG 40 REF: AMM 28-23-05	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
28-23-07	LEFT HIGH LEVEL SENSOR 722860-2-0 0974 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-23-07	RIGHT HIGH LEVEL SENSOR 722860-2-0 0970 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-23-09	FUEL PORT AND CAP K97-63-613 J30169 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 1 LEFT PROBE 765896-1-0 765896IN00805 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 1 RIGHT PROBE 765896-1-0 765896IN00804 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 2 LEFT PROBE 765873-1-0 765873IN00825 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 2 RIGHT PROBE 765873-1-0 765873IN00824 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 3 LEFT PROBE 765874-1-0 765874IN00777 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 3 RIGHT PROBE 765874-1-0 765874IN00763 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-41-01	NO. 4 LEFT PROBE 765875-1-0 765875IN00823 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-01	NO. 4 RIGHT PROBE 765875-1-0 765875IN00825 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-41-05	EFCU ELECTRICAL FUEL CONTROL UNIT 738742-1-4 738790IN00884 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-43-01	TEMPERATURE SENSOR 798840-1-0 04282 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-43-01-001 (s)	FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSOR PKG 50 REF: AMM 28-43-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
28-45-01	LEFT PRESSURE SWITCH D98C07-611 1497 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
28-45-01	RIGHT PRESSURE SWITCH D98C07-611 1505 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 29	HYDRAULIC POWER								
29-12-02	CENTER FUSELAGE HYDRAULIC SYSTEM FLUID BOOTSTRAP RESERVOIR 3032763-003 MX791925 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-02	LEFT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX793002 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
29-12-02	RIGHT ENGINE DRIVEN HYDRAULIC PUMP 3032249-002 MX793001 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
29-12-02-001 (s)	VISUAL CHECK OF MANIFOLD/ RESERVOIR PKG 2 REF: AMM 29-12-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
29-12-02-002 (s)	OPERATIONAL CHECK LEFT EDP CHECK VALVE PKG 53 REF: AMM 29-10-00	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 30-OCT-2015 0 0		
29-12-02-002 (s)	OPERATIONAL CHECK RIGHT EDP CHECK VALVE PKG 53 REF: AMM 29-10-00	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			PKG 30-OCT-2015 0 0		
29-15-03	CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 11172-2 11172-0198 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
29-15-03-001 (s)	SERVICING CENTER FUSELAGE EMERGENCY/PARKING BRAKE - HYDRAULIC 25 CU.IN ACCUMULATOR 11172-2 PKG 2 11172-0198 REF: AMM 12-13-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
29-15-04	NO. 1 FSOV FIRE SHUT OFF VALVE 3032428-001 AA525950 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-15-04	NO. 2 FSOV FIRE SHUT OFF VALVE 3032428-001 AA525951 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
29-15-04-001	OPERATIONAL CHECK LEFT ENGINE HYDRAULIC SHUT-OFF VALVE REF: AMM 29-15-04	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			30-OCT-2015 0 0	30-OCT-2019 3000	29-NOV-2019 3030
AIRWORTHINESS									
29-15-04-001	OPERATIONAL CHECK RIGHT ENGINE HYDRAULIC SHUT-OFF VALVE REF: AMM 29-15-04	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			30-OCT-2015 0 0	30-OCT-2019 3000	29-NOV-2019 3030
AIRWORTHINESS									
29-15-05	PRIORITY VALVE 2217-0001-401 00333 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
29-31-02-001 (s)	FUNCTIONAL CHECK OF DIFFERENTIAL PRESSURE INDICATOR, RETURN FILTER BYPASS VALVE AND HP RELIEF VALVE PKG 53 REF: AMM 29-31-02	MOS HRS/MSC AFL	96 6000	+30d/-30d +30/-30			30-OCT-2015 0 0		
CHAPTER 30	ICE AND RAIN PROTECTION								
30-01-01	MD INSC ILLUM PANEL 441-44279-002 1151 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-00-001 (s)	OPERATIONAL CHECK OF WING/H-STAB ANTI-ICING SYSTEM PKG 50 REF: AMM 30-10-00	MOS HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0		
30-12-01-001 (s)	FUNCTIONAL CHECK OF WING/H-STAB ANTI-ICING VALVE PRESSURE TRANSDUCERS PKG 50 REF: AMM 30-12-01	MOS HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-02	LEFT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-3 0331 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-02	RIGHT WING AND HORIZONTAL STABILIZER ANTI-ICE VALVE RYLB-53534-4 0339 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	LEFT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-329 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	LEFT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-340 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	LEFT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-472 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	RIGHT HORIZONTAL STABILIZER ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-338 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	RIGHT PYLON ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-345 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
30-12-05	RIGHT WING TIP ANTI-ICE PRESSURE TRANSDUCER APTE-485F-1000-50G 8172-3-336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-12-05-001 (s)	FUNCTIONAL CHECK LEFT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
30-12-05-001 (s)	FUNCTIONAL CHECK RIGHT WING TIP ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK LEFT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
30-12-05-002 (s)	FUNCTIONAL CHECK RIGHT HORIZONTAL STABILIZER ANTI-ICING PRESSURE TRANSDUCER PKG 50 REF: AMM 30-12-05	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
30-21-01	LEFT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0001068 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
30-21-01	RIGHT ENGINE ANTI-ICE PRESUURE VALVE 10030295 0001069 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
30-21-02	LEFT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 8172-8-445 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
30-21-02	RIGHT ENGINE ANTI-ICE PRESSURE TRANSDUCER APTE-477F-1000-100G 8178-8-706 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-21-03-001 (s)	BORESCOPE INSPECTION OF PICCOLO TUBE PKG 50 REF: AMM 30-21-03	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
30-21-04-001 (s)	DETAILED INSPECTION OF ENGINE ANTI-ICE DUCTS PKG 20 REF: AMM 30-21-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
30-31-00-002	OPERATIONAL CHECK IASP PROBE AND PITOT STATIC HEATING PKG 81 REF: AMM 30-30-00	MOS HRS/MSC AFL	24	+30d/-30d	-80		20-OCT-2017 400:54 200	01-AUG-2019	31-AUG-2019
30-41-01-001	FUNCTIONAL CHECK OF WINDSHIELD RAIN REPELLENT COATING REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C				09-NOV-2018 637:12 307		
+ 30-41-01-002 (s)	DISCARD OF WINDSHIELD RAIN REPELLENT COATING PKG 80 REF: AMM 30-41-01	MOS HRS/MSC AFL	12				PKG 30-OCT-2015 0 0		
30-42-00-001 (s)	OPERATIONAL CHECK OF WINDSHIELD HEATING SYSTEM PKG 1 REF: AMM 30-42-00	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
30-42-01	LH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-4 02915 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
30-42-01	RH PANEL WINDSHIELD HEATER (OVERLENGTH) CONTROL EPM-112-4 02916 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-81-02	LEFT NOSE ICE DETECTOR 0871LM3-1 1403 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-30-02	CVDR ACCELEROMETER 3001-01-111 0515-DTY4157 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-30-03	REAR CVDR IMPACT SWITCH 5930-4-000 6894 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-31-00-002 (s)	OPERATIONAL CHECK OF CVR (COCKPIT VOICE RECORDER) PKG 80 REF: AMM 31-31-00	MOS HRS/MSC AFL	12	+30d/-30d			PKG 09-NOV-2018 637:12 307		
31-31-01	(CVR / CVDR) COCKPIT VOICE RECORDER 5003-6100-50 001048131 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-31-03	CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON DK120 SD52422 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-31-03-001	DISCARD CVDR/ULB - COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON BATTERY DK120 SD52422 REF: AMM 31-31-03	MOS HRS/MSC AFL	DUE					01-FEB-2021 M	
31-31-09	CVDR CONTROL PANEL 441-42635-003 0691 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-33-01	FDR - FLIGHT DATA RECORDER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-33-04	FORWARD CVDR IMPACT SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-33-05	ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-33-05	RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-33-05-001	FUNCTIONAL CHECK OF RUDDER FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				30-OCT-2015 0 0		
31-33-05-002	FUNCTIONAL CHECK OF ELEVATOR FDR (RVDT) ROTATORY VARIABLE DIFFERENTIAL TRANSDUCER PN SN-UNKNOWN REF: AMM 31-33-05	MOS HRS/MSC AFL	N/A				30-OCT-2015 0 0		
31-40-01	LH DCU UNIT 011-01457-00 16906418 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-40-01	RH DCU UNIT 011-01457-00 16906423 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-40-02	LEFT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-40 2DC001937 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-40-02	RIGHT GIA 63W INTEGRATED AVIONICS UNIT 011-01105-40 2DC001947 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-41-01	LH COCKPIT PARTITION MAINTNANCE SYSTEM INSC ILLUM PANEL 441-42627-001 1323 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-42-00-001 (s)	OPERATIONAL CHECK OF HSDB SWITCH REVERSION PKG 50 REF: AMM 31-42-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
31-50-01	(GEA 71) ENGINE AIRFRAME INTERFACE UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-50-01	1 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46720521 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-50-01	2 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46720487 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-50-01	3 (GEA) ENGINE AIRFRAME INTERFACE UNIT 011-00831-00 46720516 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-00	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) MFD AMLCD DISPLAY 011-01910-10 1F1105069 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK MFD 2 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
31-61-00-001 (s)	OPERATIONAL CHECK PFD 1 FLIGHT DISPLAY SYSTEM (MANUAL AND AUTOMATIC REVERSION MODE) PKG 40 REF: AMM 31-61-00	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
31-61-01	NO. 1 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01910-10 1F1105049 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-61-01	NO. 2 (GDU1240A, 12IN/GDU1400W, 14IN) PFD AMLCD DISPLAY 011-01910-10 1F1105070 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-61-05	TAWS SYSTEM INSC ILLUMINATED PANEL ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
31-61-06	NO. 1 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-06	NO. 2 BARO INSC ILLUMINATED PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 32 LANDING GEAR									
32-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF MAIN LANDING GEAR POLYURETHANE FILMS PKG 1 REF: AMM 32-00-20	MOS HRS/MSC AFL	600				PKG 23-JUN-2018 581:30 283		
32-001	LEFT MLG SHOCK STRUT LEFT MAIN FITTING 2317-1201-503 1573458/001 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
32-002	RIGHT MLG SHOCK STRUT RIGHT MAIN FITTING 2317-1201-504 1574847/001 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
32-003	LEFT PINTLE PIN 2317-1101-003 1571218/010 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
32-003	RIGHT PINTLE PIN 2317-1101-003 1571218/004 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
32-004	LEFT PINTLE PIN 2317-1102-001 1569447/008 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
32-004	RIGHT PINTLE PIN 2317-1102-001 1569447/012 REF: See Workcard	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-005	LEFT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1568812/008	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-005	RIGHT MLG SHOCK STRUT (MF - AS) AXLE 2317-1103-003 1568812/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-006	LEFT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1558260/012	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		15300
LIFE LIMIT	REF: See Workcard								
32-006	RIGHT MLG SHOCK STRUT (TR - AS) AXLE 2317-1107-005 1558260/007	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		15300
LIFE LIMIT	REF: See Workcard								
32-007	LEFT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1567460/009	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-007	RIGHT MAIN LANDING GEAR SHOCK STRUT (LOCKING ACT) PIN 2317-1109-003 1567460/015	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-008	LEFT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1569465/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-008	RIGHT MAIN LANDING GEAR SHOCK STRUT (TRAILING) BOLT 2317-1126-003 1569465/007	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00	LEFT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-10-00	RIGHT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-10-01	LEFT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-405 00317 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-10-01	RIGHT MAIN LANDING GEAR LEG STRUT ASSY 2317-1100-406 00321 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-100	LEFT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-405 00322 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-100	RIGHT MAIN LANDING GEAR TRAILING ARM ASSY 2317-1500-406 00325 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-101	LEFT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1574118/003 REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		15300
32-101	RIGHT MAIN LANDING GEAR TRAILING ARM WHEEL AXLE 2317-1502-003 1574118/004 REF: See Workcard	MOS HRS/MSC AFL	15300	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		15300

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-102	LEFT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1567849/002	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-102	RIGHT MAIN LANDING GEAR TRAILING ARM AXLE 2317-1503-005 1567849/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-103	LEFT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1559033/018	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-103	RIGHT MAIN LANDING GEAR TRAILING ARM BOLT 2317-1509-001 1559033/017	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-104	LEFT MAIN LANDING GEAR TRAILING ARM 2317-1513-501 1574264/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-105	RIGHT MAIN LANDING GEAR TRAILING ARM 2317-1513-502 1575180/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-106	LEFT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1565266/014	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-106	RIGHT MAIN LANDING GEAR TRAILING ARM JACKING PIN 2317-1505-001 1565266/020	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-001 (s)	GENERAL VISUAL INSPECTION OF MAIN LANDING GEAR PKG 2 REF: AMM 32-11-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-11-00-002	RESTORATION (OVERHAUL) OF LEFT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			30-OCT-2015 0	30-OCT-2025 12000	29-NOV-2025 12030
32-11-00-002	RESTORATION (OVERHAUL) OF RIGHT MAIN LANDING GEAR PN SN-UNKNOWN REF: AMM 32-11-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			30-OCT-2015 0	30-OCT-2025 12000	29-NOV-2025 12030
32-11-00-003 (s)	LUBRICATION OF MAIN LANDING GEAR PKG 2 REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-11-03-004 (s)	SERVICING OF MAIN LANDING GEAR SHOCK ABSORBER PKG 2 REF: AMM 12-14-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-20-01	NOSE LANDING GEAR PN SN-UNKNOWN REF: AMM 32-21-00	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
32-200	LEFT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00685 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
32-200	RIGHT MAIN LANDING GEAR MLG SHOCK ABSORBER 2317-3000-403 00686 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-201	LEFT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1580471/002	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-201	RIGHT MAIN LANDING GEAR SHOCK ABSORBER CYLINDER 2317-3011-001 1580232/003	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-202	LEFT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1559640/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-202	RIGHT MAIN LANDING GEAR SHOCK ABSORBER SLIDING TUBE 2317-3021-001 1575084/001	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-203	LEFT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1567475/009	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-203	RIGHT MAIN LANDING GEAR SHOCK ABSORBER BEARING 2317-3001-003 1567475/002	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-204	LEFT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1565871/027	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								
32-204	RIGHT MAIN LANDING GEAR SHOCK ABSORBER NUT 2317-3004-001 1565871/029	MOS HRS/MSC AFL	16800	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		16800
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-001 (s)	GENERAL VISUAL INSPECTION OF NOSE LANDING GEAR PKG 2 REF: AMM 32-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-21-00-002	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR PN SN-UNKNOWN REF: AMM 32-21-00	MOS HRS/MSC AFL	120 12000	+30d/-30d +30/-30			30-OCT-2015 0	30-OCT-2025 12000	29-NOV-2025 12030
32-21-00-003 (s)	LUBRICATION OF NOSE LANDING GEAR PKG 2 REF: AMM 12-21-00	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-21-02	NLG RETRACTION ACTUATOR 2117-1000-401 00336 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
32-21-03	NLG DOWNLOCK ACTUATOR 2117-2000-401 00339 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
32-21-05-004 (s)	SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER PKG 2 REF: AMM 12-14-03	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-21-06-005 (s)	VISUAL CHECK OF NOSE LANDING GEAR SHIMMY DAMPER PKG 2 REF: AMM 32-21-06	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-23-03	NLG DOOR - TORQUE TUBE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-300	LEFT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3000-409 00706 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-300	RIGHT MAIN LANDING GEAR MLG LOCKING ACTUATOR 2117-3000-409 00707 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-301	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3034-501 1559580/004 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-301	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CYLINDER 2117-3034-501 1559580/003 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-302	LEFT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1559184/008 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-302	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR BEARING PISTON 2117-3001-003 1559184/009 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-303	LEFT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3027-901 15033 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-303	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR FINGER 2117-3027-901 15042 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-304	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 77001/0028	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-304	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD 2117-3008-901 77001/0023	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-305	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1572177/015	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-305	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING PISTON 2117-3009-007 1572177/006	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-306	LEFT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-003 1565473/011	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-306	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR PIN 2117-3019-003 1565473/012	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-307	LEFT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1554001/008	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								
32-307	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR LOCKING SLEEVE 2117-3007-003 1554001/005	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
LIFE LIMIT	REF: See Workcard								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-308	LEFT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1579991/002 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-308	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR STOP 2117-3011-001 1579991/005 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-309	LEFT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1571900/002 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-309	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR CAP BEARING 2117-3013-001 1571900/004 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-31-01	LANDING GEAR CONTROL LEVER 827101-13 0151 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				30-OCT-2015 0 0	
32-31-04	CENTER FUSELAGE LANDING GEAR SELECTOR VALVE 7342-1 0347T REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				30-OCT-2015 0 0	
32-31-05	LH MLG UPLOCK BOX ASSY 2617-1000-401 00654 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				30-OCT-2015 0 0	
32-31-05	NLG UPLOCK BOX ASSY 2617-1000-401 00656 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0				30-OCT-2015 0 0	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-31-05	RH MLG UPLOCK BOX ASSY 2617-1000-402 00326 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-310	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1565474/005 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-310	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (ROD) NUT 2117-3015-001 1565474/011 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			(EBT)		12008
32-311	LEFT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00649 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10508
32-311	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR ROD END MTMKS14ALGA1 00661 REF: See Workcard	MOS HRS/MSC AFL	10500	TSN:0 TSN:0 TSN:0			(EBT)		10508
+ 32-313	LEFT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		28000
+ 32-313	RIGHT MAIN LANDING GEAR LOCKING ACTUATOR (CYLINDER) NUT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	28000	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		28000
32-35-00-001	FUNCTIONAL CHECK OF LANDING GEAR EMERGENCY EXTENSION SYSTEM REF: AMM 32-35-00	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30	10		20-OCT-2017 400:54 200	30-OCT-2019 1600:54	29-NOV-2019 1630:54

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-35-00-002	GENERAL VISUAL INSPECTION OF EMERGENCY EXTENSION SYSTEM LINKAGES	MOS	24	+30d/-30d					
AIRWORTHINESS	REF: AMM 32-35-00	HRS/MSC AFL	1200	+30/-30		10	20-OCT-2017 400:54 200	30-OCT-2019 1600:54	29-NOV-2019 1630:54
32-35-02	CENTER FUSELAGE FREE FALL VALVE	MOS							
	7343-2	HRS/MSC	O/C				30-OCT-2015		
	0338T	AFL		TSN:0			0		
	REF: See Workcard			TSN:0			0		
32-400	NOSE LANDING GEAR SHOCK STRUT	MOS							
	2317-5100-403	HRS/MSC	O/C				30-OCT-2015		
	00331	AFL		TSN:0			0		
	REF: See Workcard			TSN:0			0		
32-401	NOSE LANDING GEAR SHOCK STRUT AXLE BOLT	MOS							
	2310-1144-005	HRS/MSC					30-OCT-2015		
	00394	AFL	11200	TSN:0			0		
LIFE LIMIT	REF: See Workcard			TSN:0			0	11200	
32-402	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER BOLT	MOS							
	2310-1173-001	HRS/MSC					30-OCT-2015		
	1565146/006	AFL	11200	TSN:0			0		
LIFE LIMIT	REF: See Workcard			TSN:0			0	11200	
32-403	LEFT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN	MOS							
	2317-5105-001	HRS/MSC					30-OCT-2015		
	1566144/014	AFL	11200	TSN:0			0		
LIFE LIMIT	REF: See Workcard			TSN:0			0	11200	
32-403	RIGHT NOSE LANDING GEAR SHOCK STRUT PINTLE PIN	MOS							
	2317-5105-001	HRS/MSC					30-OCT-2015		
	1566144/011	AFL	11200	TSN:0			0		
LIFE LIMIT	REF: See Workcard			TSN:0			0	11200	
32-404	NOSE LANDING GEAR SHOCK STRUT MAIN FITTING	MOS							
	2317-5301-503	HRS/MSC					30-OCT-2015		
	1570549/001	AFL	11200	TSN:0			0		
LIFE LIMIT	REF: See Workcard			TSN:0			0	11200	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-405	NOSE LANDING GEAR SHOCK STRUT SHIMMY DAMPER 2117-4000-403 00348 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-406	NOSE LANDING GEAR SHOCK STRUT WHEEL AXLE 2317-5101-001 1565159/007 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-407	LOWER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1566064/018 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-407	UPPER NOSE LANDING GEAR SHOCK STRUT TORQUE LINK 2317-5201-001 1566064/005 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-408	NOSE LANDING GEAR SHOCK STRUT DRAG BRACE PIN 2317-6003-001 1569472/002 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-409	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK AXLE 2310-1165-001 1548249/014 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-41-00	BRAKE CONTROL UNIT DAP00100-10 343450406 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-JUN-2018 581:30 283		
32-41-00-001 (s)	FUNCTIONAL CHECK OF MAIN BRAKE SYSTEM PKG 50 REF: AMM 32-41-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-01	BRAKE CONTROL UNIT TRAY DAP00134-01 1150 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-41-02	LH BRAKE PEDAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-41-02	RH BRAKE PEDAL TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-41-02-001 (s)	OPERATIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 50 REF: AMM 32-41-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
32-41-02-001 (s)	OPERATIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 50 REF: AMM 32-41-02	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
32-41-02-002 (s)	FUNCTIONAL CHECK LH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-41-02-002 (s)	FUNCTIONAL CHECK RH BRAKE PEDAL TRANSDUCER PKG 2 REF: AMM 32-41-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			PKG 09-NOV-2018 637:12 307		
32-41-06	LH MLG WHEEL SPEED TRANSDUCER DAP00103-01 232PC REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-06	RH MLG WHEEL SPEED TRANSDUCER DAP00103-01 234PE REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-41-07	BRAKE CONTROL MODULE DAP00101-02 195PF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-410	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK LOCK PIN 57675-1 00806 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-411	NOSE LANDING GEAR SHOCK STRUT TORQUE LINK BOLT 2310-1183-001 00349 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-412	NOSE LANDING GEAR SHOCK STRUT STEERING BELLCRANK 2317-5191-001 1579088/004 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-43-00-001 (s)	FUNCTIONAL CHECK OF EMERGENCY/ PARKING BRAKE SYSTEM PKG 50 REF: See Workcard	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
32-43-01-001 (s)	GENERAL VISUAL INSPECTION OF EMERGENCY/PARKING BRAKE SYSTEM PKG 50 REF: AMM 32-43-00	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
32-43-02	PRESSURE SWITCH DAP00108-01 075PB REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-43-04	EMERGENCY/PARKING BRAKE ACCUMULATOR DAP00106-01 339 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-05	EMERGENCY/PARKING BRAKE VALVE DAP00107-01 102PD REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-06	PRESSURE TRANSDUCER DAP00109-01 8067-12-17 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-08	THERMAL RELIEF VALVE DAP00110-01 402 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-10	EMERGENCY/PARKING BRAKE SUPPLY CHECK VALVE DAP00202-01 390 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-11	FORWARD FUSELAGE 2 WAY 2 POSITION SHUT-OFF VALVE 2216-0001-401 00679 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-43-11-001	OPERATIONAL CHECK OF EMERGENCY/PARKING BRAKE HYDRAULIC LINE SHUT-OFF VALVE REF: AMM 32-43-11	MOS HRS/MSC AFL	600	+30/-30	18:30		23-JUN-2018 581:30 283	1200	1230
AIRWORTHINESS									
32-45-00	LH MAIN WHEEL AND TIRE ASSY 505-19517-611 5169PF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			09-APR-2018 528:36 256		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-00	NOSE WHEEL AND TIRE ASSY 505-19601-605 5048RH REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-FEB-2019 688:18 333		
32-45-00	RH MAIN WHEEL AND TIRE ASSY 505-19517-611 5120RJ REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			13-APR-2018 533:07 256		
32-45-01	LEFT MAIN WHEEL DAP00098-02 5169PF REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:1 TSO:0 TSO:0			09-APR-2018 528:36 256		
32-45-01	RIGHT MAIN WHEEL DAP00098-02 5120RJ REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:6 TSR:0 TSR:0			13-APR-2018 533:07 256		
32-45-01-002	SPECIAL DETAIL INSPECTION LH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5169PF REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				09-APR-2018 528:36 256		
32-45-01-002	SPECIAL DETAIL INSPECTION RH MAIN WHEEL AND TIRE ASSY (NDT) OF MAIN LANDING GEAR WHEEL ASSEMBLY 505-19517-611 5120RJ REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C						
+ 32-45-01-003	RESTORATION (OVERHAUL) OF LH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5169PF REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500				09-APR-2018 528:36 256	1756	
32-45-01-003	RESTORATION (OVERHAUL) OF RH MAIN LANDING GEAR WHEEL ASSEMBLY DAP00098-02 5120RJ REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C				(EBT)		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-02	LEFT MAIN WHEEL TIRE 258K63-2 80272706 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-APR-2018 528:36 256		
32-45-02	RIGHT MAIN WHEEL TIRE 258K63-2 61352696 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2018 533:07 256		
32-45-03	LH MLG HUB CAP DAP00131-02 012PG REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-45-03	RH MLG HUB CAP DAP00131-02 024PH REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-45-11	NOSE WHEEL DAP00099-02 5048RH REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			23-FEB-2019 688:18 333		
32-45-11-002	SPECIAL DETAIL INSPECTION NOSE WHEEL AND TIRE ASSY (NDT) OF NOSE LANDING GEAR WHEEL ASSEMBLY 505-19601-605 5048RH REF: AMM 32-45-00	MOS HRS/MSC AFL	O/C				23-FEB-2019 688:18 333		
+ 32-45-11-003	RESTORATION (OVERHAUL) OF NOSE LANDING GEAR WHEEL ASSEMBLY DAP00099-02 5048RH REF: AMM 32-45-00	MOS HRS/MSC AFL	T/C 1500				23-FEB-2019 688:18 333		1833
32-45-12	NOSE TIRE 156K23B1 72852836 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-FEB-2019 688:18 333		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-45-21	LH MLG CARBON BRAKE ASSY DAP00097-03 5193PE REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-45-21	RH MLG CARBON BRAKE ASSY DAP00097-03 5192PE REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-500	NOSE LANDING GEAR SHOCK ABSORBER 2317-5170-403 00336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-501	NOSE LANDING GEAR SHOCK ABSORBER STEEL FORK 2317-5227-501 1565098/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-502	NOSE LANDING GEAR SHOCK ABSORBER LOWER BEARING 2317-5113-005 1567595/014 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-503	NOSE LANDING GEAR SHOCK ABSORBER TURNING CYLINDER 2317-5237-501 1570564/001 REF: GENERIC NO REF	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-600	NOSE LANDING GEAR DRAG BRACE 2317-6000-403 00333 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-601	NOSE LANDING GEAR UPPER DRAG BRACE 2317-6114-501 1551116/004 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-602	NOSE LANDING GEAR LOWER DRAG BRACE 2317-6201-001 1565877/008 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-603	LEFT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1565461/004 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-603	RIGHT NOSE LANDING GEAR DRAG BRACE PINTLE PIN 2317-6001-001 1565461/006 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-604	NOSE LANDING GEAR DRAG BRACE PIN PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-61-01	LH WING PROXIMITY SWITCH 80-057-01 42127 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 1 LEFT MLG PROXIMITY SWITCH 80-057-01 42179 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 1 NLG PROXIMITY SWITCH 80-057-01 41606 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 1 RIGHT MLG PROXIMITY SWITCH 80-057-01 42178 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-61-01	NO. 2 LEFT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 2 NLG PROXIMITY SWITCH 80-057-01 42125 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 2 RIGHT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 3 LEFT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	NO. 3 RIGHT MLG PROXIMITY SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-61-01	RH WING PROXIMITY SWITCH 80-057-01 42130 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-700	NOSE LANDING GEAR LOCKING STAY 2317-6500-403 00327 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
32-701	NOSE LANDING GEAR UPPER LOCKING STAY 2317-6521-003 1567149/001 REF: See Workcard	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
LIFE LIMIT			11200	TSN:0			0		11200

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-702	NOSE LANDING GEAR LOWER LOCKING STAY 2317-6531-001 1577336/003 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-703	LOWER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1570368/016 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
32-703	UPPER NOSE LANDING GEAR LOCKING STAY BOLT 2310-1734-001 1570368/017 REF: See Workcard	MOS HRS/MSC AFL	11200	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		11200
CHAPTER 33 LIGHTS									
33-01-01	OVERHEAD LIGHTS CONTROL PANEL 441-44443-001 1142 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-12-01	COCKPIT DIMMER 81-01760-002 0760 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-12-02	INSC ILLUM - TEST PANEL 441-42631-003 1322 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-31-02	NOSE (WITH/WITHOUT FDR) W001,ELECTRICAL HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-42-01	LH LWR FWD TAXI LIGHT ASSY 81017-3 000501 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-42-01	RH LWR FWD TAXI LIGHT ASSY 81017-4 000483 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-47-01	LEFT LANDING LIGHT ASSY 81017-5 000503 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-47-01	RIGHT LANDING LIGHT ASSY 81017-6 000513 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-48-00	LEFT NO. 1 NAVIGATION LIGHT 84004-7 000819 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-48-00	LEFT NO. 2 NAVIGATION LIGHT 84075-1 000199 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-48-00	RIGHT NO. 1 NAVIGATION LIGHT 84004-7 000818 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-48-00	RIGHT NO. 2 NAVIGATION LIGHT 84075-2 000219 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-48-00-001 (s)	DISCARD LEFT NO. 1 NAVIGATION LIGHT 84004-7 PKG 65 000819 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-48-00-001 (s)	DISCARD LEFT NO. 2 NAVIGATION LIGHT 84075-1 PKG 65 000199 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-001 (s)	DISCARD RIGHT NO. 1 NAVIGATION LIGHT 84004-7 PKG 65 000818 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-001 (s)	DISCARD RIGHT NO. 2 NAVIGATION LIGHT 84075-2 PKG 65 000219 REF: AMM 33-48-00	MOS HRS/MSC AFL	12000	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION LEFT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 1 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-48-00-002 (s)	GENERAL VISUAL INSPECTION RIGHT NO. 2 NAVIGATION LIGHT PKG 20 REF: AMM 33-48-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-49-00	NO. 1 STROBE LIGHT 84036-3 000410 REF: See Workcard	MOS HRS/MSC AFL	O/C			TSN:0 TSN:0 TSN:0	30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-49-00	NO. 2 STROBE LIGHT 84036-4 000430 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-49-00-001 (s)	DISCARD NO. 1 STROBE LIGHT 84036-3 PKG 60 000410 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800	+30/-30			PKG 30-OCT-2015 0 0		
33-49-00-001 (s)	DISCARD NO. 2 STROBE LIGHT 84036-4 PKG 60 000430 REF: AMM 33-49-00	MOS HRS/MSC AFL	7800	+30/-30			PKG 30-OCT-2015 0 0		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 1 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-49-00-002 (s)	GENERAL VISUAL INSPECTION NO. 2 STROBE LIGHT PKG 20 REF: AMM 33-49-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		
33-52-01	LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001444 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-NOV-2018 637:12 307		
33-52-01	RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001126 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-NOV-2018 637:12 307		
33-52-01-001	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001444 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-52-01-001	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH BE AEROSPACE BATTERY) 6450LS-00 001126 REF: AMM 33-52-01	MOS HRS/MSC AFL	12	+30d/-30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
33-52-01-002	FUNCTIONAL CHECK LH REAR EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001444 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-002	FUNCTIONAL CHECK RH FWD EMERGENCY LIGHT BATTERY (AIRCRAFT WITH DLE BATTERY) 6450LS-00 001126 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF LH REAR EMERGENCY LIGHT BATTERY 6450LS-00 001444 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-01-003	DISCARD OF RH FWD EMERGENCY LIGHT BATTERY 6450LS-00 001126 REF: AMM 33-52-01	MOS HRS/MSC AFL	N/A						
33-52-05	SELF-ILLUMINATED UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
33-52-17-001 (s)	OPERATIONAL CHECK OF INERTIAL SWITCH (AIRCRAFT WITH INERTIAL SWITCH INSTALLED) PKG 12 REF: AMM 33-52-17	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 20-OCT-2017 400:54 200		
CHAPTER 34	NAVIGATION								
34-00-01	ACSS TRANSPONDER 7510700-951 RCE02392 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-00-02	TRANSPONDER RF RELAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-00-03	NO.1 IASP SMART PROBE 2015L-4B 0888 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-00-03	NO.2 IASP SMART PROBE 2015L-4B 0889 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-00-04	SD CARD DATABASE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-10-01	RADIO ALTIMETER 066-01153-0101 KRA405B-16779 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-10-02	LEFT RADIO ALTIMETER TRANSMIT ANTENNA S67-2002-45 553-7169 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-10-02	RIGHT RADIO ALTIMETER RECEIVE ANTENNA S67-2002-45 553-7176 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-11-00	IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT C16786DA01 C16786014460 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-001	FUNCTIONAL CHECK IESI - INTEGRATED ELECTRONIC STANDBY INSTRUMENT OF INTEGRATED ELECTRONIC STANDBY INSTRUMENT NOTE: ACCOMPLISH THIS REQUIREMENT AFTER CLEANING PROCEDURE (34-11-02-001) C16786DA01 C16786014460 REF: AMM 34-11-00	MOS HRS/MSC AFL	24	+30d/-30d		-80	20-OCT-2017 400:54 200	01-AUG-2019	31-AUG-2019
34-11-02	PITOT/STATIC PROBE 0856UT4 294671 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-11-02-001	RESTORATION (CLEANING) OF PITOT/STATIC PROBE NOTE: ACCOMPLISH THIS REQUIREMENT PRIOR TO THE FUNCTIONAL CHECK (34-11-00-001) 0856UT4 294671 REF: AMM 34-11-02	MOS HRS/MSC AFL	24	+30d/-30d		10	20-OCT-2017 400:54 200	30-OCT-2019	29-NOV-2019
34-15-00-001 (s)	FUNCTIONAL CHECK OF AIR DATA SYSTEM PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 20-OCT-2017 400:54 200		
34-15-00-002 (s)	SPECIAL DETAILED INSPECTION OF RVSM CRITICAL REGION (SKIN) FOR WAVINESS PKG 81 REF: AMM 34-15-00	MOS HRS/MSC AFL	24	+30d/-30d			PKG 20-OCT-2017 400:54 200		
34-15-00-003	DETAILED INSPECTION OF IASP PKG 81 REF: AMM 34-15-07	MOS HRS/MSC AFL	24	+30d/-30d		-80	20-OCT-2017 400:54 200	01-AUG-2019	31-AUG-2019
34-20-01	LH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42030305 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-20-01	RH GRS-77 ATTITUDE AND HEADING REFERENCE SYSTEM 011-00868-10 42030256 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-20-02	LEFT MAGNETOMETER 011-00870-10 1CM015533 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-20-02	RIGHT MAGNETOMETER 011-00870-10 1CM015414 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-23-00	MAGNETIC COMPASS KCA0120W BM7390315 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-23-00-001	FUNCTIONAL CHECK MAGNETIC COMPASS OF STANDBY COMPASS KCA0120W BM7390315 REF: AMM 34-23-00	MOS HRS/MSC AFL	24	+30d/-30d	-19		20-OCT-2017 400:54 200	01-OCT-2019	31-OCT-2019
34-30-01	LEFT VOR/LOC 2 & 3 BLADE ANTENNA S65-247170 173-4617 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-30-01	RIGHT VOR/LOC 2 AND 3 ANTENNA BLADE S65-247170 173-4618 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-01	GDL-69A SATELLITE WEATHER AND RADIO RECEIVER 011-00987-00 47768805 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-40-02	AFT GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 13078 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-02	FWD GA 37 GPS WAAS & SATELLITE WEATHER AND RADIO ANTENNA 013-00245-00 12680 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-03	WEATHER RADAR RECEIVER/TRANSMITTER ANTENNA 011-01768-00 1DP006190 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-04	TCAS II UNIT 9003500-55905 TSE02969 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-05	TCAS II TOP ANTENNA 7514060-902 ANE46315 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-40-07	NOSE WEATHER RADAR ANTENNA 117-00254-01 1010 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-43-02	LOWER TCAS L BAND ANTENNA S65-5366-7L 261-119271 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-02	BOTTOM DME/XPDR/TCAS NON-DIRECTIONAL ANTENNA S65-5366-7L 261-119095 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-02	TOP XPDR L BAND ANTENNA S65-5366-7L 261-119347 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-03	KN 63 DISTANCE MEASURING UNIT 066-01070-0001 38358 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-05	PHASING COUPLER SSPD-113-10 8306 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-06	MARKER BEACON ANTENNA S35-1000-2 102-11472 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-07	MARKER BEACON ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-08	VOR/LOC/GS ANTENNA SPLITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-09	VOR/LOC/GS ANTENNA RF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-10	GSR 56 IRIDIUM UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-50-11	IRIDIUM SATCOM ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-12	GDL 59 DATALINK MANAGEMENT UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-13	WI-FI - DATALINK ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-14	ADF ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-50-15	ADF UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-51-02	NO. 1 DME L BAND ANTENNA S65-5366-7L 261-119359 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-52-00	NO. 1 TRANSPONDER 7510700-951 RCE02392 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-52-00	NO. 2 TRANSPONDER 7510700-951 RCE02391 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-52-00-001	FUNCTIONAL CHECK OF NO. 1 TRANSPONDER SYSTEM 7510700-951 RCE02392 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				20-OCT-2017	20-OCT-2019	
34-52-00-001	FUNCTIONAL CHECK OF NO. 2 TRANSPONDER SYSTEM 7510700-951 RCE02391 REF: AMM 34-52-00	MOS HRS/MSC AFL	24				20-OCT-2017	20-OCT-2019	
34-52-04	LOWER COAXIAL UNIT D2-729B005 587287 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-52-04	UPPER COAXIAL UNIT D2-729B005 587167 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-53-01	ADF MOUNTING TRAY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
34-60-03	FLIGHT MANAGEMENT SYSTEM PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 35 OXYGEN									
35-00-00-001	FUNCTIONAL CHECK OF OXYGEN SYSTEM PRESSURE LINES FOR LEAKAGE REF: AMM 35-00-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2021 2437:12	09-DEC-2021 2467:12
35-01-00-001 (s)	FUNCTIONAL CHECK OF CREW OXYGEN PRESSURE INDICATION PKG 84 REF: AMM 35-01-02	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-01-02	OXYGEN CYLINDER TRANSDUCER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-05	CREW OXYGEN SYSTEM LOW PRESSURE SWITCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-06	OXYGEN SYSTEM CONTROL PANEL 441-40945-002 0710 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-07	COCKPIT SENSOR P24099 0789 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-08	PAX LOW PRESSURE OXYGEN SYSTEM SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-09	ALTITUDE COMPENSATING REGULATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-01-10	LOW PRESSURE OXYGEN VALVE 4421132-109 00742 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-02-01	OXYGEN CYLINDER 4441122-077 696754402 REF: See Workcard	MOS HRS/MSC AFL	C/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-02-01-001	FUNCTIONAL CHECK OF OXYGEN CYLINDER ASSEMBLY 4441122-077 696754402 REF: AMM 35-02-01	MOS HRS/MSC AFL	60				01-JAN-2015	01-JAN-2020	
35-02-01-003	DISCARD OF OXYGEN CYLINDER 4441122-077 696754402 REF: AMM 35-02-01 LIFE LIMIT Manufacture Date: 01-JUL-2014	MOS HRS/MSC AFL	180				01-JUL-2015	01-JUL-2030	
35-02-05	OXYGEN PRESSURE REGULATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-11-00-001	OPERATIONAL CHECK OF CREW OXYGEN MASK AND STOWAGE BOX REF: AMM 35-11-02	MOS HRS/MSC AFL	12 600	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2019 1237:12	09-DEC-2019 1267:12
35-11-01	COPILOT OXYGEN MASK STOWAGE BOX 1186F6-23 01406 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-11-01	PILOT OXYGEN MASK STOWAGE BOX 1186F6-23 01402 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-11-02	LEFT CREW OXYGEN MASK 174232-93 37947 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
35-11-02	RIGHT CREW OXYGEN MASK 174232-93 37961 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-11-02-001	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 37947 REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2021 2437:12	09-DEC-2021 2467:12
35-11-02-001	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 37961 REF: AMM 35-11-02	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2021 2437:12	09-DEC-2021 2467:12
35-11-02-002	RESTORATION (OVERHAUL) OF LEFT CREW OXYGEN MASK 174232-93 37947 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			01-JUL-2015 0	01-JUL-2021 3600	31-JUL-2021 3630
35-11-02-002	RESTORATION (OVERHAUL) OF RIGHT CREW OXYGEN MASK 174232-93 37961 REF: AMM 35-11-02	MOS HRS/MSC AFL	72 3600	+30d/-30d +30/-30			01-JUL-2015 0	01-JUL-2021 3600	31-JUL-2021 3630
35-11-02-003	DETAILED VISUAL INSPECTION OF LEFT CREW OXYGEN MASK 174232-93 37947 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				30-OCT-2015 0 0		
35-11-02-003	DETAILED VISUAL INSPECTION OF RIGHT CREW OXYGEN MASK 174232-93 37961 REF: AMM 35-11-02	MOS HRS/MSC AFL	N/A				30-OCT-2015 0 0		
35-11-04-001 (s)	DETAILED INSPECTION OF CREW GOGGLES - (AIRCRAFT WITH SMOKE GOGGLES INSTALLED) PKG 82 REF: AMM 35-11-04	MOS HRS/MSC AFL	36	+1m/-1m			PKG 09-NOV-2018 637:12 307		
35-21-00-001	FUNCTIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN AUTO MODE REF: AMM 35-21-00	MOS HRS/MSC AFL	36 1800	+30d/-30d +30/-30			09-NOV-2018 637:12 307	09-NOV-2021 2437:12	09-DEC-2021 2467:12
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-21-00-002	OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM IN MANUAL MODE	MOS	36	+30d/-30d			09-NOV-2018	09-NOV-2021	09-DEC-2021
AIRWORTHINESS	REF: AMM 35-21-00	HRS/MSC AFL	1800	+30/-30			637:12 307	2437:12	2467:12
35-21-01	AFT ONE MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			30-OCT-2015		
	4411071-112	HRS/MSC	O/C	TSN:0			0		
	REF: See Workcard	AFL		TSN:0			0		
35-21-01	FWD ONE MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			30-OCT-2015		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: See Workcard								
35-21-01	NO. 1 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			30-OCT-2015		
	4411072-112	HRS/MSC	O/C	TSN:0			0		
	4411072-112-00056	AFL		TSN:0			0		
	REF: See Workcard								
35-21-01	NO. 2 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			30-OCT-2015		
	4411072-112	HRS/MSC	O/C	TSN:0			0		
	4411072-112-00057	AFL		TSN:0			0		
	REF: See Workcard								
35-21-01	NO. 3 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			30-OCT-2015		
	4411072-112	HRS/MSC	O/C	TSN:0			0		
	4411072-112-00058	AFL		TSN:0			0		
	REF: See Workcard								
35-21-01	NO. 4 TWO MASK DEPLOYMENT OXYGEN CONTAINER	MOS		TSN:0			09-NOV-2018		
	4411072-112	HRS/MSC	O/C	TSN:0			637:12		
	4411072-112-00638	AFL		TSN:0			307		
	REF: See Workcard								
35-21-01-001 (s)	DETAILED INSPECTION OF PASSENGER OXYGEN MASKS	MOS	36	+1m/-1m			09-NOV-2018		
	PKG 82	HRS/MSC					637:12		
	REF: AMM 35-21-01	AFL					307		

CHAPTER 36 PNEUMATIC

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-01-01	PNEUMATIC INSC ILLUM PANEL 441-42633-002 1328 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-01	LEFT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-3 0355 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-01	RIGHT PYLON BLEED PRESSURE REGULATING SHUTOFF VALVE RYLB-53505-4 0347 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-01-001 (s)	RESTORATION (CLEANING) OF BLEED PRESSURE REGULATING SHUTOFF VALVE (PRSOV) FILTER PKG 50 REF: AMM 36-11-01	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-11-01-002 (s)	OPERATIONAL CHECK OF BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-00	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
36-11-02-001 (s)	DETAILED INSPECTION OF BLEED LINE WATER DRAINS PKG 12 REF: AMM 36-11-02	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 20-OCT-2017 400:54 200		
36-11-03	AMS CONTROLLER SYLZ-53632-205 0403A REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-04	NO. 1 ENGINE FAN AIR VALVE RYLB-53527-1 0467 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-04	NO. 2 ENGINE FAN AIR VALVE RYLB-53527-1 0474 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-04-001 (s)	RESTORATION (CLEANING) OF FAN-AIR VALVE (FAV) FILTER PKG 50 REF: AMM 36-11-04	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-11-05	LH INCONEL 625 BLEED PRE-COOLER 10965000-105 T0322 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-05	RH INCONEL 625 BLEED PRE-COOLER 10964000-105 T0320 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-06	CROSS BLEED VALVE RYLB-53506-1 0336 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-06-001 (s)	OPERATIONAL CHECK OF CROSS-BLEED MANUAL SHUT-OFF FUNCTION PKG 1 REF: AMM 36-11-06	MOS HRS/MSC AFL	600	+30/-30			PKG 23-JUN-2018 581:30 283		
36-11-06-002 (s)	RESTORATION (CLEANING) OF CROSS-BLEED VALVE (XBV) FILTER PKG 50 REF: AMM 36-11-06	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-11-07	NO. 1 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 8212-12-137 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-07	NO. 2 BLEED PRESSURE TRANSDUCER APTE-479F-1000-200G 8212-12-139 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-08	NO. 1 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTY5791 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-08	NO. 2 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTY5793 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-08	NO. 3 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTY5975 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-08	NO. 4 BLEED TEMPERATURE SENSOR 8TJ107DAJ1 DTY5986 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 1 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 2 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 3 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
36-11-08-001 (s)	FUNCTIONAL CHECK NO. 4 BLEED AIR TEMPERATURE SENSOR PKG 50 REF: AMM 36-11-08	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
36-21-01-001	OPERATIONAL CHECK OF BLEED LEAKAGE SENSORS REF: AMM 36-21-01	MOS HRS/MSC AFL	6000	+30/-30			30-OCT-2015 0 0	6000	6030
AIRWORTHINESS									
CHAPTER 38 WATER/WASTE									
38-33-00	TOILET ASSY RTA9147-01 03330201 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				02-NOV-2016 159 90		
38-33-07	WASTE DRAIN VALVE 0218-0032-1 252638 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
CHAPTER 44 CABIN SYSTEMS									
44-12-07	3-CHANNEL AUDIO AMPLIFIER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
44-21-03	DC-DC CONVERTER 35-192-00 327 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
44-21-09	IFE INSC ILLUM PANEL 441-44843-001 1133 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-21-11	XM RECEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-13	XM HEAD CONTROL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-15	AUDIO VOLUME CONTROLLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-16	PAX 1 GMA 36 REMOTE AUDIO CONTROLLER 011-01793-00 1HF006146 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-16	PAX 2 GMA 36 REMOTE AUDIO CONTROLLER 011-01793-00 1HF006329 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-17	IR RECEIVER WITH CONNECTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-19	IR REMOTE CONTROLLER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-21	WIRELESS AUDIO TRANSMITTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
44-21-23	NO. 1 WIRELESS HEADPHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-23	NO. 2 WIRELESS HEADPHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-21-25	HEADPHONE DISTRIBUTION AMPLIFER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-22-01	CABIN ENTERTAINMENT - MOVING MAP/CD/DVD PLAYER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-22-03	10.4 INCH FOLD DOWN MONITOR- PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-32-01	ATG5000 TRANSCEIVER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-32-03	AIRCELL CONFIGURATION MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
44-32-05	AIRCELL AXCESS (CTR) CABIN TELECOMMUNICATIONS ROUTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
442127-0101	LH NO. 1 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
442127-0102	RH NO. 2 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
442127-0103	LH NO. 3 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
442127-0104	RH NO. 4 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
442127-0105	LH NO. 5 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
442127-0106	RH NO. 6 AUDIO CONTROL JACK PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 45 CENTRAL MAINT SYSTEM									
45-45-00-970-803	PERFORM CMC DOWNLOAD	MOS HRS/MSC AFL	A/R				15-FEB-2016 50:27 31		
CHAPTER 52 DOORS									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-00-00	KEY LOCK KIT 505-09736-901 8MA000499CM REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
52-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
52-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR STRUCTURE PKG 84 REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
52-10-01-01-901	GENERAL VISUAL INSPECTION OF DOOR, FUSELAGE HINGES AND FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
52-10-01-02-901	GENERAL VISUAL INSPECTION OF FRAMES, BEAMS AND INTERCOSTALS. MAIN DOOR STRUCTURE - INTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
52-10-01-02-902	DETAILED VISUAL INSPECTION OF DOOR SKIN, VENT FLAP SKIN, SKIN/VENT FLAP SKIN AND ALL SKIN FASTENERS. MAIN DOOR STRUCTURE - EXTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
52-10-02-01-901	GENERAL VISUAL INSPECTION OF LATCH PINS AND LATCH BOX. MAIN DOOR LATCH MECHANISM - EXTERNAL REF: NDT PART 5 52-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
52-10-20-001 (s)	GENERAL VISUAL INSPECTION OF MAIN DOOR RUBBER SEAL PKG 12 REF: AMM 52-10-20	MOS HRS/MSC AFL	24 1200	+30d/-30d +30/-30			PKG 20-OCT-2017 400:54 200		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-11-00-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF MAIN DOOR LOCKING AND ACTUATING MECHANISM PKG 41 REF: AMM 52-11-00	MOS HRS/MSC AFL	48 3000	+30d/-30d +30/-30			PKG 30-OCT-2015 0 0		
52-11-00-003 (s)	FUNCTIONAL CHECK OF MAIN-DOOR INTERNAL HANDLE STRENGTH PKG 2 REF: AMM 52-11-23	MOS HRS/MSC AFL	12 600	+30d/-30d			PKG 09-NOV-2018 637:12 307		
52-13-21-001 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM GEAR SECTOR (ACFT WITH GEAR SECTOR P/N 500-09892-005 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-21	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
52-13-22	MAIN DOOR BALANCING MECHANISM PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
52-13-22-001	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLE PN SN-UNKNOWN REF: AMM 52-13-22	MOS HRS/MSC AFL	O/C				30-OCT-2015 0 0		
52-13-22-004 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM CABLES PKG 40 REF: AMM 52-13-22	MOS HRS/MSC AFL	3000	+30/-30			PKG 30-OCT-2015 0 0		
52-13-23-001 (s)	DISCARD OF MAIN DOOR BALANCING MECHANISM PINION SHAFT (ACFT WITH PINION SHAFT P/N 500-09890-001 INSTALLED) PN PKG 50 SN-UNKNOWN REF: AMM 52-13-23	MOS HRS/MSC AFL	6000	+30/-30			PKG 30-OCT-2015 0 0		
52-20-00	EMERGENCY DOOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR STRUCTURE PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 52-20-00	HRS/MSC AFL							
52-20-01-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR STRUCTURE PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: See Workcard	HRS/MSC AFL							
52-20-01-01-901	GENERAL VISUAL INSPECTION OF SPAR AND FRAMES. EMERGENCY DOOR STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 52-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
52-20-01-01-902	DETAILED INSPECTION OF DOOR SKIN AND FASTENERS. EMERGENCY DOOR STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 52-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
52-20-20-001 (s)	INTERNAL GENERAL VISUAL INSPECTION OF EMERGENCY DOOR LOCKING AND ACTUATING MECHANISM PKG 41	MOS	48	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 52-20-20	HRS/MSC AFL	3000	+30/-30					
52-20-21-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF EMERGENCY DOOR RUBBER SEAL PKG 12	MOS	24	+30d/-30d			PKG 20-OCT-2017 400:54 200		
	REF: AMM 52-20-21	HRS/MSC AFL	1200	+30/-30					
52-31-20-001 (s)	GENERAL VISUAL INSPECTION OF FORWARD BAGGAGE DOOR LOCKING AND ACTUATING MECHANISM PKG 41	MOS	48	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 52-31-20	HRS/MSC AFL	3000	+30/-30					
52-32-20-001 (s)	GENERAL VISUAL INSPECTION OF AFT BAGGAGE DOOR LOCKING ACTUATING MECHANISM PKG 41	MOS	48	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 52-32-20	HRS/MSC AFL	3000	+30/-30					

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-71-20	LOWER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
52-71-20	UPPER PAX DOOR MICRO SWITCH ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
CHAPTER 53 FUSELAGE									
53-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF FUSELAGE POLYURETHANE FILMS PKG 1 REF: AMM 53-00-20	MOS HRS/MSC AFL	600				PKG 23-JUN-2018 581:30 283		
53-05-00-001 (s)	DETAILED INSPECTION OF FUSELAGE DRAINS PKG 84 REF: AMM 53-05-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
53-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FORWARD FUSELAGE STRUCTURES PKG 90 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
53-10-00-002 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF FORWARD FUSELAGE SKIN PANELS AND SKIN SPLICES PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
53-10-00-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 87 REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
53-10-01-01-901	DETAILED INSPECTION OF FRAMES, BEAMS, POSTS, GUSSET (SPLICES). FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - INTERNAL REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-02-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SKIN AND SPLICES. FORWARD FUSELAGE LEFT AND RIGHT SIDESKIN PANELS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE UPPER SKIN PANEL AND WINDSHIELD CUTOUT - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND SPLICES. FORWARD FUSELAGE LOWER SKIN PANEL - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. FORWARD FUSELAGE LOWER SKIN PANEL - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-04-01-901	DETAILED INSPECTION OF LONGITUDINAL SPLICE. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
53-10-04-01-902	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA. FORWARD FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 53-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FORWARD PRESSURE BULKHEAD PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
53-10-05-01-901	DETAILED VISUAL INSPECTION OF PRESSURE BULKHEAD. FORWARD FUSELAGE PRESSURE BULKHEAD - INTERNAL	MOS					30-OCT-2015 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	17500 14000						
53-10-07-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF NOSE LANDING GEAR WHEELWELL STRUCTURE PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-10-00	HRS/MSC AFL							
53-10-07-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TRUNNIONS, DRAG LOCKING STRUT AND FASTENERS. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL	MOS					30-OCT-2015 0 0		15000 12000
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000						
53-10-07-02-901	DETAILED INSPECTION OF WHEEL WHEEL STRUCTURE. NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - EXTERNAL	MOS					30-OCT-2015 0 0		15000 12000
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000						
53-10-07-02-902	DETAILED INSPECTION NOSE LANDING GEAR WHEEL WHEEL METALLIC STRUCTURE - INTERNAL OF WHEEL WHEEL STRUCTURE.	MOS					30-OCT-2015 0 0		15000 12000
AIRWORTHINESS	REF: NDT PART 5 53-10-00	HRS/MSC AFL	15000 12000						
53-14-00	NOSE RADOME 5190-102-1 687	MOS					30-OCT-2015 0 0		
	REF: See Workcard	HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0				

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL							
53-20-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL							
53-20-01-01-901	DETAILED INSPECTION OF FRAMES, SPLICES/DOUBLERS AND STRINGERS. CENTER FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 14000	
53-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 14000	
53-20-02-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 14000	
53-20-02-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 14000	
53-20-03-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, STRINGERS AND SKIN OVER WING AREA. CENTER FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000					17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-01-901	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICE. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF 2ND FASTENER ROW OF SKIN SPLICE (INNER SKIN). CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-04-02-902	GENERAL VISUAL INSPECTION OF FRAMES. CENTER FUSELAGE LONGITUDINAL LAP JOINT AND CIRCUMFERENTIAL SKIN SPLICE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD FRONT SIDE	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 53-20-00								
53-20-05-003 (s)	INTERNAL DETAILED VISUAL INSPECTION OF CENTER-TO-AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND AFT PRESSURE BULKHEAD BACK SIDE	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 53-20-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-05-01-901	GENERAL VISUAL INSPECTION OF BEAMS, FRAMES, SPLICES/ DOUBLERS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-02-901	DETAILED INSPECTION OF AFT PRESSURE BULKHEAD WEB AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-03-901	DETAILED INSPECTION OF CIRCUMFERENTIAL T WEB SECTION AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-04-901	DETAILED INSPECTION OF SKIN-TO-SPLICE AREA AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-05-05-901	GENERAL VISUAL INSPECTION OF END-FITTINGS AND FASTENERS. CENTER FUSELAGE TO AFT FUSELAGE CIRCUMFERENTIAL SKIN SPLICES AND PRESSURE BULKHEAD - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-20-06-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		
53-20-06-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF MAIN DOOR CUTOUT STRUCTURE						PKG		
	PKG 90	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-06-01-901	DETAILED INSPECTION OF SKIN, DOUBLER AND FASTENERS. PASSENGER DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-20-06-01-902	DETAILED INSPECTION OF THE FRAMES, STRINGERS, BEAMS, INTERCOSTALS, SPLICES, SKIN AND ATTACHMENTS. PASSENGER DOOR CUTOUT STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	8750 7000				0 0		8750 7000
53-20-07-01-901	DETAILED INSPECTION OF FRAMES, DOUBLERS, BEAMS, INTERCOSTALS, SPLICE AND ATTACHMENTS. EMERGENCY DOOR CUTOUT STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-20-07-01-902	DETAILED INSPECTION OF THE SKIN AND FASTENERS TO EMERGENCY DOOR CUTOUT STRUCTURE. EMERGENCY DOOR CUTOUT STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-20-08-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF PASSENGER WINDOW CUTOUT STRUCTURE PKG 90	MOS	60	+30d/-30d			30-OCT-2015		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL					0 0		
53-20-08-01-901	GENERAL VISUAL INSPECTION OF WINDOW FRAME AND ATTACHMENTS. PASSENGER WINDOW CUTOUT STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
53-20-08-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS AT WINDOW AREA. PASSENGER WINDOW CUTOUT STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-10-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF CENTER FUSELAGE-TOWING CONNECTIONS PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0		
	REF: NDT PART 5 53-20-00	HRS/MSC AFL					0 0		
53-20-10-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS AND ATTACHMENTS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		14000
53-20-10-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. CENTER FUSELAGE-TO-WING CONNECTIONS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		14000
53-20-10-02-901	GENERAL VISUAL INSPECTION OF FUSELAGE-TO-WING FITTINGS CENTER FUSELAGE-TO-WING CONNECTIONS - EXTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-20-00	HRS/MSC AFL	17500 14000				0 0		14000
53-30-00-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF AFT FUSELAGE SKINS AND BAGGAGE DOOR CUTOUT STRUCTURE PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-00-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE STRUCTURES PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-01-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, DOUBLERS, SPLICES AND ATTACHMENTS. AFT FUSELAGE UPPER SKIN PANEL - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE UPPER SKIN PANEL - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SIDE SKIN PANEL	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 53-30-00								
53-30-02-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	12500 10000				0 0	12500 10000	
53-30-02-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE SIDE SKIN PANEL - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-02-01-903	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE SIDE SKIN PANEL - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-03-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS, SPLICES AND ATTACHMENTS AFT FUSELAGE LOWER SKIN PANEL - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
53-30-03-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS. AFT FUSELAGE LOWER SKIN PANEL - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE SKIN SPLICES PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL							
53-30-04-01-901	DETAILED INSPECTION OF SKIN TO LONGITUDINAL AND CIRCUMFERENTIAL SPLICE. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - EXTERNAL	MOS					30-OCT-2015 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000						
53-30-04-01-902	DETAILED INSPECTION OF LONGITUDINAL AND CIRCUMFERENTIAL SPLICES. AFT FUSELAGE LONGITUDINAL AND CIRCUMFERENTIAL SKIN SPLICES - INTERNAL	MOS					30-OCT-2015 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000						
53-30-05-02-901	DETAILED INSPECTION OF BAGGAGE DOOR CUTOUT STRUCTURE. AFT FUSELAGE BAGGAGE DOOR CUTOUT STRUCTURE - INTERNAL	MOS					30-OCT-2015 0 0		10000 8000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	10000 8000						
53-30-06-01-901	DETAILED INSPECTION OF FRAMES, FRAMES SPLICES AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					30-OCT-2015 0 0		12500 10000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	12500 10000						
53-30-06-01-902	GENERAL VISUAL INSPECTION OF STRINGERS, DOUBLERS AND ATTACHMENTS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - INTERNAL	MOS					30-OCT-2015 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000						
53-30-06-01-903	DETAILED INSPECTION OF SKIN, SKIN SPLICES AND FASTENERS. AFT FUSELAGE TO PYLON CUTOUT STRUCTURES - EXTERNAL	MOS					30-OCT-2015 0 0		17500 14000
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000						

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-07-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-07-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF AFT FUSELAGE-TO-VERTICAL STABILIZER JUNCTION PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-07-01-901	GENERAL VISUAL INSPECTION OF FRAMES, STRINGERS AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - INTERNAL	MOS					30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		
53-30-07-01-902	DETAILED INSPECTION OF SKIN, BEDPLATES AND FASTENERS. AFT FUSELAGE TO VERTICAL STABILIZER CONNECTION - EXTERNAL	MOS					30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 53-30-00	HRS/MSC AFL	17500 14000				0 0		
53-30-08-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 87	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
53-30-08-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF FRAME 46 PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 53-30-00	HRS/MSC AFL					0 0		
CHAPTER 54	NACELLES/PYLONS								
54-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF PYLON POLYURETHANE FILMS PKG 1	MOS					PKG 23-JUN-2018 581:30 283		
	REF: AMM 54-51-20	HRS/MSC AFL	600						

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-00-001 (s)	INTERNAL DETAILED INSPECTION OF PYLON BEAMS - INTERNAL TO FUSELAGE PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 54-50-00								
54-50-00-002 (s)	INTERNAL DETAILED INSPECTION OF PYLON MAIN BOX PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: See Workcard								
54-50-01-01-901	GENERAL VISUAL INSPECTION OF PYLON FRONT, REAR SPARS AND ATTACHMENTS. PYLON FORWARD BEAM - INTERNAL	MOS HRS/MSC AFL	17500				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 54-50-00		14000						
54-50-02-01-901	GENERAL VISUAL INSPECTION OF PYLON SPARS 3, 4 AND ATTACHMENTS. PYLON AFT BEAM - INTERNAL	MOS HRS/MSC AFL	17500				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 54-50-00		14000						
54-50-03-001 (s)	EXTERNAL - DETAILED INSPECTION OF PYLON MAIN BOX AND LEADING EDGE. PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 54-52-00								
54-50-03-01-901	GENERAL VISUAL INSPECTION OF MAIN BOX SKIN, ANGLE BRACKETS AND FASTENERS. PYLON MAIN BOX - EXTERNAL	MOS HRS/MSC AFL	17500				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 54-52-00		14000						
54-50-03-01-902	DETAILED INSPECTION OF STRINGERS AND FIREWALL. PYLON MAIN BOX - INTERNAL	MOS HRS/MSC AFL	17500				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS	REF: NDT PART 5 54-52-00		14000						

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-04-01-901	GENERAL VISUAL INSPECTION OF SPARS AND BOLTS INTEGRITY. PYLON-TO-FUSELAGE CONNECTIONS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-52-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
54-50-05-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF PYLON YOKES PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 54-55-00								
54-50-05-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF YOKE LUGS. PYLON YOKES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 6 54-55-00	MOS HRS/MSC AFL	15000 12000				30-OCT-2015 0 0	15000 12000	
54-50-05-02-901	DETAILED INSPECTION OF YOKES, FRONT SPARS, GUSSET AND SHIELD PLATES. PYLON YOKES - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
54-50-06-01-901	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	15000 12000				30-OCT-2015 0 0	15000 12000	
54-50-06-01-902	DETAILED INSPECTION OF AFT MOUNT FITTING. AFT MOUNT FITTINGS - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 54-55-00	MOS HRS/MSC AFL	15000 12000				30-OCT-2015 0 0	15000 12000	
CHAPTER 55	STABILIZERS								
55-00-00-001 (s)	GENERAL VISUAL INSPECTION OF STABILIZER POLYURETHANE FILMS PKG 1	MOS HRS/MSC AFL	600				PKG 23-JUN-2018 581:30 283		
AIRWORTHINESS	REF: AMM 55-00-20								
55-10-00	HORIZONTAL STABILIZER (COMPLETION) 505-10700-415 0000860236	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-OCT-2015 0 0		
AIRWORTHINESS	REF: GENERIC NO REF								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF HORIZONTAL-STABILIZER SPARS AND RIBS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
55-10-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER-TO-ELEVATOR HINGE FITTING PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
55-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS PKG 84 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
55-10-01-01-901	DETAILED INSPECTION OF LUG, FITTING AND ATTACHMENTS. FIN-TO-HORIZONTAL STABILIZER CONNECTIONS IN HORIZONTAL STABILIZER - INTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
55-10-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FRONT, REAR SPARS AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - INTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
55-10-02-01-902	DETAILED INSPECTION OF FRONT, REAR SPAR AND FASTENERS. HORIZONTAL STABILIZER FRONT AND REAR SPARS - EXTERNAL REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
AIRWORTHINESS									
55-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 87 REF: NDT PART 5 55-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-03-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) ON HORIZONTAL-STABILIZER UPPER AND LOWER SKIN PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
55-10-03-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, STRINGERS AND STRAPS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-03-01-902	DETAILED INSPECTION OF SKIN AND ATTACHMENTS. HORIZONTAL STABILIZER MAIN BOX UPPER AND LOWER SKIN - EXTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE RIBS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-05-001 (s)	INTERNAL DETAILED INSPECTION ON HORIZONTAL STABILIZER METALLIC RIBS PKG 90	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 55-10-00	HRS/MSC AFL							
55-10-05-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIBS 1 AND ATTACHMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0		14000
55-10-05-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF INTERCOSTALS RIBS ACCESS HOLES. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 6 55-10-00	HRS/MSC AFL	17500 14000				0		14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-05-02-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF INTERCOSTALS RIBS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-05-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF TIP RIB. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-05-04-901	DETAILED INSPECTION OF RIB 1 FITTING AND REINFORCEMENTS. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-05-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 1 ACCESS HOLE. HORIZONTAL STABILIZER METALLIC RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-07-01-901	GENERAL VISUAL INSPECTION OF HINGES. HORIZONTAL STABILIZER ELEVATOR HINGE FITTING - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-10-08-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF HORIZONTAL STABILIZER TRIM ACTUATOR SUPPORT FITTINGS	MOS	60	+30d/-30d			PKG 30-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-10-00								
55-10-08-01-901	DETAILED INSPECTION OF FITTING, INCLUDING HINGES, PINS, FLANGES, WEBS AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-09-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF SUPPORT			OF HORIZONTAL STABILIZER-TO-ELEVATOR TORQUE-TUBE			PKG		
	PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC					0		
		AFL					0		
55-10-09-01-901	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - EXTERNAL						30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS					0	17500	
		HRS/MSC	17500				0	17500	
		AFL	14000				0	14000	
55-10-09-01-902	DETAILED INSPECTION OF COMPOSITE SUPPORT AND ATTACHMENTS. HORIZONTAL STABILIZER COMPOSITE COMMAND BOX - INTERNAL						30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS					0	17500	
		HRS/MSC	17500				0	17500	
		AFL	14000				0	14000	
55-10-10-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF FITTINGS			OF ELEVATOR TRIM-TAB FITTINGS			PKG		
	PKG 90	MOS	120	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 55-10-00	HRS/MSC					0		
		AFL					0		
55-10-10-01-901	DETAILED INSPECTION OF FITTING AND ATTACHMENTS. HORIZONTAL STABILIZER TAB ACTUATOR SUPPORT FITTINGS - EXTERNAL						30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-10-00	MOS					0	17500	
		HRS/MSC	17500				0	17500	
		AFL	14000				0	14000	
55-20-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF ELEVATOR MAIN BOX						PKG		
	PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
	REF: See Workcard	HRS/MSC					0		
		AFL					0		
55-20-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. ELEVATOR MAIN BOX - INTERNAL						30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	MOS					0	17500	
		HRS/MSC	17500				0	17500	
		AFL	14000				0	14000	



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-01-01-902	DETAILED INSPECTION OF SKIN AND FASTENERS, INCLUDING MAIN BOX, TRAILING EDGE, LEADING EDGE. ELEVATOR MAIN BOX - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-02-01-901	DETAILED INSPECTION OF ELEVATOR HINGE PINS. ELEVATOR HINGE FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-02-02-901	GENERAL VISUAL INSPECTION OF ELEVATOR HINGES. ELEVATOR HINGE FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TORQUE TUBE ASSEMBLY PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		
55-20-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ELEVATOR TORQUE TUBE FLANGE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-03-02-901	SPECIAL DETAILED INSPECTION (DYE PENETRANT) OF ELEVATOR TORQUE TUBE. ELEVATOR TORQUE TUBE ASSY - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 8 55-20-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-20-04-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF MASS-BALANCE WEIGHT ATTACHMENTS PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-20-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-04-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF MASS-BALANCE WEIGHT ATTACHMENTS PKG 90 REF: NDT PART 5 55-20-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
55-22-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF ELEVATOR TRIM-TAB PKG 87 REF: NDT PART 5 55-22-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
55-30-00	VERTICAL STABILIZER 505-10100-415 0000855476 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
55-30-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-AFT FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
55-30-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF VERTICAL-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER PKG 84 REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
55-30-01-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FITTING ATTACHMENTS TO COMPOSITE. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL REF: NDT PART 6 55-30-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
55-30-01-02-901	DETAILED INSPECTION OF CHANNEL FITTING AND BARREL NUT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL REF: NDT PART 5 55-30-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-01-03-901	DETAILED INSPECTION OF BOLT. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-01-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF METALLIC RIBS ATTACHMENTS. VERTICAL STABILIZER-TO-FUSELAGE ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-02-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		
55-30-02-01-901	DETAILED INSPECTION OF FITTING, LUG AND ATTACHMENTS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-02-03-901	DETAILED INSPECTION OF PIN VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-02-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIB 5. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
55-30-02-05-901	SPECIAL DETAILED INSPECTION (BOREScope) OF RIB 7. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-02-06-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 6 AND RIB 8. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-02-07-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF RIB 5 , L PROFILES AND SHROUDS. VERTICAL STABILIZER-TO-HORIZONTAL STABILIZER ATTACHMENTS ON VERTICAL STABILIZER - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-03-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX SKIN AND SPARS						PKG		
	PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		
55-30-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER MAIN BOX						PKG		
	PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
	REF: See Workcard	HRS/MSC AFL					0 0		
55-30-03-01-901	DETAILED INSPECTION OF SKIN, SPAR AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-03-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR, STRINGER, RIBS, FLANGES AND ATTACHMENTS. VERTICAL STABILIZER MAIN BOX - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-04-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF VERTICAL STABILIZER-TO-RUDDER HINGE FITTING						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 55-30-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-04-01-901	GENERAL VISUAL INSPECTION OF HINGES. VERTICAL STABILIZER RUDDER HINGE FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-05-002 (s)	INTERNAL DETAILED VISUAL INSPECTION OF HORIZONTAL-STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER	MOS	60	+30d/-30d			30-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
55-30-05-01-901	DETAILED INSPECTION OF FITTING 1 AND FASTENERS. HORIZONTAL STABILIZER ACTUATOR SUPPORT FITTING ON VERTICAL STABILIZER - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-30-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB ACTUATOR FITTING	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-30-00								
55-30-06-01-901	DETAILED INSPECTION OF FITTINGS, LUGS AND ATTACHMENTS. HORIZONTAL TAIL TRIM ACTUATOR SUPPORT FITTINGS ON VERTICAL TAIL - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-30-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
55-40-01-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF RUDDER MAIN BOX	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 87	HRS/MSC AFL					0 0		
	REF: NDT PART 5 55-40-00								
55-40-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. RUDDER MAIN BOX - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 55-40-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-01-01-902	DETAILED INSPECTION OF MAIN BOX, TRAILING EDGE AND LEADING EDGE SKINS, INCLUDING FASTENERS. RUDDER MAIN BOX - EXTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
55-40-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER HINGE FITTINGS PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 55-40-00								
55-40-02-01-901	DETAILED INSPECTION OF PINS OF RUDDER HINGES. RUDDER HINGE FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
55-40-02-02-901	GENERAL VISUAL INSPECTION OF RUDDER HINGES FITTINGS. RUDDER HINGE FITTINGS - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
55-40-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TORQUE TUBE ASSEMBLY PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 55-40-00								
55-40-03-01-901	GENERAL VISUAL INSPECTION OF RUDDER TORQUE TUBE, TORQUE TUBE HINGE FITTINGS AND PINS. RUDDER TORQUE TUBE ASSEMBLY - INTERNAL								
AIRWORTHINESS	REF: NDT PART 5 55-40-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
55-42-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF RUDDER TRIM-TAB PKG 90	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
AIRWORTHINESS	REF: NDT PART 5 55-42-00								

CHAPTER 56 WINDOWS



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-00	LEFT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-3 15166H5768 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-10-00	RIGHT GLASS, HEATED WINDSHIELD ASSY, (LH) NP-195301-4 15157H4986 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-10-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF SIDE WINDOW PKG 84 REF: NDT PART 5 56-12-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
56-10-01-002	FUNCTIONAL CHECK TORQUE OF WINDSHIELD AND SIDE WINDOW ATTACHING BOLTS REF: AMM 56-10-00	MOS HRS/MSC AFL	1200	+30/-30			23-JUN-2018 581:30 283	1781:30	1811:30
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT L/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION COCKPIT R/H SIDE WINDOW STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION LEFT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
56-10-03-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION RIGHT WINDSHIELD STRUCTURE PKG 90 REF: NDT PART 5 56-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FRAMES AND FASTENERS. WINDSHIELD FRAME AND FASTENERS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 56-10-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
56-12-00	LEFT ACRYLIC SIDE WINDOW NP-195302-3 15132H2534 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-12-00	RIGHT ACRYLIC SIDE WINDOW NP-195302-4 15148H3991 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 1 WINDOW TRANSPARENCY 14024 2302722 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 10 WINDOW TRANSPARENCY 14024 2436266 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 11 WINDOW TRANSPARENCY 14024 2436272 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 2 WINDOW TRANSPARENCY 14024 2302732 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 3 WINDOW TRANSPARENCY 14024 2355486 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-20-00	NO. 4 WINDOW TRANSPARENCY 14024 2355487 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 5 WINDOW TRANSPARENCY 14024 2355489 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 6 WINDOW TRANSPARENCY 14024 2374835 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 7 WINDOW TRANSPARENCY 14024 2374836 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 8 WINDOW TRANSPARENCY 14024 2374837 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-00	NO. 9 WINDOW TRANSPARENCY 14024 2436250 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
56-20-01-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PASSENGER WINDOW PANELS PKG 84 REF: NDT PART 5 56-20-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
CHAPTER 57 WINGS									
57-00-00-001 (s)	GENERAL VISUAL INSPECTION OF OF WINGLET POLYURETHANE FILMS PKG 1 REF: AMM 57-35-21	MOS HRS/MSC AFL	600				PKG 23-JUN-2018 581:30 283		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-001 (s)	INTERNAL DETAILED VISUAL INSPECTION OF WING MAIN BOX PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
57-10-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF WING CENTER UPPER SKIN PKG 87 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
57-10-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING-TO-CENTER FUSELAGE CONNECTIONS PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
57-10-01-01-901	DETAILED INSPECTION OF WING-TO-FUSELAGE LINKS. WING TO CENTER FUSELAGE CONNECTIONS - EXTERNAL REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
57-10-02-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING FRONT SPAR PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
57-10-02-01-901	DETAILED INSPECTION OF WING FRONT SPAR LOWER CAP, SPLICES AND ATTACHMENTS. WING FRONT SPAR - INTERNAL REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	
57-10-03-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING REAR SPAR PKG 90 REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
57-10-03-01-901	DETAILED INSPECTION OF WING REAR SPAR LOWER CAP, THIRD CAP, SPLICES AND ATTACHMENTS. WING REAR SPAR - INTERNAL REF: NDT PART 5 57-10-00	MOS HRS/MSC AFL	17500 14000				30-OCT-2015 0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-04-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING ROOT SPAR PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 57-20-00	HRS/MSC AFL							
57-10-04-01-901	DETAILED INSPECTION OF WING ROOT SPAR. WING ROOT SPAR - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0		14000
57-10-05-01-901	GENERAL VISUAL INSPECTION OF MIDDLE SPAR, SPLICES AND ATTACHMENTS. WING MIDDLE SPAR - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0		14000
57-10-06-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING UPPER PANEL PKG 87	MOS	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
57-10-07-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING LOWER PANEL PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: NDT PART 5 57-10-00	HRS/MSC AFL							
57-10-07-01-901	GENERAL VISUAL INSPECTION OF ACCESS WINDOWS FRAMES AND STRINGERS. WING LOWER SKIN PANEL - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0		14000
57-10-07-01-902	DETAILED INSPECTION OF WING SKIN. WING LOWER SKIN PANEL - EXTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0		14000
57-10-08-01-901	DETAILED INSPECTION OF MACHINED RIBS. WING RIBS - INTERNAL	MOS					30-OCT-2015 0		17500
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0		14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-08-02-901	DETAILED INSPECTION OF MAIN LANDING GEAR RIBS. WING RIBS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-11-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING CENTER SPLICE	MOS	60	+30d/-30d			30-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-10-00								
57-10-11-01-901	DETAILED INSPECTION OF SPAR SPLICES, LOWER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-11-01-902	SPECIAL DETAILED INSPECTION (BORESCOPE) OF UPPER SKIN SPLICES, INCLUDING FASTENERS. WING CENTRAL SPLICES - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-10-12-01-901	DETAILED INSPECTION OF SKIN SPLICES, INCLUDING FASTENERS. KINK LOWER SKIN SPLICE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-10-00	HRS/MSC AFL	12500 10000				0 0	12500 10000	
57-50-01-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING-EDGE TORQUE BOX AND CONTROL SURFACES FITTINGS	MOS	60	+30d/-30d			30-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-50-00								
57-50-01-01-901	DETAILED INSPECTION OF TORSION BOXES RIBS AND ATTACHMENTS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-01-01-902	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF RIBS ROLLERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	11250 9000				0 0	11250 9000	
57-50-01-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TORSION BOXES RIBS LUG RAILS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-01-03-901	DETAILED INSPECTION OF TORSION BOXES SKINS AND FASTENERS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-01-04-901	DETAILED INSPECTION OF AILERON AND FLAP HINGES FITTINGS. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTINGS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-01-05-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-01-05-902	DETAILED INSPECTION OF BELL CRANK SUPPORT FITTING. WING TRAILING EDGE TORQUE BOX AND CONTROL SURFACES SUPPORT FITTING - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-50-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF WING TRAILING EDGE MLG TRUNNION, ACTUATOR FITTINGS AND UPLOCK						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 57-20-00	HRS/MSC AFL					0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-02-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-02-01-902	DETAILED INSPECTION OF MLG ACTUATOR SUPPORT FITTING. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-02-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-50-02-02-902	DETAILED INSPECTION OF MLG TRUNNIONS. WING TRAILING EDGE MLG TRUNNION, ACTUATOR SUPPORT FITTINGS AND UPLOCK - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-50-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-52-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE INBOARD FLAP PKG 90	MOS	120	+30d/-30d			30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL					0 0		
57-52-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE INBOARD FLAP PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL					0 0		
57-52-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-52-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP INBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP INBOARD RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP INBOARD TRACKS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-52-00	HRS/MSC AFL	11250 9000				0 0	11250 9000	
57-52-04-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-52-04-02-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP ACTUATOR FITTING. FLAP INBOARD ACTUATOR SUPPORT FITTING - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-52-00	HRS/MSC AFL	17500 14000				0 0	17500 14000	
57-53-00-001 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OF THE OUTBOARD FLAP	MOS	120	+30d/-30d			30-OCT-2015		
	PKG 90	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-53-00								
57-53-00-002 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THE OUTBOARD FLAP	MOS	60	+30d/-30d			30-OCT-2015		
	PKG 84	HRS/MSC AFL					0 0		
	REF: NDT PART 5 57-53-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-53-01-01-902	DETAILED INSPECTION OF MAIN BOX AND VANE. FLAP OUTBOARD COMPOSITE STRUCTURE - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-53-02-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAP RIBS. FLAP OUTBOARD RIBS - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-53-03-01-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF FLAP TRACKS. FLAP OUTBOARD TRACKS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-53-00	HRS/MSC AFL	11250 9000				0 0		11250 9000
57-53-04-01-901	DETAILED INSPECTION OF PIN OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-53-04-02-901	DETAILED INSPECTION OF LUG OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-53-04-03-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLANGES OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-53-04-04-901	SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF NECK OF FLAP ACTUATOR SUPPORT FITTING. FLAP OUTBOARD ACTUATOR SUPPORT FITTINGS AND VANE SUPPORT FITTING - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 6 57-53-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-60-00-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF THEAILERON PKG 87	MOS	120	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 57-60-00	HRS/MSC AFL					0 0		
57-60-00-002 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE METHOD) OFAILERON TAB PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
	REF: NDT PART 5 57-60-00	HRS/MSC AFL					0 0		
57-60-01-01-901	SPECIAL DETAILED INSPECTION (BORESCOPE) OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - INTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-60-01-01-902	DETAILED INSPECTION OF SKIN, SPARS, RIBS AND FASTENERS. AILERON MAIN BOX - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-60-01-02-901	DETAILED INSPECTION OFAILERON ROOT RIBS. AILERON MAIN BOX - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-60-02-01-901	DETAILED INSPECTION OFAILERON HINGES PINS. AILERON HINGE FITTINGS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0		17500 14000
57-60-02-02-901	DETAILED INSPECTION OFAILERON HINGES FITTINGS. AILERON HINGE FITTINGS - EXTERNAL	MOS					30-OCT-2015		
AIRWORTHINESS	REF: NDT PART 5 57-60-00	HRS/MSC AFL	17500 14000				0 0		17500 14000

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-02-001 (s)	EXTERNAL DETAILED VISUAL INSPECTION OF SPOILER HINGE FITTINGS						PKG		
	PKG 84	MOS	60	+30d/-30d			30-OCT-2015		
		HRS/MSC					0		
	REF: NDT PART 5 57-70-00	AFL					0		

CHAPTER 70 STANDARD PRACTICES - ENGINES

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01

700010	NO. 1 ENGINE - TREATMENT MAGNESIUM CORROSION								
		MOS					14-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 70-00-00	ENC					0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01

700010	NO. 2 ENGINE - TREATMENT MAGNESIUM CORROSION								
		MOS					09-JUL-2015		
		HRS/MSC	A/R				0		
	REF: MM 70-00-00	ENC					0		

CHAPTER 71 POWER PLANT

71-11-00-001 (s)	GENERAL VISUAL INSPECTION OF UPPER MID COWL						PKG		
	PKG 50	MOS					30-OCT-2015		
		HRS/MSC	6000	+30/-30			0		
	REF: AMM 71-11-00	AFL					0		

71-20-00	LEFT AFT ENGINE MOUNT ISOLATOR								
	LM-475-SA4	MOS				TSN:0	30-OCT-2015		
	LK0960	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	AFL				TSN:0	0		

71-20-00	LEFT INBOARD FORWARD ENGINE MOUNT ISOLATOR								
	LM-475-SA3	MOS				TSN:0	30-OCT-2015		
	LK1767	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	AFL				TSN:0	0		

71-20-00	LEFT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR								
	LM-475-SA3	MOS				TSN:0	30-OCT-2015		
	LK1752	HRS/MSC	O/C			TSN:0	0		
	REF: See Workcard	AFL				TSN:0	0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00	RIGHT AFT ENGINE MOUNT ISOLATOR LM-475-SA4 LK0963 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
71-20-00	RIGHT INBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1906 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
71-20-00	RIGHT OUTBOARD FORWARD ENGINE MOUNT ISOLATOR LM-475-SA3 LK1821 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
71-21-01-01-901	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ON THE ENGINE MOUNT COMPONENTS. ENGINE FORWARD MOUNTING ASSEMBLY	MOS HRS/MSC AFL	6000 6000				30-OCT-2015 0 0	6000 6000	
AIRWORTHINESS	REF: AMM 71-20-00								
71-22-01-01-901	DETAILED VISUAL INSPECTION OF AFT MOUNTS BOLTS TORQUE SEAL	MOS HRS/MSC AFL	3600				30-OCT-2015 0 0	3600	
AIRWORTHINESS	REF: See Workcard								
71-22-01-01-902	RESTORATION (OVERHAUL) OF ENGINE MOUNT ASSEMBLY AND ATTACHMENTS (INCLUDING BOLTS). NOTE: THE FLIGHT CYCLES / FLIGHT HOURS ACCUMULATED SHALL BE BASED ENGINE AFT MOUNTING ASSEMBLY	MOS HRS/MSC AFL	6000 6000				30-OCT-2015 0 0	6000 6000	
AIRWORTHINESS	REF: AMM 71-20-00								
71-31-00-001 (s)	DETAILED INSPECTION OF PYLON FIREWALL SEAL PKG 20 REF: AMM 71-31-00	MOS HRS/MSC AFL	1800	+30/-30			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-60-01	LEFT ENGINE AIR INLET 505-43420-403 CPI-173 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
71-60-01	RIGHT ENGINE AIR INLET 505-43430-403 CPI142 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
71EN1 71.EN1	NO. 1 ENGINE 3072913-01 PCE-DG0626 REF: See Workcard	MOS HRS/MSC AFL	E/C				03-AUG-2015 0 0		
71EN2 71.EN2	NO. 2 ENGINE 3072913-01 PCE-DG0624 REF: See Workcard	MOS HRS/MSC AFL	E/C				03-AUG-2015 0 0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01									
70-00-00-200-801	NO. 1 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS REF: MM 70-00-00	MOS HRS/MSC ENC	A/R				14-JUL-2015 0 0		
71-00-00-160-805	NO. 1 ENGINE - COMPRESSOR WASH REF: MM 71-00-00	DAYS HRS/MSC ENC	A/R				30-OCT-2015 0 0		
71-00-00-760-810	NO. 1 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN REF: MM 71-00-00	MOS HRS/MSC ENC	A/R				14-JUL-2015 0 0		
71-00-00-760-823	NO. 1 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH) REF: MM 71-00-00	MOS HRS/MSC ENC	12 630				09-NOV-2018 637:12 307	09-NOV-2019 (1267:12) 1267:12	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-02-810-801	NO. 1 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				09-NOV-2018 637:12 307	09-NOV-2019 (1267:12) 1267:12	
	REF: MM 72-00-02	HRS/MSC ENC	630						
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
70-00-00-200-801	NO. 2 ENGINE - INSPECT FOR CORROSION ON STRUCTURAL CASES, DUCTS	MOS					09-JUL-2015 0 0		
	REF: MM 70-00-00	HRS/MSC ENC	A/R						
71-00-00-160-805	NO. 2 ENGINE - COMPRESSOR WASH	DAYS					30-OCT-2015 0 0		
	REF: MM 71-00-00	HRS/MSC ENC	A/R						
71-00-00-760-810	NO. 2 ENGINE - PERFORM A PERFORMANCE CALIBRATION RUN	MOS					09-JUL-2015 0 0		
	REF: MM 71-00-00	HRS/MSC ENC	A/R						
71-00-00-760-823	NO. 2 ENGINE - CLEARING TLD (TIME LIMITED DISPATCH)	MOS	12				09-NOV-2018 637:12 307	09-NOV-2019 (1267:12) 1267:12	
	REF: MM 71-00-00	HRS/MSC ENC	630						
72-00-02-810-801	NO. 2 ENGINE - CHECK ELECTRONIC ENGINE CONTROL (EEC) FAULT ISOLATION	MOS	12				09-NOV-2018 637:12 307	09-NOV-2019 (1267:12) 1267:12	
	REF: MM 72-00-02	HRS/MSC ENC	630						

CHAPTER 72		ENGINE							
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01									
72-00-00-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA						PKG		
	PKG 1	MOS	12	+30d			09-NOV-2018 637:12 307		
	REF: MM 72-00-00	HRS/MSC ENC	600	+10%					

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-802 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-803 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-804 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-805 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-806 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-807 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-808 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-809 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-802	NO. 1 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	MOS					14-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-280-818	NO. 1 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS	120	+1m			14-JUL-2015	14-JUL-2025	14-AUG-2025
	REF: MM 72-00-00	HRS/MSC ENC					0 0		
72-00-00-280-820 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	MOS	12	+30d			09-NOV-2018		
	PKG 1	HRS/MSC ENC	600	+10%			637:12 307		
	REF: MM 72-00-00								
72-00-00-640-802	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					09-NOV-2018		
	REF: MM 72-00-00	HRS/MSC ENC	BF/F				637:12 307		
+ 72-00-00-640-806	NO. 1 ENGINE - OIL ANALYSIS	MOS					14-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
720010	NO. 1 ENGINE - OVERHAUL	MOS					14-JUL-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	5000	+100			0 0	(5000) 5000	5100
720060	NO. 1 ENGINE - HOT SECTION INSPECTION	MOS					14-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	2500	+50			0 0	(2500) 2500	2550
721010	NO. 1 ENGINE - GEARBOX	MOS					14-JUL-2015		
	PN	HRS/MSC ENC	O/C		TSN:0		0 0		
	SN-UNKNOWN				TSN:0				
	REF: GENERIC NO REF				TSN:0				

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 1 ENGINE - OIL PUMP 3073477-02 EC01A004A944 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723004	NO. 1 ENGINE - LP SHAFT ASSEMBLY 3073356-01 PKAAA616631 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(30000) 30000	
723010	NO. 1 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A003MAN9 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(15000) 15000	
723020	NO. 1 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1D5020 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(15000) 15000	
723030	NO. 1 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A003M892 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(13500) 13500	
723040	NO. 1 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 EAAD000R644 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(13500) 13500	
723050	NO. 1 ENGINE - FAN CASE ASSEMBLY 3075221-01 EDA1498L REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723060	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723070	NO. 1 ENGINE - INTERMEDIATE CASE ASSEMBLY 3079507-01 HBA0069 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723080	NO. 1 ENGINE - GAS GENERATOR CASE ASSEMBLY 3076150-01 RWA79E515 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723090	NO. 1 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A003MW6T REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723095	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA613881 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723110	NO. 1 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00R695 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723120	NO. 1 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 UAAG543 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723130	NO. 1 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 UAAG632 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723140	NO. 1 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA000017896 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723150	NO. 1 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAD000T066 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723160	NO. 1 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 3052670-02 FCN424499 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723170	NO. 1 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA616542 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723180	NO. 1 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052616-01 FCN429585 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723190	NO. 1 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052634-01 FCN430387 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
723705	NO. 1 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A003MKH4 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(13500) 13500	
723706	NO. 1 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A003MTXE REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(13500) 13500	
724001	NO. 1 ENGINE - INNER COMBUSTION LINER 3075516-01 A003M8LN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724002	NO. 1 ENGINE - OUTER COMBUSTION LINER 3075522-01 A003MEXP REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
724010	NO. 1 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221902318 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
724706	NO. 1 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A003KC8X REF: See Workcard	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(10000) 10000	
724825	NO. 1 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 EAAD000T372 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0	(13500) 13500	
725010	NO. 1 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3077471-01 HWNW8916 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6143 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6156 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6168 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6170 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6172 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9402 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9417 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9418 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9423 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9425 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3077471-01 HWNW9236 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9433 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9434 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9435 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9441 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9455 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9471 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9481 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9490 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9492 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3077471-01 HWNX4292 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9503 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9505 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9506 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9513 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC9516 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6863 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6864 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK1674 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2405 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2408 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPA9981 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2493 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2505 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2506 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2508 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2511 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2519 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2520 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2644 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2654 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3703 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPB0409 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3714 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3731 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3733 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3734 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3750 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL3758 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6337 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6338 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6339 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6353 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6059 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6358 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6063 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6065 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC6070 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6365 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6374 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6375 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6396 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6400 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6412 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6423 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6433 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 1 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6444 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725010	NO. 1 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL6454 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725015	NO. 1 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN427882 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725020	NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA80E360 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725025	NO. 1 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA006A000 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725030	NO. 1 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3053163CL01 PDAK2T2A01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725035	NO. 1 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAK55YA01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
725040	NO. 1 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHKPAHC01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 1 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN429217 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726020	NO. 1 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223908 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726030	NO. 1 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223911 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726040	NO. 1 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223912 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726050	NO. 1 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223913 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726060	NO. 1 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726070	NO. 1 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3078183-01 PKAAA608080 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726080	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA74E709 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726090	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1507692 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726110	NO. 1 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1506242 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726120	NO. 1 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0225414 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
726130	NO. 1 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA613893 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
727010	NO. 1 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
727020	NO. 1 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA015A900 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
793010	NO. 1 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
72-00-00-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE INLET AREA PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-212-802 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE INTERMEDIATE CASE AND AGB PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-803 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BYPASS DUCT PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-804 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE TURBINE EXHAUST CASE PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-805 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FUEL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-806 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE OIL DISTRIBUTION SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-807 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE LP COMPRESSOR INLET COMPONENTS PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-808 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE T6 TEMPERATURE INDICATING SYSTEM PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
72-00-00-212-809 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANE (RETAINING) CLAMP PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-00-00-280-802	NO. 2 ENGINE - BORESCOPE INSPECTION HP COMPRESSOR, DIFFUSER AND COMBUSTOR	MOS					09-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
72-00-00-280-818	NO. 2 ENGINE - INSPECT LOW UTILIZATION PROGRAM (IF REQUIRED - SEE NOTES)	MOS	120	+1m			09-JUL-2015	09-JUL-2025	09-AUG-2025
	REF: MM 72-00-00	HRS/MSC ENC					0 0		
72-00-00-280-820 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FAN EXIT VANES	MOS	12	+30d			09-NOV-2018		
	PKG 1	HRS/MSC ENC	600	+10%			637:12 307		
	REF: MM 72-00-00								
72-00-00-640-802	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE OIL LEVEL	MOS					09-NOV-2018		
	REF: MM 72-00-00	HRS/MSC ENC	BF/F				637:12 307		
+ 72-00-00-640-806	NO. 2 ENGINE - OIL ANALYSIS	MOS					09-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	A/R				0 0		
720010	NO. 2 ENGINE - OVERHAUL	MOS					09-JUL-2015		
	REF: GENERIC NO REF	HRS/MSC ENC	5000	+100			0 0	(5000) 5000	5100
720060	NO. 2 ENGINE - HOT SECTION INSPECTION	MOS					09-JUL-2015		
	REF: MM 72-00-00	HRS/MSC ENC	2500	+50			0 0	(2500) 2500	2550
721010	NO. 2 ENGINE - GEARBOX	MOS					09-JUL-2015		
	PN	HRS/MSC ENC	O/C		TSN:0		0 0		
	SN-UNKNOWN				TSN:0				
	REF: GENERIC NO REF				TSN:0				

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722001	NO. 2 ENGINE - OIL PUMP 3073477-02 EC01A004A938 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723004	NO. 2 ENGINE - LP SHAFT ASSEMBLY 3073356-01 PKAAA616627 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(30000) 30000	
723010	NO. 2 ENGINE - LP COMPRESSOR FAN ROTOR 3073311-01 A003MDHW REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(15000) 15000	
723020	NO. 2 ENGINE - LP COMPRESSOR INLET ROTOR 3073292-01 TXA1D5001 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(15000) 15000	
723030	NO. 2 ENGINE - 1ST STAGE HP COMPRESSOR ROTOR 3072981-01 A003ME2D REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(13500) 13500	
723040	NO. 2 ENGINE - 2ND STAGE HP COMPRESSOR ROTOR 3056210-01 EAAD000R968 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(13500) 13500	
723050	NO. 2 ENGINE - FAN CASE ASSEMBLY 3075221-01 EDA1498K REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723060	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY ROLLER CYLINDRICAL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723070	NO. 2 ENGINE - INTERMEDIATE CASE ASSEMBLY 3079507-01 HBA0099 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723080	NO. 2 ENGINE - GAS GENERATOR CASE ASSEMBLY 3076150-01 RWA79E512 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723090	NO. 2 ENGINE - GAS GENERATOR DIFFUSER 3073236-01 A003MW6P REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723095	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3052673-01 PKAAA613871 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723110	NO. 2 ENGINE - NO. 3 SEAL BEARING RUNNER 3052668-01 AFD00R702 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723120	NO. 2 ENGINE - REAR NO. 4 SEAL BEARING RUNNER 3072571-01 UAAG748 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723130	NO. 2 ENGINE - FRONT NO. 4 SEAL BEARING RUNNER 3072572-01 UAAG628 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723140	NO. 2 ENGINE - NO. 4 SCOOP OIL BEARING 3052737-01 LPA000017906 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723150	NO. 2 ENGINE - HIGH PRESSURE SHAFT COMPRESSOR 3072574-01 EAAD000T075 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723160	NO. 2 ENGINE - COMPRESSOR ROTOR BALANCING ASSEMBLY BALL ANNULAR BEARING 3052670-02 FCN424493 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723170	NO. 2 ENGINE - SPIRAL BEVEL GEARBOX DRIVE GEAR SHAFT 3072280-01 PKAAA616527 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723180	NO. 2 ENGINE - FORWARD LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING 3052616-01 FCN429589 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723190	NO. 2 ENGINE - REAR LOW PRESSURE SHAFT ASSEMBLY BALL ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
723705	NO. 2 ENGINE - 1ST STAGE LOW PRESSURE TURBINE DISK 3053812-01 A003MKH9 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(13500) 13500	
723706	NO. 2 ENGINE - 2ND STAGE LOW PRESSURE TURBINE DISK 3053743-01 A003M7DH REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(13500) 13500	
724001	NO. 2 ENGINE - INNER COMBUSTION LINER 3075516-01 A003M8LL REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724002	NO. 2 ENGINE - OUTER COMBUSTION LINER 3075522-01 A003M3BE REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
724010	NO. 2 ENGINE - TURBINE SUPPORT CASE ASSEMBLY 3075468-01 ACM221902316 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
724706	NO. 2 ENGINE - HIGH PRESSURE TURBINE DISK 3053331-01 A003METX REF: See Workcard	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(10000) 10000	
LIFE LIMIT									
724825	NO. 2 ENGINE - CENTRIFUGAL IMPELLER 3052661-01 A003MD02 REF: GENERIC NO REF	MOS HRS/MSC ENC	13500	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0	(13500) 13500	
LIFE LIMIT									
725010	NO. 2 ENGINE - NO. 1 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8284 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 10 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8359 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 11 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8365 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 12 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8366 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 13 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8369 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 14 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8371 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 15 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8378 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 16 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8381 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 17 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8399 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 18 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5746 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 19 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5763 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 2 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8306 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 20 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5771 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 21 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5780 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 22 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5786 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 23 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5787 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 24 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5788 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 25 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5792 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 26 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5812 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 27 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5823 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 28 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5831 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 29 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5834 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 3 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8315 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 30 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5849 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 31 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5850 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 32 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5858 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 33 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH5862 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 34 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6771 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 35 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6774 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 36 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6779 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 37 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6784 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 38 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6785 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 39 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6793 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 4 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8316 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 40 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6798 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 41 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6805 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 42 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6818 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 43 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6820 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 44 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6822 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 45 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6825 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 46 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6827 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 47 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6831 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 48 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6840 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 49 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6851 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 5 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8317 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 50 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6853 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 51 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6861 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 52 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPH6862 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 53 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK3843 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 54 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6762 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 55 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6774 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 56 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6NG REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO. 57 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6781 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 58 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6793 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 59 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6804 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 6 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8327 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 60 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6816 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 7 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8329 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 8 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8335 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO. 9 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPC8343 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.61 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6826 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.62 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6828 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.63 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6831 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.64 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6842 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.65 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6855 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.66 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6857 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.67 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6860 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.68 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK6864 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - NO.69 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPK7408 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725010	NO. 2 ENGINE - NO.70 HIGH PRESSURE TURBINE BLADE 3077471-01 HWPL2033 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725015	NO. 2 ENGINE - LOW PRESSURE TURBINE ROTOR ASSEMBLY ROLLER CYLINDRICAL BEARING 3073355-01 FCN427874 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725020	NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 3076552-01 RWA80E052 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725025	NO. 2 ENGINE - NO. 5 CARBON SEAL BEARING RUNNER 3073353-01 MDAA005A992 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725030	NO. 2 ENGINE - LOW PRESSURE (CASTING) TURBINE VANE RING 3053163CL01 PDAK1CCE01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725035	NO. 2 ENGINE - TURBINE (CASTING) VANE RING 3052361CL01 PDAK51TN01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
725040	NO. 2 ENGINE - LOW PRESSURE TURBINE VANE ASSEMBLY 3073262CL02 BHKNLRH01 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 2 ENGINE - ROLLER CYLINDRICAL BEARING 3052549-01 FCN429214 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726020	NO. 2 ENGINE - FORWARD HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223590 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726030	NO. 2 ENGINE - REAR HYDRAULIC PUMP DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223595 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726040	NO. 2 ENGINE - FORWARD FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223605 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726050	NO. 2 ENGINE - REAR FUEL CONTROL DRIVE ROLLER FLANGED BEARING 3073908-01 AEB0223610 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726060	NO. 2 ENGINE - ACCESSORY DRIVE ROLLER FLANGED BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726070	NO. 2 ENGINE - ACCESSORY DRIVE GEARSHAFT ASSEMBLY 3078183-01 PKAAA602851 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726080	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT 3072279-01 RWA74E712 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726090	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL FLANGED BEARING 3072235-01 FAA1301686 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726110	NO. 2 ENGINE - ACCESSORY GEARBOX DRIVE SHAFT BALL ANNULAR BEARING 3052605-01 FAA1506236 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726120	NO. 2 ENGINE - ACCESSORY GEARBOX BALL ANNULAR BEARING 3052550-01 BB0225416 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
726130	NO. 2 ENGINE - SPLINED BEVEL GEARBOX DRIVE GEAR SHAFT 3072282-01 PKAAA613887 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
727010	NO. 2 ENGINE - FRONT OUTER BYPASS DUCT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
727020	NO. 2 ENGINE - REAR BYPASS DUCT ASSEMBLY 3074835-01 KYAA015A902 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
793010	NO. 2 ENGINE - 7 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
CHAPTER 73	ENGINE FUEL AND CONTROL								
73-21-01	LEFT FADEC 1012300-3-003 2013040022 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-OCT-2017 400:54 200		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-21-01	RIGHT FADEC 1012300-3-003 2014050012 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:1 TSN:1219 TSR:0 TSR:0			20-OCT-2017 400:54 200		
73-33-01	LEFT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 DTY0813 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
73-33-01	RIGHT ENGINE LOW ACCURACY ENGINE FUEL MASS FLOW FLOWMETER 8TJ300AAB2 DTY1602 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01

72-00-00-280-819 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
73-10-01-212-801	NO. 1 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
+ 73-10-04-000-801	NO. 1 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT) (9900) 9900		
73-10-05-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
73-10-05-960-801	NO. 1 ENGINE - DISCARD FUEL THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			23-JUN-2018 581:30 283	(1181:30) 1181:30	1241:30

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-07-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
+ 73-20-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F82135 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-02-212-801 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
73-20-10-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-05 ADXBA001155 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-20-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-30-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100				(5000) 5000 M 5100	
73-30-02-212-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
731002	NO. 1 ENGINE - FLOW DIVIDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0	14-JUL-2015 0 0	

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005	NO. 1 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2018 581:30 283		
731010	NO. 1 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65004 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65129 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65130 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65005 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65006 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65117 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65123 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 1 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65124 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65125 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65127 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
731010	NO. 1 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65128 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
732001	NO. 1 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2015020021 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:99:51 TSN:103			20-OCT-2017 400:54 200		
732002	NO. 1 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F82135 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
732005	NO. 1 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
732006	NO. 1 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010	NO. 1 ENGINE - ELECTRICAL WIRING HARNESS 3073237-05 ADXBA001155 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
732030	NO. 1 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
732040	NO. 1 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
72-00-00-280-819 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE EMERGENCY FUEL SHUTOFF VALVE LEVER ASSEMBLY PKG 1 REF: MM 72-00-00	MOS HRS/MSC ENC	12 600	+30d +10%			09-NOV-2018 637:12 307		
73-10-01-212-801	NO. 2 ENGINE - EXAMINE - FUEL MANIFOLD TRANSFER TUBES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
+ 73-10-04-000-801	NO. 2 ENGINE - DISCARD OF FUEL MANIFOLD ADAPTER ASSEMBLIES REF: MM 73-10-04	MOS HRS/MSC ENC	9900				(EBT) (9900) 9900		
73-10-05-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION (GVI) OF THE FUEL FILTER ELEMENT REF: MM 73-10-05	MOS HRS/MSC ENC	12	+30d			09-NOV-2018 637:12 307	09-NOV-2019	09-DEC-2019
73-10-05-960-801	NO. 2 ENGINE - DISCARD FUEL THE FUEL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			23-JUN-2018 581:30 283	(1181:30) 1181:30	1241:30

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-07-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE FSOV CABLE PKG 1 REF: MM 73-10-07	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
+ 73-20-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - FUEL METERING UNIT 3071682-05 F82145 REF: MM 73-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-02-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE ENGINE WIRING HARNESS PKG 1 REF: MM 73-20-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
73-20-10-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - ENGINE WIRING HARNESS 3073237-05 ADXBA001176 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-20-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL NOZZLES REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
73-20-30-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100				(5000) 5000 M 5100	
73-30-02-212-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE FUEL PRESSURE TRANSDUCER SENSOR PKG 1 REF: MM 73-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
731002	NO. 2 ENGINE - FLOW DIVIDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C				09-JUL-2015 0 0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005	NO. 2 ENGINE - FUEL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			23-JUN-2018 581:30 283		
731010	NO. 2 ENGINE - NO. 1 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65105 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 10 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65221 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 11 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65227 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 2 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65106 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 3 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65109 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 4 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65110 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 5 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65214 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731010	NO. 2 ENGINE - NO. 6 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65215 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 7 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65217 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 8 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65218 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
731010	NO. 2 ENGINE - NO. 9 FUEL NOZZLE ASSEMBLY 3057135-01 DEAAA65220 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
732001	NO. 2 ENGINE - ENGINE ELECTRONIC CONTROL (EEC) UNIT 1012300-3-003 2014050012 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSR:1 TSN:1219 TSR:0 TSR:0			20-OCT-2017 400:54 200		
732002	NO. 2 ENGINE - FUEL METERING UNIT (FMU) 3071682-05 F82145 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
732005	NO. 2 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
732006	NO. 2 ENGINE - N1 SPEED SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010	NO. 2 ENGINE - ELECTRICAL WIRING HARNESS 3073237-05 ADXBA001176 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
732030	NO. 2 ENGINE - FUEL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
732040	NO. 2 ENGINE - FUEL SHUT-OFF CABLE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

CHAPTER 74 IGNITION

ENGINE NO.	Model	Serial #	PCE	DG	Part #	Task Description	Unit	Interval	Time Since	Adj	Warr Exp	Compliance	Next Due	Max Limit
ENGINE NO. 1	Model : PW535E	Serial #	PCE-DG0626		Part # 3072913-01									
74-00-01-750-801 (s)						NO. 1 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				09-NOV-2018 637:12 307		
74-10-01-212-801 (s)						NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 31J2807-07 PKG 1 NNA15240013 REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			09-NOV-2018 637:12 307		
74-20-01-212-801 (s)						NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			09-NOV-2018 637:12 307		
74-20-02-210-801 (s)						NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR 3070508-01 PKG 1 N/A REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				09-NOV-2018 637:12 307		



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR 3070508-01 PKG 1 N/A REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG 09-NOV-2018 637:12 307		
74-20-02-960-801	NO. 1 ENGINE - DISCARD 5 O'CLOCK IGNITER 3070508-01 N/A REF: See Workcard	MOS HRS/MSC ENC	O/C				23-JUN-2018 581:30 283		
+ 74-20-02-960-801	NO. 1 ENGINE - DISCARD 7 OCLOCK IGNITER 3070508-01 N/A REF: See Workcard	MOS HRS/MSC ENC	O/C				23-JUN-2018 581:30 283		
741001	NO. 1 ENGINE - EXCITER IGNITION 31J2807-07 NNA15240013 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
742000	NO. 1 ENGINE - 5 O'CLOCK IGNITER 3070508-01 N/A REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			23-JUN-2018 581:30 283		
742001	NO. 1 ENGINE - 7 O'CLOCK IGNITER 3070508-01 N/A REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			23-JUN-2018 581:30 283		
742002	NO. 1 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-01 NNA16330165 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			20-OCT-2017 400:54 200		
742003	NO. 1 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA16440280 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:3 TSN:0 TSN:0			20-OCT-2017 400:54 200		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00-01-750-801 (s)	NO. 2 ENGINE - DO A FUNCTIONAL TEST OF IGNITION SYSTEM PKG 1 REF: MM 74-00-01	MOS HRS/MSC ENC	12 600				PKG 09-NOV-2018 637:12 307		
74-10-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXCITER IGNITION OF THE IGNITION EXCITER 31J2807-07 PKG 1 NNA15260115 REF: MM 74-10-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
74-20-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE IGNITION CABLES PKG 1 REF: MM 74-20-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 5 O'CLOCK IGNITION IGNITOR 3070508-01 PKG 1 NNA18090061 REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG 09-NOV-2018 637:12 307		
74-20-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION OF THE 7 O'CLOCK IGNITION IGNITOR 3070508-01 PKG 1 NNA18050199 REF: MM 74-20-02	MOS HRS/MSC ENC	12 600				PKG 09-NOV-2018 637:12 307		
74-20-02-960-801	NO. 2 ENGINE - DISCARD 5 O'CLOCK IGNITER 3070508-01 NNA18090061 REF: See Workcard	MOS HRS/MSC ENC	O/C				23-JUN-2018 581:30 283		
+ 74-20-02-960-801	NO. 2 ENGINE - DISCARD 7 OCLOCK IGNITER 3070508-01 NNA18050199 REF: See Workcard	MOS HRS/MSC ENC	O/C				23-JUN-2018 581:30 283		
741001	NO. 2 ENGINE - EXCITER IGNITION 31J2807-07 NNA15260115 REF: See Workcard	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0 TSN:0	09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742000	NO. 2 ENGINE - 5 O'CLOCK IGNITER 3070508-01 NNA18090061 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			23-JUN-2018 581:30 283		
742001	NO. 2 ENGINE - 7 O'CLOCK IGNITER 3070508-01 NNA18050199 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			23-JUN-2018 581:30 283		
742002	NO. 2 ENGINE - INBOARD SHORT IGNITOR LEAD 3127408-01 NNA16330178 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:2 TSN:0 TSN:0			20-OCT-2017 400:54 200		
742003	NO. 2 ENGINE - OUTBOARD LONG IGNITOR LEAD 3127408-02 NNA16440288 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:3 TSN:0 TSN:0			20-OCT-2017 400:54 200		

CHAPTER 75

AIR

ENGINE NO.	Model	Serial #	PCE-DG0626	Part #	3072913-01
75-30-01-212-801 (s)					
	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE				PKG
	PKG 1	MOS	12	+30d	09-NOV-2018
		HRS/MSC	600	+10%	637:12
	REF: MM 75-30-01	ENC			307
+ 75-30-01-212-802					
	NO. 1 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR				(EBT)
	PN	MOS			
	SN-UNKNOWN	HRS/MSC	5000	+100	(5000) 5000 M 5100
	REF: MM 75-30-01	ENC			
75-30-01-212-803					
	NO. 1 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE				(EBT)
	3053367-01	MOS			
	AHX0500489	HRS/MSC	5000	+100	(5000) 5000 M 5100
	REF:	ENC			

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-900-802	NO. 1 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR8089 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
75-30-01-900-803	NO. 1 ENGINE - LINEAR TRANSFORMER 3071811-01 1931 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
+ 75-30-02-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1931 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
+ 75-30-20-212-801	NO. 1 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) (5000) 5000 M 5100		
750010	NO. 1 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
753002	NO. 1 ENGINE - SERVO COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
753010	NO. 1 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX0500489 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
753020	NO. 1 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-30-01-212-801 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF THE BOV ASSY AND BOV SERVO VALVE PKG 1 REF: MM 75-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
+ 75-30-01-212-802	NO. 2 ENGINE - EXAMINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: MM 75-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
75-30-01-212-803	NO. 2 ENGINE - EXAMINE - COMPRESSOR AIR BLEED VALVE 3053367-01 AHX0500488 REF:	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
75-30-01-900-802	NO. 2 ENGINE - BLEED OFF VALVE (BOV) AND BOV SERVO VALVE 3075987-01 TR8284 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		09-JUL-2015 0 0		
75-30-01-900-803	NO. 2 ENGINE - LINEAR TRANSFORMER 3071811-01 1924 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		09-JUL-2015 0 0		
+ 75-30-02-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - LINEAR VARIABLE DIFFERENTIAL TRANSFORMER 3071811-01 1924 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 75-30-20-212-801	NO. 2 ENGINE - TEST, EXAMINE OR REPLACE - THE BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
750010	NO. 2 ENGINE - P3 AIR INERTIAL SEPARATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753002	NO. 2 ENGINE - SERVO COMPUTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
753010	NO. 2 ENGINE - COMPRESSOR BLEED VALVE ASSEMBLY 3053367-01 AHX0500488 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
753020	NO. 2 ENGINE - BOV TORQUE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

CHAPTER 76 ENGINE CONTROLS

76-11-03	THROTTLE CONTROL QUADRANT ASSEMBLY 6990010-11 1724 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-2015 0 0		
----------	---	-----------------------	-----	-------------------------	--	--	-----------------------	--	--

CHAPTER 77 ENGINE INDICATING

ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01

77-20-02-750-801	NO. 1 ENGINE - OPERATIONAL CHECK T6 TEMPERATURE INDICATING SYSTEM MOS HRS/MSC ENC REF: MM 77-20-02	36 1800	+30d +100	TSN:0			09-NOV-2018 637:12 307	09-NOV-2021 (2437:12) 2437:12	09-DEC-2021 2537:12
+ 77-40-01-212-801	NO. 1 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT 3075878-01 15032302 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
774001	NO. 1 ENGINE - DATA COLLECTION UNIT 3075878-01 15032302 REF: See Workcard	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		

ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
77-20-02-750-801	NO. 2 ENGINE - OPERATIONAL CHECK	T6	TEMPERATURE INDICATING SYSTEM						
		MOS	36	+30d			09-NOV-2018	09-NOV-2021	09-DEC-2021
		HRS/MSC	1800	+100			637:12	(2437:12) 2437:12	2537:12
	REF: MM 77-20-02	ENC					307		
+ 77-40-01-212-801	NO. 2 ENGINE - GENERAL VISUAL INSPECTION, EXAMINE, AND TEST/ REPLACE - DATA COLLECTION UNIT						(EBT)		
	3075878-01	MOS						(5000) 5000	M 5100
	15032973	HRS/MSC	5000	+100					
	REF: GENERIC NO REF	ENC							
774001	NO. 2 ENGINE - DATA COLLECTION UNIT								
	3075878-01	MOS			TSN:0		09-JUL-2015		
	15032973	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	ENC			TSN:0		0		
CHAPTER 78	EXHAUST								
78-00-00	LH ENGINE EXHAUST ASSEMBLY								
	PN	MOS			TSN:0		30-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
78-00-00	RH ENGINE EXHAUST ASSEMBLY								
	PN	MOS			TSN:0		30-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF: GENERIC NO REF	AFL			TSN:0		0		
CHAPTER 79	OIL								
79-31-05	LEFT ENGINE MAIN OIL PRESSURE SENSOR								
	APTE-478A-1000-270D	MOS			TSN:0		30-OCT-2015		
	00646	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
79-31-05	RIGHT ENGINE MAIN OIL PRESSURE SENSOR								
	APTE-478A-1000-270D	MOS			TSN:0		30-OCT-2015		
	00654	HRS/MSC	O/C		TSN:0		0		
	REF: See Workcard	AFL			TSN:0		0		
ENGINE NO. 1 Model : PW535E Serial # PCE-DG0626 Part # 3072913-01									

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 79-10-02-212-801	NO. 1 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-04 09543014 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 79-20-00-212-801	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
79-20-01-210-801	NO. 1 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
79-20-01-960-801	NO. 1 ENGINE - DISCARD OIL THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			23-JUN-2018 581:30 283	(1181:30) 1181:30	1241:30
+ 79-30-01-210-801	NO. 1 ENGINE - EXAMINE - CHIP COLLECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
+ 79-30-01-212-801	NO. 1 ENGINE - EXAMINE THE CHIP DETECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000	M 5100
79-30-01-770-801 (s)	NO. 1 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
79-30-02-210-801 (s)	NO. 1 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-03-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-30-20-212-801	NO. 1 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
790000	NO. 1 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		14-JUL-2015 0 0		
790020	NO. 1 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				14-AUG-2015 0 0		
792010	NO. 1 ENGINE - TEMPERATURE SENSOR ATS-9-800 042915-6 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		14-JUL-2015 0 0		
793003	NO. 1 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-04 09543014 REF: See Workcard	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		14-JUL-2015 0 0		
793005	NO. 1 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		14-JUL-2015 0 0		
793010	NO. 1 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C		TSN:0 TSN:0 TSN:0		14-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793020	NO. 1 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
793025	NO. 1 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			14-JUL-2015 0 0		
ENGINE NO. 2 Model : PW535E Serial # PCE-DG0624 Part # 3072913-01									
+ 79-10-02-212-801	NO. 2 ENGINE - OVERHAUL OR REFURBISH - FUEL-TO-OIL HEAT EXCHANGER (FOHE) 3052640-04 09543015 REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) 	(5000) 5000	M 5100
+ 79-20-00-212-801	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL TEST - OIL FILTER DIFFERENTIAL PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) 	(5000) 5000	M 5100
79-20-01-210-801	NO. 2 ENGINE - EXAMINE AND REPLACE - OIL FILTER REF: MM 79-20-01	MOS HRS/MSC ENC	5000	+100			(EBT) 	(5000) 5000	M 5100
79-20-01-960-801	NO. 2 ENGINE - DISCARD OIL THE OIL FILTER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	600	+10%			23-JUN-2018 581:30 283	(1181:30) 1181:30	1241:30
+ 79-30-01-210-801	NO. 2 ENGINE - EXAMINE - CHIP COLLECTOR PN SN-UNKNOWN REF: MM 79-30-01	MOS HRS/MSC ENC	5000	+100			(EBT) 	(5000) 5000	M 5100
+ 79-30-01-212-801	NO. 2 ENGINE - EXAMINE THE CHIP DETECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT) 	(5000) 5000	M 5100

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-30-01-770-801 (s)	NO. 2 ENGINE - OPERATIONAL CHECK OF THE CHIP DETECTOR PKG 1 REF: MM 79-30-01	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
79-30-02-210-801 (s)	NO. 2 ENGINE - SPECIAL DETAIL INSPECTION OF THE OIL FILTER IMPENDING BYPASS SWITCH PKG 1 REF: MM 79-30-02	MOS HRS/MSC ENC	12 600	+30d +10%			PKG 09-NOV-2018 637:12 307		
79-30-03-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
+ 79-30-20-212-801	NO. 2 ENGINE - DO A VISUAL INSPECTION - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	5000	+100			(EBT)	(5000) 5000 M 5100	
790000	NO. 2 ENGINE - OIL FILTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0 TSN:0	09-JUL-2015 0 0		
790020	NO. 2 ENGINE - CHANGE OIL REF: See Workcard	MOS HRS/MSC ENC	A/R				14-AUG-2015 0 0		
792010	NO. 2 ENGINE - TEMPERATURE SENSOR ATS-9-800 042915-1 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0 TSN:0	09-JUL-2015 0 0		
793003	NO. 2 ENGINE - FUEL OIL HEAT EXCHANGER 3052640-04 09543015 REF: See Workcard	MOS HRS/MSC ENC	O/C			TSN:0 TSN:0 TSN:0	09-JUL-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793005	NO. 2 ENGINE - OIL CHIP COLLECTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
793010	NO. 2 ENGINE - 5 O'CLOCK OIL LEVEL INDICATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
793020	NO. 2 ENGINE - OIL TANK FILLER CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		
793025	NO. 2 ENGINE - OIL LEVEL INDICATOR (SIGHT GLASS) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			09-JUL-2015 0 0		

CHAPTER --	GENERAL								
Z210-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE NOSE SECTION PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
Z210-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE NOSE SECTION PKG 84 REF: See Workcard	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
Z220-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 84 REF: AMM 05-41-00	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
Z220-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE FORWARD FUSELAGE COCKPIT SECTION PKG 87 REF: See Workcard	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z230-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE FRONT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-42-00								
Z230-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-42-00								
Z240-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE CENTER FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-42-00								
Z240-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE CENTER FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-42-00								
Z310-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE FRONT SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-43-00								
Z310-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE FRONT SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-43-00								
Z320-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE AFT FUSELAGE REAR SECTION PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-43-00								
Z320-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE AFT FUSELAGE REAR SECTION PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-43-00								

Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z330-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE VERTICAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-44-00								
Z330-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-44-00								
Z340-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE HORIZONTAL STABILIZER PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-44-00								
Z340-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE HORIZONTAL STABILIZER PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-44-00								
Z410-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE PYLON PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-46-00								
Z410-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE PYLON PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-46-00								
Z430-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE NACELLE PKG 87	MOS HRS/MSC AFL	120	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-46-00								
Z430-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE NACELLE PKG 84	MOS HRS/MSC AFL	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-46-00								



Status Report

EMB-505 - PHENOM 300 S/N 50500310 (N302TG): 757:42 HRS, 361 AFL as of 31-Jul-2019

Owner/Operator: CRASEL CORP

Report Date: 22-AUG-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z500-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE WINGS PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-45-00	HRS/MSC AFL							
Z500-002 (s)	INTERNAL GENERAL VISUAL INSPECTION OF THE WINGS PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-45-00	HRS/MSC AFL							
Z700-001 (s)	EXTERNAL GENERAL VISUAL INSPECTION OF OF THE MAIN LANDING GEAR BAY PKG 84	MOS	60	+30d/-30d			PKG 30-OCT-2015 0 0		
	REF: AMM 05-47-00	HRS/MSC AFL							